

NHTSA Recalls of Interest June 7, 2021

Front Seat Belts Not Securely Attached To B-Pillar

NHTSA Campaign Number: 21V389000

Manufacturer Tesla, Inc.

Components SEAT BELTS

Potential Number of Units Affected 5.530

Summary

Tesla, Inc. (Tesla) is recalling certain 2018-2020 Model 3 and 2019-2021 Model Y vehicles. One or both fasteners that secure the front seat shoulder belt to the b-pillar may not be properly attached.

Remedy

Tesla Service will inspect and repair both fasteners if necessary, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Tesla customer service online by visiting www.tesla.com/support/contact or by calling 1-877-79-TESLA (or 1-877-798-3752). Tesla's number for this recall is SB-21-20-001.

Vehicles

MAKE MODEL YEAR

TESLA MODEL 3 2018-2020 TESLA MODEL Y 2019-2021

Seat Belt Retractor Not Securely Attached

NHTSA Campaign Number: 21V388000

Manufacturer Tesla, Inc.

Components SEAT BELTS

Potential Number of Units Affected 2,166

Summary

Tesla, Inc. (Tesla) is recalling certain 2019-2021 Model Y vehicles. One or both fasteners that secure the left and right second row seat belt retractors may not be properly attached.

Remedy

Tesla Service will inspect and replace both fasteners if necessary, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Tesla customer service online by visiting www.tesla.com/support/contact or by calling 1-877-79-TESLA (or 1-877-798-3752). Tesla's number for this recall is SB-21-20-002.

Vehicle

MAKE MODEL YEAR

TESLA MODEL Y 2019-2021

ESP Software Not Updated for Camper Option

NHTSA Campaign Number: 21V360000

Manufacturer Daimler Vans USA, LLC

Components ELECTRONIC STABILITY CONTROL

Potential Number of Units Affected 168

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2019 Mercedes-Benz Sprinter vehicles equipped with the camper upfit option. The Electronic Stability Control (ESP) software was not updated for vehicles with a higher center of gravity.

Remedy

Dealers will update the software, free of charge. Owner notification letters are expected to be mailed June 21, 2021. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3HOLAPLI.

Vehicle

MAKE MODEL YEAR

MERCEDES-BENZ SPRINTER (VS30) 2019

Damaged Steering Gear May Cause Steering Loss

NHTSA Campaign Number: 21V407000

Manufacturer Ford Motor Company

Components STEERING

Potential Number of Units Affected 220

Summary

Ford Motor Company (Ford) is recalling certain 2021 F-150 vehicles. The steering gear may have internal damage, which could result in difficulty steering, or the inability to rotate the steering wheel while driving.

Remedy

Owners are advised to not drive their vehicles until the repair is complete. Vehicles will be towed in for service, and dealers will remove and replace the steering gear, free of charge. Owner notification letters are expected to be mailed in June 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S28.

Vehicle

MAKE MODEL YEAR

FORD F-150 2021

Loose Brake Caliper Bolts

NHTSA Campaign Number: 21V387000

Manufacturer Tesla, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 5,974

Summary

Tesla, Inc. (Tesla) is recalling certain 2019-2021 Model 3 and 2020-2021 Model Y vehicles. The brake caliper bolts may be loose, allowing the brake caliper to separate and contact the wheel rim.

Remedy

Tesla Service will inspect and tighten, or replace the caliper bolts as necessary, free of charge. The manufacturer has not yet provided a schedule for owner notification. Owners may contact Tesla customer service online by visiting www.tesla.com/support/contact or by calling 1-877-79-TESLA (or 1-877-798-3752). Tesla's number for this recall is SB-21-33-002.

Vehicles

MAKE MODEL YEAR

TESLA MODEL 3 2019-2021 TESLA MODEL Y 2020-2021