

NHTSA Recalls of Interest July 12, 2021

Air Bags Can Improperly Deploy

Incorrect positioning of the air bag control module can cause the vehicle's air bags to deploy improperly during a crash, increasing the risk of injury. Additionally, the vehicle's air bags can deploy unintentionally, increasing the risk of a crash.

NHTSA Campaign Number: 21V492000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 379

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2020-2021 Jetta and Jetta GLI vehicles. The air bag control module was welded in the incorrect position.

Remedy

Dealers will replace the air bag control module, free of charge. Owner notification letters are expected to be mailed August 27, 2021. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 69CK.

Vehicle

MAKE MODEL YEAR

VOLKSWAGEN JETTA 2020-2021

Air Bag Cover Emblem May Shatter

NHTSA Campaign Number: 21V494000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 260,915

Summary

Mazda North American Operations (Mazda) is recalling certain 2004-2007 Mazda3 vehicles. During air bag deployment, the plastic emblem on the steering wheel air bag module cover may shatter, and project plastic fragments into the vehicle.

Remedy

Dealers will replace the air bag module cover, free of charge. Owner notification letters are expected to be mailed August 28, 2021. Owners may contact Mazda customer service at 1-800-222-5500 Option 4. Mazda's number for this recall is 4921G.

Vehicle

MAKE MODEL YEAR

MAZDA MAZDA3 2004-2007

Roof Rail Air Bag Inflator May Rupture

NHTSA Campaign Number: 21V504000

Manufacturer General Motors, LLC

Components AIR BAGS

Potential Number of Units Affected 410,019

Summary

General Motors LLC (GM) is recalling certain 2015-2016 GMC Sierra 1500, 2500, 3500, and Chevrolet Silverado 1500, 2500, and 3500 trucks. The roof-rail air bag (RRAB) inflator end cap may detach from the inflator, or the inflator sidewall may rupture.

Remedy

Dealers will replace the left and right side RRAB modules, free of charge. Interim owner notification letters informing owners of the safety risk are expected to be mailed August 16, 2021. Owners will receive a second notice when the remedy is available. Owners may contact GMC customer service at 1-888-988-7267 or Chevrolet customer service at 1-800-222-1020. This recall supersedes NHTSA recall number 20V-736. GM's number for this recall is N202324251.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	SILVERADO 1500	2015-2016
CHEVROLET	SILVERADO 2500	2015-2016
CHEVROLET	SILVERADO 3500	2015-2016
GMC	SIERRA 1500	2015-2016
GMC	SIERRA 2500	2015-2016
GMC	SIERRA 3500	2015-2016