



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest July 5, 2021

### [Air Bag Inflators May Underinflate Bag](#)

**NHTSA Campaign Number:** 21V470000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 62,812

#### **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2000-2001 Audi TT Coupe, TT Roadster, 2000-2002 A4, and S4 vehicles equipped with Non-Azide Driver Air Bag Inflators (NADI) that do not contain phase stabilized ammonium nitrate (PSAN) propellant. Due to a manufacturing issue, the NADI inflators may absorb moisture, possibly causing the air bag to deploy improperly in the event of a crash.

#### **Remedy**

Dealers will replace the driver frontal airbag inflator with an alternative inflator, free of charge. Owner notification letters are expected to be mailed August 20, 2021. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 69CJ.

#### **Vehicles**

##### **MAKE MODEL YEAR**

AUDI	A4	2000-2002
AUDI	S4	2000-2002
AUDI	TT	2000-2001

## Front Air Bag May Not Deploy Properly

**NHTSA Campaign Number:** 21V472000

**Manufacturer** General Motors, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 6

### **Summary**

General Motors, LLC (GM) is recalling certain 2021 Chevrolet Traverse and Buick Enclave vehicles. During service by dealers, certain vehicles may have received incorrect air bag calibration software that may affect frontal airbag deployment.

### **Remedy**

Dealers will update the air bag calibration software, free of charge. Owner notification letters are expected to be mailed August 9, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020 and Buick customer service at 1-800-521-7300. GM's number for this recall is N212340220.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
BUICK	ENCLAVE	2021
CHEVROLET	TRAVERSE	2021

## Incorrect Passenger Seat May Affect Air Bag

**NHTSA Campaign Number:** 21V467000

**Manufacturer** Porsche Cars North America, Inc.

**Components** SEATS, AIR BAGS

**Potential Number of Units Affected** 149

### **Summary**

Porsche Cars North America, Inc. (Porsche) is recalling certain 2021 911 Turbo Coupe, 911 Turbo S Coupe, 911 Carrera 4S Targa, 911 Carrera 4S Cabriolet, 911 Turbo S Cabriolet, and 911 Turbo Cabriolet vehicles. Incorrect passenger seat was installed and may cause a Occupant Classification System (OCS) malfunction.

## Remedy

Dealers will install the correct seat, free of charge. Owner notification letters are expected to be mailed August 20, 2021. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AMB3.

## Vehicle

### MAKE MODEL YEAR

PORSCHE 911 2021

## Second Row Seatback Improperly Welded/FMVSS 225

**NHTSA Campaign Number:** 21V474000

**Manufacturer** Nissan North America, Inc.

**Components** SEATS, CHILD SEAT

**Potential Number of Units Affected** 47,098

## Summary

Nissan North America, Inc. (Nissan) is recalling certain 2021 Rogue vehicles. The second-row upper tether wires may have been improperly welded to the seatback frame, preventing a child seat from being securely anchored. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 225, "Child Restraint Anchorage Systems."

## Remedy

Dealers will inspect and replace the rear seatbacks as necessary, free of charge. Owner notification letters are expected to be mailed July 30, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC812.

## Vehicle

### MAKE MODEL YEAR

NISSAN ROGUE 2021

## Seat Belt Retractor May Lock/FMVSS 208 and 209

**NHTSA Campaign Number:** 21V480000

**Manufacturer** Winnebago Industries, Inc.

**Components** SEAT BELTS

**Potential Number of Units Affected** 1,566

### **Summary**

Winnebago Industries, Inc. (Winnebago) is recalling certain 2021-2022 Solis, Travato, and Ekko vehicles, equipped with GE-ES Double Flipseats. The seat belt retractors may lock up when the vehicle is on a slight incline. As such, these seats fail to comply with the requirements of Federal Motor Vehicle Safety Standards numbers 208, "Occupant Crash Protection" and 209, "Seat Belt Assemblies."

### **Remedy**

Winnebago will work with Freedman to notify owners, and dealers will inspect the seat and repair, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Winnebago customer service at 1-614-585-6939 or 1-800-537-1885 or Freedman customer service at 1-800-443-4540.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
WINNEBAGO	EKKO	2021-2022
WINNEBAGO	SOLIS	2021-2022
WINNEBAGO	TRAVATO	2021-2022

## **Software Error Can Cause Loss of Motive Power**

**NHTSA Campaign Number:** 21V486000

**Manufacturer** Porsche Cars North America, Inc.

**Components** ELECTRICAL SYSTEM, ENGINE AND ENGINE COOLING

**Potential Number of Units Affected** 10,373

### **Summary**

Porsche Cars North America, Inc. (Porsche) is recalling certain 2020-2021 Taycan Turbo, Taycan Turbo S, Taycan 4S, 2021 Taycan, Taycan Cross Turismo, Taycan Turbo S Cross Turismo, Taycan 4S Cross Turismo, and Taycan Turbo Cross Turismo vehicles. The monitoring software can incorrectly detect a fault and shutdown the power train, causing a loss of motive power.

**Remedy**

Dealers will reprogram the power electronics and the engine control unit, free of charge. Owner notification letters are expected to be mailed August 27, 2021. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AMB5.

**Vehicle**

**MAKE    MODEL    YEAR**

PORSCHE TAYCAN 2020-2021