



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest August 2, 2021

### Seat Belt Locking Retractor Malfunction/FMVSS 208

**NHTSA Campaign Number:** 21V555000

**Manufacturer** Nissan North America, Inc.

**Components** SEAT BELTS

**Potential Number of Units Affected** 4,083

#### **Summary**

Nissan North America, Inc. (Nissan) is recalling certain 2021 Rogue Sport vehicles. The seat belt automatic locking retractor (ALR)

may deactivate early, reducing the protection offered to an installed child seat. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

#### **Remedy**

Dealers will replace the front passenger seat belt and as necessary both outer rear seat belts, free of charge. Owner notification letters are expected to be mailed September 14, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is RT049 & RT050.

#### **Vehicle**

**MAKE      MODEL      YEAR**

NISSAN ROGUE SPORT 2021

## Passenger Seat Belt Malfunction/FMVSS 208

**NHTSA Campaign Number:** 21V554000

**Manufacturer** BMW of North America, LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 21,537

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2021 2 Series (230i, 230i xDrive, M240i, M240i xDrive), 330e, 330e Xdrive, 4 Series Coupe (430i, 430i xDrive, M440i xDrive) M4 Coupe, M4 Competition Coupe, BMW 4 Series Convertible (430i, M440i), BMW X1 sDrive28i, xDrive28i, 2 Series Gran Coupe (228i, 228i xDrive, M235i xDrive), M2 Competition Coupe, 330i, 330i xDrive, M340i, M340i xDrive, M3, M3 Competition, 530i, 530i xDrive, 540i, 540i xDrive, MINI Hardtop 2 Door (Cooper, CooperS, JCW), X2 sDrive28i, X2 xDrive28i, X2 M35i, Z4 sDrive30i, Z4 M40i, MINI Hardtop 2 Door (Cooper SE), MINI Convertible (Cooper, Cooper S, JCW), MINI Clubman (Cooper S, Cooper S All4, JCW), MINI Countryman (Cooper, Cooper All4, Cooper S, Cooper S All4, JCW All4), Rolls Royce Ghost, MINI Countryman (Cooper S E All4), Rolls Royce Phantom, Rolls Royce Cullinan, and Toyota Supra vehicles. The passenger seat belt Automatic Locking Retractor (ALR) may deactivate early, before the webbing fully retracts. As such, these assemblies fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

### **Remedy**

Dealers will inspect the seat belt retractors (including the seat belts) and, if necessary, replace the retractors, free of charge. Owner notification letters are expected to be mailed September 13, 2021. Owners may contact BMW customer service at 1-800-525-7417; 1-866-825-1525 (MINI); 1-877-877-3735 (Rolls Royce); and 1-888-270-9371 (Toyota).

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
BMW	228I	2021
BMW	230I	2021
BMW	330E	2021
BMW	330I	2021
BMW	430I	2021
BMW	530I	2021
BMW	540I	2021
BMW	M2	2021
BMW	M235I	2021
BMW	M240I	2021
BMW	M3	2021

MAKE	MODEL	YEAR
BMW	M340I	2021
BMW	M4	2021
BMW	M440I	2021
BMW	X1	2021
BMW	X2	2021
BMW	Z4	2021
MINI	COOPER	2021
MINI	COOPER S	2021
MINI	COOPER S CLUBMAN	2021
MINI	COOPER SE	2021
MINI	COUNTRYMAN	2021
ROLLS-ROYCE	CULLINAN	2021
ROLLS-ROYCE	GHOST	2021
ROLLS-ROYCE	PHANTOM	2021
TOYOTA	SUPRA	2021

## Loss of ABS/ESC

**NHTSA Campaign Number:** 21V569000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 498

### Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021 E-Tron Quattro and 2020-2021 Audi E-Tron Sportback Quattro vehicles. An improperly welded rotor and shaft may separate within the integrated brake system.

### Remedy

Dealers will replace the brake booster, free of charge. Owner notification letters are expected to be mailed September 24, 2021. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 47R1.

### Vehicle

**MAKE MODEL YEAR**

AUDI E-TRON 2020-2021

## Brake System Calibrated Incorrectly

**NHTSA Campaign Number:** 21V579000

**Manufacturer** General Motors, LLC

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 2

### **Summary**

General Motors, LLC (GM) is recalling certain 2021 Chevrolet Tahoe and GMC Yukon vehicles. Dealer service technicians may have calibrated the brake system incorrectly, affecting Electronic Stability Control (ESC), traction control, Anti-Lock Brake System (ABS), and braking while towing a trailer.

### **Remedy**

Dealers will recalibrate the brake system control module, free of charge. Owner notification letters are expected to be mailed September 13, 2021. Owners may contact Chevrolet customer service at 1-800-222-1202; GMC customer service at 1-800-462-8782. GM's number for this recall is N212340970.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

CHEVROLET	TAHOE	2021
-----------	-------	------

GMC	YUKON	2021
-----	-------	------

## Front Seat Control Module Malfunction

**NHTSA Campaign Number:** 21V550000

**Manufacturer** Bentley Motors, Inc.

**Components** SEATS

**Potential Number of Units Affected** 3,647

### **Summary**

Bentley Motors, Inc. (Bentley) is recalling certain 2020-2021 Continental GT/GT Convertible vehicles. During some automated front seat movements, the front seat may trap a rear passenger's legs.

## Remedy

Dealers will update the software for the front seats, free of charge. Owner notification letters are expected to be mailed August 23, 2021. Owners may contact Bentley customer service at 1-800-777-6923. Bentley's number for this recall is RE21/26 (RC08).

## Vehicle

MAKE	MODEL	YEAR
------	-------	------

BENTLEY	CONTINENTAL GT	2020-2021
---------	----------------	-----------

## Spare Tire is Incorrect Size

**NHTSA Campaign Number:** 21V578000

**Manufacturer** General Motors, LLC

**Components** TIRES

**Potential Number of Units Affected** 86

## Summary

General Motors, LLC. (GM) is recalling certain 2020-2021 Chevrolet Silverado 2500 and GMC Sierra 2500 vehicles equipped with a 17" spare tire (RPO ZHQ or ZXT) and either the 20" accessory road tire (RPO REM) or the 18" accessory road tire (RPO Q2V). Operating the spare tire with other 20" or 18" tires can prevent the Anti-Lock Braking System (ABS) from engaging.

## Remedy

Dealers will provide the appropriate spare tire and apply a new spare tire information label, free of charge. Owner notification letters are expected to be mailed September 13, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020; GMC customer service at 1-800-462-8782. GM's number for this recall is N212329780.

## Vehicles

MAKE	MODEL	YEAR
------	-------	------

CHEVROLET	SILVERADO 2500	2020-2021
GMC	SIERRA 2500	2020-2021