

NHTSA Recalls of Interest September 20, 2021

Seat Belt Locking Retractor Malfunction/FMVSS 208

NHTSA Campaign Number: 21V699000

Manufacturer Chrysler (FCA US, LLC)

Components SEAT BELTS

Potential Number of Units Affected 8,379

Summary

Chrysler (FCA US, LLC) is recalling certain 2021 Ram ProMaster City and Ram ProMaster vehicles. The seat belt automatic locking retractors may deactivate early, which can prevent the child restraint system from securing properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will inspect and replace the seat belt retractors as necessary, free of charge. Owner notification letters are expected to be mailed October 29, 2021. Owners may contact FCA US LLC customer service at 1-800-853-1403. FCA US LLC's number for this recall is Y61.

Vehicles

MAKE MODEL YEAR

RAM PROMASTER 2021 RAM PROMASTER CITY 2021

Seat Belt Locking Retractor Malfunction/FMVSS 208

NHTSA Campaign Number: 21V682000

Manufacturer Volvo Car USA, LLC

Components SEAT BELTS

Potential Number of Units Affected 19,149

Summary

Volvo Car USA, LLC (Volvo Car) is recalling certain 2021 XC40, XC 40 Recharge, V60CC, V90, V90CC, XC90, and 2021-2022 V60, XC60, S60 vehicles. The seat belt automatic locking retractors may deactivate early, which can prevent the child restraint system from securing properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will inspect and replace the seat belt assemblies, as necessary, free of charge. Owner notification letters are expected to be mailed October 31, 2021. Owners may contact Volvo Car customer service at 1-800-458-1552. Volvo Car's number for this recall is R10111.

Vehicles

MAKE MODEL YEAR

VOLVO S60 2021-2022 VOLVO V60 2021-2022 VOLVO V60CC 2021 VOLVO V90 2021 VOLVO V90CC 2021 VOLVO XC40 2021 VOLVO XC60 2021-2022 VOLVO XC90 2021

Seat Belt Locking Retractor Malfunction/FMVSS 208

NHTSA Campaign Number: 21V683000

Manufacturer Polestar Automotive USA, Inc.

Components SEAT BELTS

Potential Number of Units Affected 2

Summary

Polestar Automotive USA, Inc. (Polestar) is recalling certain 2021 Polestar PS1 vehicles. The seat belt automatic locking retractors may deactivate early, which can prevent the child restraint system from securing properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will inspect and replace the seat belt assemblies, as necessary, free of charge. Owner notification letters are expected to be mailed October 31, 2021. Owners may contact Polestar customer service at 1-800-806-2504. Polestar's number for this recall is R10112.

Vehicle

MAKE MODEL YEAR

POLESTAR POLESTAR 1 2021

Automatic Locking Retractor Malfunction/FMVSS 208

NHTSA Campaign Number: 21V703000

Manufacturer Maserati North America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 701

Summary

Maserati North America, Inc. (Maserati) is recalling certain 2021 Levante, Quattroporte, and Ghibli vehicles. The seat belt automatic locking retractors may deactivate early, which can prevent the child restraint system from securing properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will inspect and replace the seat belt assemblies, as necessary, free of charge. Owner notification letters are expected to be mailed October 22, 2021. Owners may contact Maserati customer service at 1-877-696-2737. Maserati's number for this recall is 434.

Vehicles

MAKE	MODEL	YEAR
MASERATI GHIBLI		2021
MASERATI LEVANTE		2021
MASERATI Q	UATTROPOR'	TE 2021

Sensing Diagnostic Module Not Activated/FMVSS 208

NHTSA Campaign Number: 21V702000

Manufacturer General Motors, LLC

Components AIR BAGS

Potential Number of Units Affected 2

Summary

General Motors, LLC. (GM) is recalling certain 2022 GMC Acadia vehicles. The sensing diagnostic module (SDM) may have been left in "manufacturing mode" and not activated at the assembly plant prior to shipment. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

The vehicles will be returned to the assembly plant for SDM activation. Both affected vehicles are still in dealer inventory and therefore no owner notification letters will be mailed. Owners may contact GMC 1-800-462-8782. GM's number for this recall is N212344261.

Vehicle

MAKE MODEL YEAR

GMC ACADIA 2022

Secondary Hood Latch May Detach/FMVSS 113

NHTSA Campaign Number: 21V706000

Manufacturer Nissan North America, Inc.

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 3,030

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2022 Pathfinder vehicles. Insufficient welds may allow the secondary hood latch retainer bracket to detach from the front bumper assembly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 113, "Hood Latch System."

Remedy

Dealers will inspect and replace the secondary hood latch bracket as necessary, free of charge. Owner notification letters are expected to be mailed October 21, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC840.

Vehicle

MAKE MODEL YEAR

NISSAN PATHFINDER 2022

Instrument Cluster May Go Blank

NHTSA Campaign Number: 21V700000

Manufacturer Newmar Corporation

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 1,554

Summary

Newmar Corporation (Newmar) is recalling certain 2019-2021 London Aire, Dutch Star, Essex, King Aire, Mountain Aire, 2020-2021 Ventana, and 2021 New Aire recreational vehicles. The instrument cluster may intermittently go blank while the vehicle is in motion.

Remedy

Dealers will update the control module software, and reroute and secure the ductwork, free of charge. Owner notification letters are expected to be mailed on November 8, 2021. Owners may contact Newmar's customer service at 1-800-731-8300.

Vehicles

MAKE	MODEL	YEAR
NEWMAR D	OUTCH STAR	2019-2021
NEWMAR E	SSEX	2019-2021
NEWMAR K	ING AIRE	2019-2021
NEWMAR L	ONDON AIRE	2019-2021
NEWMAR M	IOUNTAIN AIRE	2019-2021
NEWMAR N	IEW AIRE	2021
NEWMAR V	ENTANA	2020-2021

Pressure Input Rod On Brake Booster May Be Loose

NHTSA Campaign Number: 21V695000

Manufacturer Volkswagen Group of America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 99

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021 Arteon vehicles. The pressure input rod connection on the brake booster may be loose and could detach.

Remedy

Dealers will tighten the pressure input rod connection, free of charge. Owner notification letters are expected to be mailed November 5, 2021. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 47R3.

Vehicle

MAKE MODEL YEAR

VOLKSWAGEN ARTEON 2021

Pressure Input Rod On Brake Booster May Be Loose

NHTSA Campaign Number: 21V697000

Manufacturer Porsche Cars North America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 11

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2020-2021 911 Carrera and Taycan vehicles. The pressure input rod connection on the brake booster may be loose and could detach.

Remedy

Dealers will repair or replace the brake booster as necessary, free of charge. Owner notification letters are expected to be mailed November 7, 2021. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AMB9.

Vehicles

MAKE MODEL YEAR

PORSCHE 911 CARRERA 2020-2021 PORSCHE TAYCAN 2020-2021