



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest October 4, 2021

[Seat May Slide Forward in a Crash/FMVSS 210](#)

NHTSA Campaign Number: 21V750000

Manufacturer Mazda North American Operations

Components SEAT BELTS, SEATS

Potential Number of Units Affected 8,648

Summary

Mazda North American Operations (Mazda) is recalling certain 2020-2021 CX-9 vehicles equipped with 60/40 split bench second-row seats. The left-side second-row seat may unexpectedly slide forward during a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 210, "Seat Belt Assembly Anchorages."

Remedy

Dealers will replace the internal parts of the affected second-row seats, free of charge. Owner notification letters are expected to be mailed November 26, 2021. Owners may contact Mazda customer service at 1-800-222-5500, Option 4. Mazda's number for this recall is 5221I.

Vehicle

MAKE MODEL YEAR

MAZDA CX-9 2020-2021

Second-Row Seat Back Weld May Separate

NHTSA Campaign Number: 21V743000

Manufacturer Nissan North America, Inc.

Components SEATS

Potential Number of Units Affected 5,895

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2022 Pathfinder vehicles. The second-row seat back frames may have insufficient welds that could separate.

Remedy

Dealers will inspect and replaced the seat assemblies as necessary, free of charge. Owner notification letters are expected to be mailed November 19, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's numbers for this recall are PC845, PC846, and PC847.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

NISSAN	PATHFINDER	2022
--------	------------	------

Third-Row Headrests may Move or Detach/FMVSS 202

NHTSA Campaign Number: 21V742000

Manufacturer Nissan North America, Inc.

Components SEATS

Potential Number of Units Affected 10,082

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2022 Pathfinder vehicles. The third-row headrests may have an improper weld or misaligned internal components, which can allow the headrest to move or detach. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 202, "Head Restraints."

Remedy

Dealers will replace all three third-row seat headrests, free of charge. Owner notification letters are expected to be mailed November 19, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC844.

Vehicle

MAKE MODEL YEAR

NISSAN PATHFINDER 2022

ESC Indicator Lamp May Not Illuminate/FMVSS 136

NHTSA Campaign Number: 21V719000

Manufacturer PACCAR Incorporated

Components ELECTRONIC STABILITY CONTROL

Potential Number of Units Affected 19

Summary

PACCAR Incorporated (PACCAR) is recalling certain 2022 Peterbilt 567 and 579 vehicles. The Electronic Stability Control (ESC) malfunction indicator lamp may not illuminate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 136, "Electronic Stability Control Systems on Heavy Vehicles."

Remedy

Dealers will reprogram the ESC system, free of charge. Owner notification letters are expected to be mailed on November 15, 2021. Owners may contact PACCAR's customer service at 1-940-591-4220 (Peterbilt). PACCAR's number for this recall is 21PBL.

Vehicles

MAKE MODEL YEAR

PETERBILT 567 2022

PETERBILT 579 2022

ECU Software May Cause Loss of Drive Power

NHTSA Campaign Number: 21V734000

Manufacturer Toyota Motor Engineering & Manufacturing

Components HYBRID PROPULSION SYSTEM, ENGINE AND ENGINE COOLING

Potential Number of Units Affected 8,411

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2022 Prius and Prius Prime vehicles. The Engine Control Unit (ECU) software may falsely detect an error and shut down the hybrid system, causing a loss of drive power.

Remedy

Dealers will update the ECU software, free of charge. Owner notification letters are expected to be mailed November 20, 2021. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is 21TB07/21TA07.

Vehicles

MAKE	MODEL	YEAR
TOYOTA	PRIUS	2022
TOYOTA	PRIUS PRIME	2022

Rearview Camera Image May Not Display

NHTSA Campaign Number: 21V735000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 228,297

Summary

Ford Motor Company (Ford) is recalling certain 2020-2021 Explorer, Lincoln Corsair, and Lincoln Aviator vehicles equipped with 360-degree cameras. The video output may fail, preventing the rearview camera image from displaying.

Remedy

Dealers will update the Image Processing Module (IPMB) software, free of charge. Owner notification letters are expected to be mailed October 7, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S44.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPLORER	2020-2021
LINCOLN	AVIATOR	2020-2021
LINCOLN	CORSAIR	2020-2021

Power Control Module May Cause Fuel Pump Failure

NHTSA Campaign Number: 21V739000

Manufacturer General Motors, LLC

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 14,939

Summary

General Motors, LLC (GM) is recalling certain 2021 Cadillac Escalade, Escalade ESV, Chevrolet Suburban, Tahoe, GMC Yukon, and Yukon XL vehicles. The fuel pump power control module may cause the fuel pump to fail or operate intermittently, which can interrupt fuel flow to the engine, and cause an unexpected engine stall.

Remedy

Dealers will replace the fuel pump power control module, free of charge. Owner notification letters are expected to be mailed November 8, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020; Cadillac customer service at 1-800-458-8006; or GMC customer service at 1-800-462-8782. GM's number for this recall is N212332040.

Vehicles

MAKE	MODEL	YEAR
CADILLAC	ESCALADE	2021
CADILLAC	ESCALADE ESV	2021
CHEVROLET	SUBURBAN	2021
CHEVROLET	TAHOE	2021
GMC	YUKON	2021
GMC	YUKON XL	2021

Turn Signal May Activate in Wrong Direction

NHTSA Campaign Number: 21V749000

Manufacturer Hyundai Motor America

Components EXTERIOR LIGHTING, ELECTRICAL SYSTEM

Potential Number of Units Affected 466,109

Summary

Hyundai Motor America (Hyundai) is recalling certain 2015-2017 Sonata, 2016-2017 Sonata Hybrid, and Sonata Plug-In Hybrid vehicles. The Smart Junction Box (SJB) software logic may not properly interpret the signals received

from the multifunction switch, which could cause the turn signal to activate in the opposite direction of what the driver intended.

Remedy

Dealers will update the SJB software, free of charge. Owner notification letters are expected to be mailed November 19, 2021. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 210.

Vehicles

MAKE	MODEL	YEAR
HYUNDAI	SONATA	2015-2017
HYUNDAI	SONATA HYBRID	2016-2017
HYUNDAI	SONATA PLUG-IN HYBRID	2016-2017