



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest November 15, 2021

Window Air Bag Mounted Incorrectly/FMVSS 226

NHTSA Campaign Number: 21V860000

Manufacturer Mercedes-Benz USA, LLC

Components AIR BAGS

Potential Number of Units Affected 46

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 GLB 250 and AMG GLB 35 vehicles. The driver-side window air bag may not have been mounted correctly to the lower area of the A-pillar. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 226, "Ejection Mitigation."

Remedy

Dealers will inspect the mounting of the driver-side window air bag and repair it as necessary, free of charge. Owner notification letters are expected to be mailed January 4, 2021. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

MERCEDES-BENZ	AMG GLB35	2021
---------------	-----------	------

MERCEDES-BENZ	GLB250	2021
---------------	--------	------

Inaccurate Fuel Gauge Reading

NHTSA Campaign Number: 21V862000

Manufacturer Kia Motors America

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 53

Summary

Kia Motors America (Kia) is recalling certain 2020-2021 Stinger vehicles. A software error in the instrument cluster may cause an inaccurate fuel gauge reading.

Remedy

Dealers will update the software, free of charge. Owner notification letters are expected to be mailed December 10, 2021. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC219.

Vehicle

MAKE MODEL YEAR

KIA STINGER 2020-2021

Broken Shaft Seal May Cause Loss of Power Steering

NHTSA Campaign Number: 21V856000

Manufacturer Mack Trucks, Inc.

Components STEERING

Potential Number of Units Affected 79

Summary

Mack Trucks, Inc. (Mack) is recalling certain 2021 Granite and LR vehicles. A machining defect may cause pressure to build in the power steering pump and break the shaft seal, resulting in a loss of power steering assist.

Remedy

Dealers will replace the power steering pump, free of charge. Owner notification letters are expected to be mailed December 22, 2021. Owners may contact Mack customer service at 1-800-866-1177. Mack's number for this recall is SC0432.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

MACK	GRANITE (GR)	2021
------	--------------	------

MACK	LR	2021
------	----	------

Broken Shaft Seal May Cause Loss of Power Steering

NHTSA Campaign Number: 21V851000

Manufacturer Oshkosh Corporation

Components STEERING

Potential Number of Units Affected 563

Summary

Oshkosh Corporation (Oshkosh) is recalling certain 2020-2021 S-Series vehicles. A machining defect may cause pressure to build in the power steering pump and break the shaft seal, resulting in a loss of power steering assist.

Remedy

Owners will inspect and replace the power steering pump as necessary. Owners may perform this work themselves or reach out to one of our service centers to perform the inspection and repair work free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Oshkosh customer service at 1-888-686-7278.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

OSHKOSH	S-SERIES	2020-2021
---------	----------	-----------

Rearview Camera Image May Be Blocked from View

NHTSA Campaign Number: 21V855000

Manufacturer BMW of North America, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 442

Summary

Rolls-Royce Motor Cars, Ltd. (Rolls-Royce) is recalling certain 2019-2022 Rolls-Royce Phantom vehicles. The Central Information Display may not raise to the correct position, resulting in a rearview camera image that is partially blocked from view.

Remedy

Dealers will update the software, free of charge. Owner notification letters are expected to be mailed December 27, 2021. Owners may contact Rolls Royce customer service at 1-877-877-3735.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

ROLLS-ROYCE	PHANTOM	2019-2022
-------------	---------	-----------

Missing Drive Bushing May Cause Steering Loss

NHTSA Campaign Number: 21V852000

Manufacturer Volkswagen Group of America, Inc.

Components STEERING

Potential Number of Units Affected 1

Summary

Volkswagen Group of American, Inc. (Volkswagen) is recalling one 2021 ID.4 vehicle. The steering gear may have an incorrectly assembled or missing drive bushing.

Remedy

A dealer will replace the steering gear, free of charge. The owner notification letter is expected to be mailed December 31, 2021. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 48Q7.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

VOLKSWAGEN	ID.4	2021
------------	------	------

Unexpected Engine Shut Down

NHTSA Campaign Number: 21V837000

Manufacturer Navistar, Inc.

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 7,004

Summary

Navistar, Inc. (Navistar) is recalling certain 2020-2023 IC CE school buses. The engine control module (ECM) may set a fault code that results in an unexpected engine shut down.

Remedy

The remedy is currently under development. Owner notification letters notifying owners of the safety risk were mailed November 5, 2021. A second letter will be mailed once the remedy is available. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 21507.

Vehicle

MAKE MODEL YEAR

IC BUS CE 2020-2023