



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest November 29, 2021

Blocked Drain Tube May Cause Air Bag Deployment

NHTSA Campaign Number: 21V892000

Manufacturer Volkswagen Group of America, Inc.

Components VISIBILITY, AIR BAGS

Potential Number of Units Affected 54,429

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021 Atlas and 2020-2021 Atlas Cross Sport vehicles. The air conditioning system drain tube could be blocked, causing water to leak inside the vehicle near the air bag control module.

Remedy

Dealers will repair the drain tube and replace the air bag control module, as necessary, free of charge. Interim owner notification letters informing owners of the safety risk are expected to be mailed January 14, 2022. Owners will receive a second notice when remedy parts become available. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 87H4.

Vehicles

| MAKE | MODEL | YEAR |
|-------------|-------------------|-------------|
| VOLKSWAGEN | ATLAS | 2021 |
| VOLKSWAGEN | ATLAS CROSS SPORT | 2020-2021 |

Seat Belt Retractor Malfunction/FMVSS 208

NHTSA Campaign Number: 21V900000

Manufacturer Honda (American Honda Motor Co.)

Components SEAT BELTS

Potential Number of Units Affected 4,346

Summary

Honda (American Honda Motor Co.) is recalling certain 2021 Accord Sedan, Accord Hybrid, CR-V, Ridgeline, 2022 Insight and CR-V Hybrid vehicles. The automatic locking retractor on the second-row center seat belt assembly may deactivate improperly, which can result in an unsecured child restraint system. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will replace the second-row center seat belt assembly, free of charge. Owner notification letters are expected to be mailed January 17, 2022. Owners may contact Honda customer service at 1-888-234-2138.

Vehicles

| MAKE | MODEL | YEAR |
|-------------|---------------|-------------|
| HONDA | ACCORD | 2021 |
| HONDA | ACCORD HYBRID | 2021 |
| HONDA | CR-V | 2021 |
| HONDA | CR-V HYBRID | 2022 |
| HONDA | INSIGHT | 2022 |
| HONDA | RIDGELINE | 2021 |

Incorrect Seat Belt Webbing Guide Installed

NHTSA Campaign Number: 21V889000

Manufacturer Toyota Motor Engineering & Manufacturing

Components SEAT BELTS

Potential Number of Units Affected 2,259

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2022 Sienna vehicles equipped with seating for eight passengers. An incorrect seat belt webbing guide may have been installed on the outboard second-row seat belt assemblies.

Remedy

Dealers will replace the outboard second-row seat belt assemblies, free of charge. Owner notification letters are expected to be mailed January 13, 2022. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's numbers for this recall are 21TB08 and 21TA08.

Vehicle

MAKE MODEL YEAR

TOYOTA SIENNA 2022

Seat Belt Locking Retractor Malfunction/FMVSS 208

NHTSA Campaign Number: 21V893000

Manufacturer Jayco, Inc.

Components SEAT BELTS

Potential Number of Units Affected 45

Summary

Jayco, Inc. (Jayco) is recalling certain 2021-2022 Jayco Swift and Entegra Ethos motorhomes. The seat belt automatic locking retractors may deactivate early, which can prevent the child restraint system from securing properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will inspect and replace the seat belt retractors as needed, free of charge. Owner notification letters are expected to be mailed January 12, 2022. Owners may contact Jayco customer service at 1-800-283-8267.

Vehicles

MAKE MODEL YEAR

ENTEGR A ETHOS 2021-2022

JAYCO SWIFT 2021-2022

Insufficient Fuel May Cause Stall

NHTSA Campaign Number: 21V901000

Manufacturer Honda (American Honda Motor Co.)

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 357

Summary

Honda (American Honda Motor Co.) is recalling certain 2021 NC750XD motorcycles equipped with 6-speed dual clutch automatic transmissions. The fuel injection control module software may be programmed incorrectly, which can result in insufficient fuel when stopping, or accelerating from a stop.

Remedy

Dealers will reprogram the fuel injection and dual clutch transmission software, free of charge. Owner notification letters are expected to be mailed January 7, 2022. Owners may contact Honda Powersports customer service at 866-784-1870. Honda's number for this recall is KN0.

Vehicle

MAKE MODEL YEAR

HONDA NC750XD 2021