



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest December 6, 2021

Air Bag Cover May Break Apart During Crash

NHTSA Campaign Number: 21V923000

Manufacturer Ford Motor Company

Components AIR BAGS

Potential Number of Units Affected 5

Summary

Ford Motor Company (Ford) is recalling certain 2022 Super Duty F-250 and F-350 vehicles. The strength of the driver-side air bag cover may be insufficient.

Remedy

Dealers will replace the driver-side air bag module, free of charge. Owner notification letters are expected to be mailed January 17, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S49.

Vehicles

MAKE MODEL YEAR

FORD F-250 SD 2022

FORD F-350 SD 2022

Reduced Braking Performance/FMVSS 135

NHTSA Campaign Number: 21V922000

Manufacturer Ford Motor Company

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 114,996

Summary

Ford Motor Company (Ford) is recalling certain 2021-2022 Bronco Sport and Escape vehicles. The rear brake linings may have been manufactured incorrectly, which can affect braking performance. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 135, "Light Vehicle Brake Systems."

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed January 10, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21C31.

Vehicles

MAKE	MODEL	YEAR
FORD	BRONCO SPORT	2021-2022
FORD	ESCAPE	2021-2022

Passenger-Side Sliding Door May Not Latch

NHTSA Campaign Number: 21V908000

Manufacturer Kia Motors America

Components STRUCTURE, LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 2,956

Summary

Kia Motors America (Kia) is recalling certain 2022 Carnival vehicles. The remote controller assembly for the passenger-side power sliding door may malfunction, preventing the passenger-side sliding door from securely latching.

Remedy

Dealers will replace the passenger-side power sliding door release actuator's drum and holder inside the remote controller assembly, free of charge. Owner notification letters are expected to be mailed December 16, 2021. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC221.

Vehicle

MAKE MODEL YEAR

KIA CARNIVAL 2022

Missing Electronic Stability Control/FMVSS 136

NHTSA Campaign Number: 21V914000

Manufacturer Daimler Trucks North America, LLC

Components ELECTRONIC STABILITY CONTROL, SERVICE BRAKES, AIR

Potential Number of Units Affected 1

Summary

Daimler Trucks North America, LLC. (DTNA) is recalling one 2020 Thomas Built Buses Saf-T-Liner HDX transit bus. The chassis was assembled without the electronic stability control hardware and software. As such, this vehicle fails to comply with the requirements of Federal Motor Vehicle Safety Standard number 136, "Electronic Stability Control Systems on Heavy Vehicles."

Remedy

A dealer will install an electronic stability control system, free of charge. The owner notification letter is expected to be mailed January 16, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL909.

Vehicle

MAKE MODEL YEAR

THOMAS BUILT BUSES SAF-T-LINER HDX 2020

Rearview Image May Not Display/FMVSS 111

NHTSA Campaign Number: 21V918000

Manufacturer Chrysler (FCA US, LLC)

Components BACK OVER PREVENTION, STEERING

Potential Number of Units Affected 38,157

Summary

Chrysler (FCA US, LLC) is recalling certain 2021 Ram 1500 pickup trucks. The Trailer Reverse Steering Control Module (TRSCM) may prevent the rearview image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed January 12, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Y80.

Vehicle

MAKE MODEL YEAR

RAM 1500 2021

Seat May Not Lock into Upright Position/FMVSS 207

NHTSA Campaign Number: 21V919000

Manufacturer Chrysler (FCA US, LLC)

Components SEATS

Potential Number of Units Affected 793

Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Wagoneer and Grand Wagoneer vehicles. The second-row center-seat recliner pull strap may bind on the seat trim surface, preventing the seat back from locking into the upright position. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 207, "Seating Systems."

Remedy

Dealers will inspect and replace as necessary, the rear center-seat recliner strap, free of charge. Owner notification letters are expected to be mailed January 12, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Y86.

Vehicles

MAKE MODEL YEAR

JEEP GRAND WAGONEER 2022

JEEP WAGONEER 2022

Hood May Open While Driving

NHTSA Campaign Number: 21V932000

Manufacturer Honda (American Honda Motor Co.)

Components STRUCTURE, LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 724,826

Summary

Honda (American Honda Motor Co.) is recalling certain 2019 Passport, 2016-2019 Pilot, and 2017-2020 Ridgeline vehicles. The hood latch striker may become damaged and separate from the hood, which can result in the hood opening while driving.

Remedy

Dealers will either repair the hood latch striker, or replace the hood if necessary, free of charge. Owner notification letters are expected to be mailed January 17, 2022. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is PBV.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

HONDA	PASSPORT	2019
-------	----------	------

HONDA	PILOT	2016-2019
-------	-------	-----------

HONDA	RIDGELINE	2017-2020
-------	-----------	-----------

Coolant Leak Inside EGR Module May Cause Fire

NHTSA Campaign Number: 21V907000

Manufacturer BMW of North America, LLC

Components FUEL SYSTEM, DIESEL

Potential Number of Units Affected 50,404

Summary

BMW of North America, LLC (BMW) is recalling certain 2013-2018 328d, 328d xDrive, 2014-2018 328d Sports Wagon, 328d xDrive Sports Wagon, 2014-2016 535d, 535d xDrive, 2015 740Ld xDrive, 2015-2017 X3 xDrive28d SAV, and 2014-2017 X5 xDrive35d SAV diesel vehicles equipped with an Exhaust Gas Recirculation (EGR) module with an integrated cooler. The EGR cooler may leak internally, causing coolant to mix with diesel engine soot, which could result in smoldering particles and a melting intake manifold.

Remedy

Dealers will replace the EGR cooler and inspect the intake manifold, replacing it as necessary, free of charge. Owner notification letters are expected to be mailed January 12, 2022. This recall includes all vehicles previously recalled under 18V-755. Vehicles previously recalled under 18V-755 will need to have the new remedy performed for this recall. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE MODEL YEAR

BMW	328D	2013-2018
BMW	535D	2014-2016
BMW	740LD	2015
BMW	X3	2015-2017
BMW	X5	2014-2017