



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest January 10, 2022

### Rearview Image May Not Display/FMVSS 111

**NHTSA Campaign Number:** 21V00A000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 7

#### **Summary**

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Wagoneer and Grand Wagoneer vehicles. The radio software may prevent the rearview image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

#### **Remedy**

Dealers will reprogram the radio software, free of charge. Owner notification letters are expected to be mailed February 9, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is YA1.

#### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
JEEP	GRAND WAGONEER	2022
JEEP	WAGONEER	2022

## Damaged Circuit Board Affects Lighting Functions

**NHTSA Campaign Number:** 21V00H000

**Manufacturer** Daimler Trucks North America, LLC

**Components** ELECTRICAL SYSTEM, EXTERIOR LIGHTING

**Potential Number of Units Affected** 25,734

### **Summary**

Daimler Trucks North America LLC (DTNA) is recalling certain 2018 Freightliner Custom Chassis XBP, 2017-2020 XBR, 2017-2022 XBS, 2016-2019 XCL, 2016-2023 XCM, 2017-2021 XCP, 2016-2023 XCR, and 2017-2023 XCS recreational vehicle chassis. The rear mounted Power Distribution Module (PDM) may have internal damage, which could result in the rear marker lights, brake lights, or turn signals not functioning.

### **Remedy**

The remedy is currently under development. Owner notification letters are expected to be mailed February 20, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL917. This recall is an expansion of NHTSA recalls 20V-404 and 18V-502. Vehicles previously recalled will need to receive the new remedy repair once it is available.

### **Vehicles**

#### **MAKE MODEL YEAR**

FCCC	XBP	2018
FCCC	XBR	2017-2020
FCCC	XBS	2017-2022
FCCC	XCL	2016-2019
FCCC	XCM	2016-2023
FCCC	XCP	2017-2021
FCCC	XCR	2016-2023
FCCC	XCS	2017-2023

## Power Steering Assist May Fail

**NHTSA Campaign Number:** 21V989000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** STEERING

## Potential Number of Units Affected 1

### Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling one 2020 CLA250 vehicle. The power supply connection to the electric power steering may have been contaminated with melted adhesive, which can cause the power steering assist to fail while driving.

### Remedy

A dealer will inspect and repair the power supply connection, as necessary, free of charge. The owner notification letter is expected to be mailed January 11, 2021. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2021120016.

### Vehicle

MAKE	MODEL YEAR
------	------------

MERCEDES-BENZ	CLA250 2020
---------------	-------------

## Software May Cause Unintentional Vehicle Movement

**NHTSA Campaign Number:** 21V972000

**Manufacturer** Daimler Vans USA, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 48,400

### Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2019-2021 Mercedes-Benz Sprinter and Freightliner Sprinter vehicles. A software error in the park lock system may allow the vehicle to move after the gear selector has been placed in the Park 'P' position without the parking brake applied.

### Remedy

Dealers will update the electronic stability program control unit software, free of charge. Owner notification letters are expected to be mailed January 31, 2022. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3PA27 ERI/ERO.

### Vehicles

MAKE	MODEL	YEAR
------	-------	------

FREIGHTLINER	SPRINTER 1500	2019-2021
FREIGHTLINER	SPRINTER 2500	2019-2021

MAKE	MODEL	YEAR
FREIGHTLINER	SPRINTER 3500	2019-2021
FREIGHTLINER	SPRINTER 4500	2019-2021
MERCEDES-BENZ	SPRINTER 1500	2019-2021
MERCEDES-BENZ	SPRINTER 2500	2019-2021
MERCEDES-BENZ	SPRINTER 3500	2019-2021
MERCEDES-BENZ	SPRINTER 4500	2019-2021

## Electronic Control Center Circuit Board May Short

**NHTSA Campaign Number:** 21V970000

**Manufacturer** TOURIG

**Components** ELECTRICAL SYSTEM, EQUIPMENT

**Potential Number of Units Affected** 1

### Summary

TOURIG is recalling one 2017 Mercedes-Benz Sprinter vehicle, equipped with a Multiplex G9 unit used for controlling equipment and accessories in the motorhome. Excessive voltage may cause the components on the board to become damaged.

### Remedy

Dealers will install an additional circuit module to the existing component board, free of charge. The owner notification letter is expected to be mailed January 2022. Owners may contact TOURIG at 1-303-710-2914.

### Vehicle

MAKE	MODEL	YEAR
TOURIG	MERCEDES-BENZ SPRINTER	2017

## Cracks in Rear Tires

**NHTSA Campaign Number:** 21V984000

**Manufacturer** Bugatti

**Components** TIRES

## **Potential Number of Units Affected 9**

### **Summary**

Bugatti is recalling certain 2021-2022 Chiron Pur Sport vehicles. After 2,500 miles of usage, the rear tires may develop cracks.

### **Remedy**

As an interim repair, dealers will replace the rear tires on the affected vehicles every 1,875 miles or when tire age reaches 1.5 years. Once newly designed tires are available, the tires will be replaced again. Repairs will be performed free of charge. Owners with tires that have already reached 2,500 miles or 1.5 years should not drive their vehicle until the tires are replaced. Owner notification letters are expected to be mailed in January 2022. Owners may contact Bugatti customer service at 1-703-826-7545. Bugatti's number for this recall is BUGCR025.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

BUGATTI	CHIRON PUR SPORT	2021-2022
---------	------------------	-----------