



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

February 7, 2022

Vehicle May Fail to Stop at Stop Sign

NHTSA Campaign Number: 22V037000

Manufacturer Tesla, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 53,822

Summary

Tesla, Inc. (Tesla) is recalling certain 2016-2022 Model S and Model X, 2017-2022 Model 3, and 2020-2022 Model Y vehicles. The "rolling stop" functionality available as part of the Full Self-Driving (Beta) software may allow the vehicle to travel through an all-way stop intersection without first coming to a stop.

Remedy

Tesla will perform an over-the-air (OTA) software update that disables the "rolling stop" functionality, free of charge. Owner notification letters are expected to be mailed March 28, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-22-00-001.

Vehicles

MAKE MODEL YEAR

TESLA MODEL 3 2017-2022

MAKE MODEL YEAR

TESLA MODEL S 2016-2022
TESLA MODEL X 2016-2022
TESLA MODEL Y 2020-2022

Seat Belt Chime May Not Activate/FMVSS 208

NHTSA Campaign Number: 22V045000

Manufacturer Tesla, Inc.

Components ELECTRICAL SYSTEM, SEAT BELTS

Potential Number of Units Affected 817,143

Summary

Tesla, Inc. (Tesla) is recalling certain 2021-2022 Model S and Model X, 2017-2022 Model 3, and 2020-2022 Model Y vehicles. The audible chime may not activate when the vehicle starts and the driver has not buckled their seat belt. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Tesla will perform an over-the-air (OTA) software update, free of charge. Owner notification letters are expected to be mailed April 1, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-22-00-002.

Vehicles

MAKE MODEL YEAR

TESLA MODEL 3 2017-2022
TESLA MODEL S 2021-2022
TESLA MODEL X 2021-2022
TESLA MODEL Y 2020-2022

Rear Wheel Driveshaft Assemblies May Fail

NHTSA Campaign Number: 22V036000

Manufacturer General Motors, LLC

Components POWER TRAIN

Potential Number of Units Affected 1,789

Summary

General Motors, LLC (GM) is recalling certain 2021 GMC Yukon, Yukon XL, Cadillac Escalade, Escalade ESV, Chevrolet Suburban, and Chevrolet Tahoe vehicles. The rear wheel driveshaft assemblies may have internal components that were not heat-treated properly, possibly resulting in driveshaft failure.

Remedy

Dealers will replace the left and/or right rear driveshaft assemblies, free of charge. An owner notification letter mailing date has not been finalized. Owner notification letters are expected to be mailed April 15, 2022. Owners may contact Chevrolet customer service at 1-800-222-1020; Cadillac customer service at 1-800-458-8006 or GMC customer service at 1-800-462-8782. GM's number for this recall is N212351030.

Vehicles

MAKE	MODEL	YEAR
CADILLAC	ESCALADE	2021
CADILLAC	ESCALADE ESV	2021
CHEVROLET	SUBURBAN	2021
CHEVROLET	TAHOE	2021
GMC	YUKON	2021
GMC	YUKON XL	2021

Windshield Wipers May Not Operate Properly

NHTSA Campaign Number: 22V035000

Manufacturer Chrysler (FCA US, LLC)

Components VISIBILITY

Potential Number of Units Affected 171,789

Summary

Chrysler (FCA US, LLC) is recalling certain 2019-2020 Ram 2500 and Ram 3500 vehicles, Ram 3500 Cab Chassis, 4500 Cab Chassis, 5500 Cab Chassis and 3500 Cab Chassis with a gross vehicle weight rating (GVWR) of less than 10,000 lbs. The windshield wiper arms may loosen, possibly causing the wipers to function improperly and reduce the driver's visibility in certain weather conditions.

Remedy

Dealers will tighten the wiper nuts, free of charge. Owner notification letters are expected to be mailed March 18, 2022. This recall is an expansion of recall number 20V-208. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z08.

Vehicles

MAKE MODEL YEAR

RAM	2500	2019-2020
RAM	3500	2019-2020
RAM	4500	2019-2020
RAM	5500	2019-2020

Rear Axle May Be Misaligned

NHTSA Campaign Number: 22V034000

Manufacturer Volkswagen Group of America, Inc.

Components TIRES, SUSPENSION

Potential Number of Units Affected 31,058

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2019-2021 Audi A5 Sportback, RS5 Coupe, RS5 Sportback, S5 Sportback, 2020-2021 A4 Allroad, A4 Sedan, A5 Cabriolet, A5 Coupe, A6 Allroad, A6 Sedan, A7, A8, Q5, S4 Sedan, S5 Coupe, S5 Cabriolet, S6 Sedan, S7, S8, SQ5, 2021 Q5 Sportback, Q7, Q8, RS6 Avant, RS7, RSQ8, SQ5 Sportback, SQ7, and SQ8 vehicles. The rear axle alignment may not have been inspected after the repairs for Recall 21V-295 (42L1) were performed.

Remedy

Dealers will inspect the rear axle, adjust the alignment as necessary, and replace any prematurely or unevenly worn tires, free of charge. Owner notification letters are expected to be mailed March 25, 2022. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 42L5.

Vehicles

MAKE MODEL YEAR

AUDI	A4	2020-2021
AUDI	A4 ALLROAD	2020-2021
AUDI	A5	2019-2021

MAKE	MODEL	YEAR
AUDI	A5 CABRIOLET	2020-2021
AUDI	A6	2020-2021
AUDI	A6 ALLROAD	2020-2021
AUDI	A7	2020-2021
AUDI	A8	2020-2021
AUDI	Q5	2020-2021
AUDI	Q7	2021
AUDI	Q8	2021
AUDI	RS Q8	2021
AUDI	RS5	2019-2021
AUDI	RS6	2021
AUDI	RS7	2021
AUDI	S4	2020-2021
AUDI	S5	2019-2021
AUDI	S6	2020-2021
AUDI	S7	2020-2021
AUDI	S8	2020-2021
AUDI	SQ5	2020-2021
AUDI	SQ7	2021
AUDI	SQ8	2021

Turn Signal Lights May Fail/FMVSS 108

NHTSA Campaign Number: 22V033000

Manufacturer Toyota Motor Engineering & Manufacturing

Components EXTERIOR LIGHTING

Potential Number of Units Affected 41,544

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2021 Venza Hybrid vehicles. Water may enter the rear turn signal LED lights, allowing condensation to form on the circuit board, and causing a short circuit. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Dealers will replace both rear turn signal LED bulbs and replace the rear turn signal light assembly as necessary, free of charge. Owner notification letters are expected to be mailed March 19, 2022. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is 22TB01/22TA01.

Vehicle

MAKE **MODEL** **YEAR**

TOYOTA VENZA HYBRID 2021

Instrument Cluster Malfunction/FMVSS 123

NHTSA Campaign Number: 22V030000

Manufacturer Harley-Davidson Motor Company

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 3,917

Summary

Harley Davidson Motor Company (Harley-Davidson) is recalling certain 2021 Pan America 1250S (RA1250S), Pan America 1250 (RA1250), and Sportster S (RH1250S) motorcycles. The instrument cluster module may not display the speedometer and neutral indicator at start-up when the module is below freezing temperatures. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 123, "Motorcycle Controls and Displays."

Remedy

Dealers will update the instrument cluster module software, free of charge. Owner notification letters are expected to be mailed February 8, 2022. Owners may contact Harley-Davidson customer service at 1-800-258-2464. Harley-Davidson's number for this recall is 0631.

Vehicles

MAKE **MODEL** **YEAR**

HARLEY-DAVIDSON RA1250 2021

HARLEY-DAVIDSON RA1250S 2021

HARLEY-DAVIDSON RH1250S 2021

Programmable Relay Power Center Module Failure

NHTSA Campaign Number: 22V029000

Manufacturer Forest River, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 1,699

Summary

Forest River, Inc. (Forest River) is recalling certain 2021 Battisti Coach; Federal Coach-Spirit; StarCraft Quest XL; 2022 StarTrans P/S2; Elkhart Coach; Glaval Concord II, Legacy, Primetime; StarCraft Allstar MVP, Allstar XLT; Eldorado Advance; 2021-2022 Eldorado National(K-s)-Advantage; StarTrans Senator II, Senator II HD, Candidate II; StarCraft Starquest, Starlite; Glaval Commute, Entourage, Universal; Berkshire Coach Ultra; and 2021-2023 StarCraft Allstar and Allstar XL Transit Buses.

The Programmable Relay Power Center (PRC) module can fail.

Remedy

Dealers will install a wire jumper harness to the PRC module, free of charge. Owner notification letters are expected to be mailed March 7, 2022. Owners may contact Forest River customer service at 1-800-348-7440. Forest River's number for this recall is 51-1461.

Vehicles

MAKE	MODEL	YEAR
BATTISTI CUSTOMS	BATTISTI	2021
BERKSHIRE	ULTRA 24	2021
BERKSHIRE	ULTRA 28	2021
BERKSHIRE	ULTRA 34	2021
BERKSHIRE	ULTRA 42	2021
BERKSHIRE	ULTRA BC	2021
ELDORADO	ADVANCE	2022
ELDORADO	ADVANTAGE	2021-2022
ELKHART	ECII	2022
FEDERAL COACH	SPIRIT	2021
GLAVAL BUS	COMMUTE	2021-2022
GLAVAL BUS	CONCORDE II	2022
GLAVAL BUS	ENTOURAGE	2021-2022
GLAVAL BUS	LEGACY	2022
GLAVAL BUS	PRIMETIME	2022
GLAVAL BUS	UNIVERSAL	2021-2022
STARCRAFT BUS	ALLSTAR	2021-2023
STARCRAFT BUS	ALLSTAR MVP	2022
STARCRAFT BUS	ALLSTAR XL	2021-2023
STARCRAFT BUS	ALLSTAR XLT	2022
STARCRAFT BUS	QUEST XL	2021
STARCRAFT BUS	STARLITE	2021-2022
STARCRAFT BUS	STARQUEST	2021-2022
STARTRANS	CANDIDATE II	2021-2022

MAKE	MODEL	YEAR
STARTRANS	PS2	2022
STARTRANS	SENATOR II	2021-2022
STARTRANS	SENATOR II HD	2021-2022