



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

March 14, 2022

### Seat Belt Pretensioner May Explode

**NHTSA Campaign Number:** 22V123000

**Manufacturer** Hyundai Motor America

**Components** SEAT BELTS

**Potential Number of Units Affected** 140

#### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2022 Elantra and Elantra HEV vehicles. In the event of a crash, the front passenger-side seat belt pretensioner may explode upon deployment.

#### **Remedy**

Dealers will replace the seat belt pretensioners, free of charge. Owner notification letters are expected to be mailed May 2, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 220. This recall is an expansion of NHTSA recall numbers 21V-796 and 22V-069.

#### **Vehicles**

MAKE	MODEL	YEAR
HYUNDAI	ELANTRA	2022
HYUNDAI	ELANTRA HEV	2022

## Seat Belt Pretensioners May Explode

**NHTSA Campaign Number:** 22V127000

**Manufacturer** Kia Motors America

**Components** SEAT BELTS

**Potential Number of Units Affected** 213

### **Summary**

Kia Motors America (Kia) is recalling certain 2022 Sorento Hybrid and Sorento Plug-in Hybrid vehicles. In the event of a crash, the front driver-side and/or passenger-side seat belt pretensioner(s) may explode upon deployment.

### **Remedy**

Dealers will replace the seatbelt pretensioner(s), free of charge. Owner notification letters are expected to be mailed May 3, 2022. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC231.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
KIA	SORENTO HYBRID	2022
KIA	SORENTO PHEV	2022

## Unsecured Air Bag Control Unit

**NHTSA Campaign Number:** 22V124000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 14

### **Summary**

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 S580 4Matic vehicles. The air bag control unit may be improperly secured and may result in an unintentional air bag or seat belt deployment, or an improper deployment in the event of a crash.

### **Remedy**

Dealers will inspect and tighten the air bag control unit fastening nuts, as necessary, free of charge. Owner notification letters are expected to be mailed May 3, 2022. Owners may contact MBUSA customer service at 1-800-637-6372.

### **Vehicle**

MAKE	MODEL	YEAR
------	-------	------

MERCEDES-BENZ	S580	2021
---------------	------	------

## Loose Rear Brake Caliper Housing Fasteners

**NHTSA Campaign Number:** 22V125000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 4

### Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2020 AMG CLA 35 and 2021 GLA 250 vehicles. The rear brake caliper housing fasteners may be loose, which can reduce brake performance or cause rear brake components to detach from the vehicle.

### Remedy

Dealers will inspect and tighten the fasteners on the rear brake caliper housings, as necessary, free of charge. Owner notification letters are expected to be mailed May 3, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

### Vehicles

MAKE	MODEL	YEAR
------	-------	------

MERCEDES-BENZ	AMG CLA35	2020
---------------	-----------	------

MERCEDES-BENZ	GLA250	2021
---------------	--------	------

## Low Air Pressure May Apply Parking Brake

**NHTSA Campaign Number:** 22V128000

**Manufacturer** Hino Motors Sales U.S.A., Inc.

**Components** SERVICE BRAKES, AIR

**Potential Number of Units Affected** 141

### Summary

Hino Motors Sales U.S.A., Inc. (Hino) is recalling certain 2022 NJ7A vehicles. The charge pipe flare nut attached to the air compressor may not have been tightened properly, resulting in low air pressure in the system.

### **Remedy**

Dealers will tighten the charge pipe flare nut, free of charge. Owner notification letters are expected to be mailed on May 3, 2022. Owners may contact Hino's customer service at 1-248-699-9390. Hino's number for this recall is M0360.

### **Vehicle**

#### **MAKE MODEL YEAR**

HINO NJ7A 2022

## **Improperly Programmed ECU May Cause Engine Stall**

**NHTSA Campaign Number:** 22V130000

**Manufacturer** Yamaha Motor Corporation, USA

**Components** ENGINE AND ENGINE COOLING

**Potential Number of Units Affected** 3,594

### **Summary**

Yamaha Motor Corporation, USA (Yamaha) is recalling certain 2021-2022 MT-09, MT-09 SP, and MTT9GT (Tracer 9 GT) motorcycles. Improper electronic control unit (ECU) programming may limit the throttle response, cause an engine stall, or fail to illuminate the engine warning light when a system error occurs.

### **Remedy**

Owners should not operate their motorcycle, other than to take it to a dealer, until the remedy is performed. Dealers will reprogram the ECU, free of charge. Owner notification letters are expected to be mailed March 17, 2022. Owners may contact Yamaha customer service at 1-866-894-1626. Yamaha's number for this recall is 990158.

### **Vehicles**

#### **MAKE MODEL YEAR**

YAMAHA MT-09 2021-2022

YAMAHA MTT9GT 2021-2022

# Fuel Hose Leak in Engine Compartment

**NHTSA Campaign Number:** 22V134000

**Manufacturer** Daimler Vans USA, LLC

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 42,132

## **Summary**

Daimler Vans USA, LLC (DVUSA) is recalling certain 2017-2022 Mercedes-Benz Metris vehicles. The connection of the upper and lower fuel hoses to the engine may be insecure, which can result in a fuel leak.

## **Remedy**

Dealers will inspect and repair the fuel hose connections, and replace the clamps and fuel hose, as necessary, free of charge. Owner notification letters are expected to be mailed April 11, 2022. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS2KRAUCH.

## **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

MERCEDES-BENZ	METRIS	2017-2022
---------------	--------	-----------