



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

March 21, 2022

Blank or Distorted Rearview Camera Image

NHTSA Campaign Number: 22V151000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 78,376

Summary

Ford Motor Company (Ford) is recalling certain 2021-2022 Edge vehicles. A software error may cause the rearview camera to display a blank or distorted image when the vehicle is in reverse.

Remedy

The rearview camera software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed April 25, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S14.

Vehicle

MAKE MODEL YEAR

FORD EDGE 2021-2022

Delayed Deployment of Front Side Air Bag

NHTSA Campaign Number: 22V152000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 222,892

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019-2020 Atlas, 2020-2023 Atlas Cross Sport, and 2021-2023 Atlas FL vehicles. The door wiring harness electrical contacts may corrode, disrupting the electrical connection and delaying the deployment of the driver or passenger front side air bag during a side impact crash.

Remedy

The remedy is currently under development. Interim owner notification letters informing owners of the safety risk are expected to be mailed May 10, 2022. A second notice will be sent once the remedy becomes available. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 97GF.

Vehicles

MAKE	MODEL	YEAR
VOLKSWAGEN	ATLAS	2019-2023
VOLKSWAGEN	ATLAS CROSS SPORT	2020-2023

ESC Light May Not Indicate Malfunction/FMVSS 126

NHTSA Campaign Number: 22V140000

Manufacturer Chrysler (FCA US, LLC)

Components SERVICE BRAKES, HYDRAULIC, ELECTRONIC STABILITY CONTROL

Potential Number of Units Affected 370,437

Summary

Chrysler (FCA US, LLC) is recalling certain 2019-2022 Ram 2500 and 2021-2022 Dodge Durango vehicles, and 2019-2022 3500 cab chassis with GVWR less than 10,000 lbs. The ABS control module software may prevent the electronic stability control (ESC) malfunction indicator light from illuminating during certain conditions. As such,

these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 126, "Electronic Stability Control Systems."

Remedy

Dealers will update the ABS control module software, free of charge. Owner notification letters are expected to be mailed April 29, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z20.

Vehicles

MAKE	MODEL	YEAR
DODGE	DURANGO	2021-2022
RAM	2500	2019-2022
RAM	3500	2019-2022

Taillight Malfunction/FMVSS 108

NHTSA Campaign Number: 22V141000

Manufacturer General Motors, LLC

Components EXTERIOR LIGHTING

Potential Number of Units Affected 9

Summary

General Motors, LLC (GM) is recalling certain 2022 GMC Hummer EV vehicles. Taillight software can cause one or both rear taillights to become inoperative, or remain fully or partially illuminated. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Dealers will inspect and replace as necessary, the left and/or right rear taillight assemblies. Owner notification letters are expected to be mailed April 25, 2022. Owners may contact GMC customer service at 1-800-462-8782. GM's number for this recall is N222359830.

Vehicle

MAKE	MODEL	YEAR
GMC	HUMMER EV	2022

Windshield Wiper Motor May Fail

NHTSA Campaign Number: 22V142000

Manufacturer Ford Motor Company

Components VISIBILITY

Potential Number of Units Affected 157,306

Summary

Ford Motor Company (Ford) is recalling certain 2021 F-150 vehicles. The front windshield wiper motor may become inoperative, causing the wipers to fail.

Remedy

Dealers will replace the front windshield wiper motor, free of charge. Owner notification letters are expected to be mailed April 18, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S12.

Vehicle

MAKE MODEL YEAR

FORD F-150 2021

Fuel Gauge May Display Inaccurate Fuel Reading

NHTSA Campaign Number: 22V155000

Manufacturer Volkswagen Group of America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 45,789

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2021 Audi RS6 Avant, RS7, 2020-2021 A6 Allroad, S6 Sedan, S7, 2019-2021 A6 Sedan, and A7 vehicles. The fuel level sender may stick, causing an inaccurate fuel level reading to be displayed on the instrument cluster.

Remedy

Dealers will install a new sensor in the tank, free of charge. Owner notification letters are expected to be mailed May 13, 2022. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 20DN.

Vehicles

MAKE MODEL YEAR

AUDI	A6	2019-2021
AUDI	A7	2019-2021
AUDI	RS6	2021
AUDI	RS7	2021
AUDI	S6	2020-2021
AUDI	S7	2020-2021