



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

April 11, 2022

Roof Rail Air Bags May Not Deploy

NHTSA Campaign Number: 22V210000

Manufacturer General Motors, LLC

Components AIR BAGS

Potential Number of Units Affected 89

Summary

General Motors, LLC (GM) is recalling certain 2020-2022 Chevrolet Traverse and 2021-2022 Buick Enclave vehicles. The harness connector to the left or right side roof rail air bag may have incompatible electrical terminals, which could prevent the air bags from deploying in a crash.

Remedy

Dealers will replace the harness connector to the roof rail air bags, free of charge. Owner notification letters are expected to be mailed May 16, 2022. Owners may contact Buick customer service at 1-800-521-7300 or Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N212352140.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

BUICK	ENCLAVE	2021-2022
-------	---------	-----------

CHEVROLET	TRAVERSE	2020-2022
-----------	----------	-----------

Improper Deployment of Rear Air Bags

NHTSA Campaign Number: 22V215000

Manufacturer Mercedes-Benz USA, LLC

Components AIR BAGS, SEATS

Potential Number of Units Affected 15

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021-2022 Maybach S580 vehicles. Trim parts on both front seats may detach during rear air bag deployment, which can damage the air bag cushion or cause the air bag to deploy improperly.

Remedy

Dealers will replace the trim parts, free of charge. Owner notification letters are expected to be mailed May 31, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

MERCEDES-BENZ	MAYBACH S580	2021-2022
---------------	--------------	-----------

Seat Belt May Not Lock/FMVSS 209 & 208

NHTSA Campaign Number: 22V219000

Manufacturer Jaguar Land Rover North America, LLC

Components SEAT BELTS

Potential Number of Units Affected 14,812

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2016-2017 Range Rover and Range Rover Sport vehicles. The driver's seat belt emergency locking retractor may not lock as intended. As such, these vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard (FMVSS) numbers 209, "Seat Belt Assemblies" and 208, "Occupant Crash Protection."

Remedy

Dealers will inspect and replace the seat belt assembly, as necessary, free of charge. Owner notification letters are expected to be mailed June 3, 2022. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N678. This recall replaces NHTSA recall number 19V-350. Vehicles previously

inspected under recall 19V-350 that did not receive a replacement seat belt assembly will need to have this new recall remedy performed.

Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2016-2017
LAND ROVER	RANGE ROVER SPORT	2016-2017

Rearview Camera Display May Not Operate

NHTSA Campaign Number: 22V183000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 119

Summary

Ford Motor Company (Ford) is recalling certain 2022 Transit vehicles. The rearview camera supplied in the Rear Video Camera and Prep Kit will not function when installed by the final stage manufacturer (upfitter), resulting in a blank rearview image.

Remedy

Dealers will update the audio control module configuration settings, free of charge. Owner notification letters are expected to be mailed April 25, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S18.

Vehicle

MAKE MODEL YEAR

FORD TRANSIT 2022

Reduced Brake Performance

NHTSA Campaign Number: 22V205000

Manufacturer Daimler Trucks North America, LLC

Components SERVICE BRAKES, AIR

Potential Number of Units Affected 13

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2023 Western Star 4900 trucks. The inversion valve air lines may have been incorrectly installed, potentially reducing brake performance.

Remedy

Dealers will inspect and repair the inversion valve air lines, free of charge. Owner notification letters are expected to be mailed May 29, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-924.

Vehicle

MAKE	MODEL YEAR
WESTERN STAR 4900	2023

Unsecured Steering Module Electrical Connector

NHTSA Campaign Number: 22V214000

Manufacturer Mercedes-Benz USA, LLC

Components STEERING

Potential Number of Units Affected 4

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 S580 4Matic and S500 4Matic vehicles. The electrical connector to the steering column module may not be secured properly, which can disable gear shifts and/or safety features including the electronic stability program, the driver's air bag, and turn signal indicators.

Remedy

Dealers will inspect and reinstall the cover for the electrical connector, as necessary, free of charge. Owner notification letters are expected to be mailed May 31, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL YEAR
MERCEDES-BENZ S500	2021
MERCEDES-BENZ S580	2021

Loss of Power Steering Assist

NHTSA Campaign Number: 22V204000

Manufacturer Mack Trucks, Inc.

Components STEERING

Potential Number of Units Affected 33

Summary

Mack Trucks, Inc. (Mack) is recalling certain 2023 LR Battery Electric trucks. During certain driving maneuvers, the power steering system may lose pressure, causing a loss of power steering assist.

Remedy

No remedy has been established at this time. Owner notification letters are expected to be mailed on May 30, 2022. Owners may contact Mack's customer service at 1-800-866-1177. Mack's number for this recall is SC0434.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

MACK	LR ELECTRIC	2023
------	-------------	------

Transmission May Shift into Neutral While Driving

NHTSA Campaign Number: 22V188000

Manufacturer Ford Motor Company

Components POWER TRAIN

Potential Number of Units Affected 47,084

Summary

Ford Motor Company (Ford) is recalling certain 2021 F-150 vehicles. The Diagnostic Trouble Code (DTC) for low transmission fluid pressure may falsely activate and cause the transmission to unexpectedly shift into neutral.

Remedy

Dealers will update the Powertrain Control Module (PCM) software, free of charge. Owner notification letters are expected to be mailed May 2, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S15.

Vehicle

MAKE MODEL YEAR

FORD F-150 2021

Rearview Camera Display May Not Operate Correctly

NHTSA Campaign Number: 22V186000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 305

Summary

Ford Motor Company (Ford) is recalling certain 2022 Transit vehicles. The image processing module for the 360-degree camera system may not process the image from the rearview camera under certain rear loading vehicle conditions.

Remedy

Dealers will update the Image Processing Module B (IPMB) software, free of charge. Owner notification letters are expected to be mailed April 25, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S16.

Vehicle**MAKE MODEL YEAR**

FORD TRANSIT 2022