



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

April 25, 2022

[Airbag Control Unit Software Malfunction](#)

NHTSA Campaign Number: 22V240000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 1,029

Summary

BMW of North America, LLC (BMW) is recalling certain 2022-2023 iX xDrive40, iX XDrive50, and iX M60 vehicles. The air bag malfunction indicator light and display message may not illuminate in the event of a problem with the air bag control or pedestrian protection systems, due to incorrect software.

Remedy

Dealers will reprogram the air bag control unit software, free of charge. Owner notification letters are expected to be mailed June 6, 2022. Owners may contact BMW customer service at 1-800-525-7417.

Vehicle

MAKE MODEL YEAR

BMW IX 2022-2023

Driver's Air Bag Inflator May Explode

NHTSA Campaign Number: 22V246000

Manufacturer General Motors, LLC

Components AIR BAGS

Potential Number of Units Affected 2,687

Summary

General Motors, LLC (GM) is recalling certain 2015 Buick Enclave, Chevrolet Traverse and GMC Acadia vehicles. The driver's air bag inflator may explode during deployment, due to a manufacturing defect.

Remedy

Dealers will replace the driver's air bag module, free of charge. Owner notification letters are expected to be mailed May 30, 2022. Owners may contact Buick customer service at 1-800-521-7300; Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-800-462-8782. GM's number for this recall is N222366190.

Vehicles

| MAKE | MODEL | YEAR |
|-------------|--------------|-------------|
| BUICK | ENCLAVE | 2015 |
| CHEVROLET | TRAVERSE | 2015 |
| GMC | ACADIA | 2015 |

Head Restraint Cushion May Detach

NHTSA Campaign Number: 22V247000

Manufacturer Ford Motor Company

Components SEATS

Potential Number of Units Affected 933

Summary

Ford Motor Company (Ford) is recalling certain 2022 Lincoln Aviator vehicles. The front-row driver and passenger seat power head restraint cushion may detach from the head restraint assembly when adjusted to the full forward position.

Remedy

Dealers will replace the front-row passenger and driver head restraints, free of charge. Owner notification letters are expected to be mailed May 9, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S23.

Vehicle

MAKE MODEL YEAR

LINCOLN AVIATOR 2022

Head Restraints Not Welded Properly/FMVSS 202

NHTSA Campaign Number: 22V248000

Manufacturer Chrysler (FCA US, LLC)

Components SEATS

Potential Number of Units Affected 114

Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Compass vehicles. The front seat head restraints were not welded properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 202, "Head Restraints."

Remedy

Dealers will replace both front seat head restraints, free of charge. Owner notification letters are expected to be mailed June 3, 2022. Owners may contact FCA US LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z36.

Vehicle

MAKE MODEL YEAR

JEEP COMPASS 2022

Rearview Camera Image May Not Display/FMVSS 111

NHTSA Campaign Number: 22V252000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 21,904

Summary

Ford Motor Company (Ford) is recalling certain 2019 F-150, Super Duty F-250, F-350, F-450, and F-550 vehicles. Due to a poor electrical connection, the rearview camera may intermittently display a blank or distorted image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will replace the rearview camera, free of charge. Owner notification letters are expected to be mailed May 16, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20C19.

Vehicles

MAKE MODEL YEAR

FORD F-150 2019
FORD F-250 SD 2019
FORD F-350 SD 2019
FORD F-450 SD 2019
FORD F-550 SD 2019

Inoperable Rearview Camera Display/FMVSS 111

NHTSA Campaign Number: 22V232000

Manufacturer Mercedes-Benz USA, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 126,443

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2018-2021 CLA-Class, GLE/GLS-Class, A-Class, C-Class, E-Class, E-Class Coupe/Convertible, GLA/GLB-Class, GLC-Class, CLS-Class, and EQC-Class vehicles. Please refer to MBUSA's recall report for specific vehicle model details. The rearview camera may not display the rearview image due to a software error. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will update the rearview camera software, free of charge. Owner notification letters are expected to be mailed June 7, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

| MAKE | MODEL | YEAR |
|---------------|-------------|-----------|
| MERCEDES-BENZ | A220 | 2019-2020 |
| MERCEDES-BENZ | AMG A35 | 2020 |
| MERCEDES-BENZ | AMG C43 | 2019-2021 |
| MERCEDES-BENZ | AMG C63 | 2019-2021 |
| MERCEDES-BENZ | AMG C63 S | 2019-2021 |
| MERCEDES-BENZ | AMG CLA35 | 2020-2021 |
| MERCEDES-BENZ | AMG CLA45 | 2020-2021 |
| MERCEDES-BENZ | AMG CLS53 | 2019-2020 |
| MERCEDES-BENZ | AMG E53 | 2019-2020 |
| MERCEDES-BENZ | AMG GLA35 | 2021 |
| MERCEDES-BENZ | AMG GLA45 | 2021 |
| MERCEDES-BENZ | AMG GLB35 | 2021 |
| MERCEDES-BENZ | AMG GLC43 | 2020 |
| MERCEDES-BENZ | AMG GLC63 | 2020 |
| MERCEDES-BENZ | AMG GLC63 S | 2020 |
| MERCEDES-BENZ | C300 | 2019-2021 |
| MERCEDES-BENZ | C350E | 2020 |
| MERCEDES-BENZ | CLA250 | 2020 |
| MERCEDES-BENZ | CLS450 | 2019-2020 |
| MERCEDES-BENZ | E300 | 2019 |
| MERCEDES-BENZ | E350 | 2020-2021 |
| MERCEDES-BENZ | E400 | 2018 |
| MERCEDES-BENZ | E450 | 2019-2021 |
| MERCEDES-BENZ | GLA250 | 2021 |
| MERCEDES-BENZ | GLB250 | 2020-2021 |
| MERCEDES-BENZ | GLC300 | 2020 |
| MERCEDES-BENZ | GLC350E | 2020 |
| MERCEDES-BENZ | GLE350 | 2020 |
| MERCEDES-BENZ | GLE450 | 2020 |
| MERCEDES-BENZ | GLS450 | 2020 |

Frayed Passenger Seat Belt Buckle Wires

NHTSA Campaign Number: 22V236000

Manufacturer Prevest Car (US) Inc.

Components SEAT BELTS

Potential Number of Units Affected 33

Summary

Prevost Car (US) Inc. (Prevost) is recalling certain 2018 X3-45 buses. The passenger seat belt buckle wires may be frayed.

Remedy

Prevost will replace the seat belt buckles, free of charge. Owner notification letters are expected to be mailed June 3, 2022. Owners may contact Prevost customer service at 1-866-870-2046.

Vehicle

MAKE MODEL YEAR

PREVOST X3-45 2018

Stability Control Deactivated on Startup/FMVSS 126

NHTSA Campaign Number: 22V239000

Manufacturer Toyota Motor Engineering & Manufacturing

Components ELECTRONIC STABILITY CONTROL

Potential Number of Units Affected 458,054

Summary

Toyota Engineering & Manufacturing (Toyota) is recalling certain 2022 Lexus LX, Lexus NX HEV, Lexus NX PHEV, Toyota RAV4 HEV, 2021-2022 Lexus LS HEV, Toyota Mirai, RAV4 PRIME, Sienna, Venza, and 2020-2022 Toyota Highlander HEV vehicles. The Skid Control ECU software may not turn on the Vehicle Stability Control (VSC) system when the vehicle is restarted after the driver has disabled the VSC system. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 126, "Electronic Stability Control Systems."

Remedy

Dealers will update the Skid Control ECU software, free of charge. Owner notification letters are expected to be mailed May 16, 2022. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is 22TA03. Lexus' number for this recall is 22LA01.

Vehicles

| MAKE | MODEL | YEAR |
|-------|---------|-----------|
| LEXUS | LS500 H | 2021-2022 |
| LEXUS | LX600 | 2022 |
| LEXUS | NX350H | 2022 |
| LEXUS | NX450H+ | 2022 |

| MAKE | MODEL | YEAR |
|-------------|-------------------|-------------|
| TOYOTA | HIGHLANDER HYBRID | 2020-2022 |
| TOYOTA | MIRAI | 2021-2022 |
| TOYOTA | RAV4 HYBRID | 2022 |
| TOYOTA | RAV4 PRIME | 2021-2022 |
| TOYOTA | SIENNA | 2021-2022 |
| TOYOTA | VENZA | 2021-2022 |

Windshield Wipers May Fail

NHTSA Campaign Number: 22V250000

Manufacturer Ford Motor Company

Components VISIBILITY

Potential Number of Units Affected 652,996

Summary

Ford Motor Company (Ford) is recalling certain 2020-2021 F-150, Expedition, 2020-2022 Super Duty F-250, F-350, F-450, F-550, and 2020-2021 Lincoln Navigator vehicles. The windshield wiper arms may break, causing the windshield wipers to fail.

Remedy

Dealers will replace both front windshield wiper arms, free of charge. Owner notification letters are expected to be mailed May 23, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S26.

Vehicles

| MAKE | MODEL | YEAR |
|-------------|--------------|-------------|
| FORD | EXPEDITION | 2020-2021 |
| FORD | F-150 | 2020-2021 |
| FORD | F-250 SD | 2020-2022 |
| FORD | F-350 SD | 2020-2022 |
| FORD | F-450 SD | 2020-2022 |
| FORD | F-550 SD | 2020-2022 |
| LINCOLN | NAVIGATOR | 2020-2021 |

Steering Column Wiring Too Short

NHTSA Campaign Number: 22V253000

Manufacturer Ford Motor Company

Components STEERING

Potential Number of Units Affected 19,175

Summary

Ford Motor Company (Ford) is recalling certain 2022 F-150 vehicles. The power-adjustable telescoping steering column connector wiring may be too short. Wiring that is too short can become damaged or separate if the adjustable steering column is extended all the way.

Remedy

Dealers will inspect the steering column wiring harness and repair the wiring, as necessary, free of charge. Owner notification letters are expected to be mailed May 9, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S24.

Vehicle

MAKE MODEL YEAR

FORD F-150 2022

Unintentional Rollaway Due to Detached Shift Cable

NHTSA Campaign Number: 22V254000

Manufacturer Ford Motor Company

Components POWER TRAIN

Potential Number of Units Affected 96,015

Summary

Ford Motor Company (Ford) is recalling certain 2015 Escape vehicles equipped with 2.0L engines. The bushing that attaches the shifter cable to the transmission may degrade or detach.

Remedy

Dealers will replace the under hood shifter bushing and add a protective cap over the shift cable bushing, free of charge. Owner notification letters are expected to be mailed May 9, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S25.

Vehicle

MAKE MODEL YEAR

FORD ESCAPE 2015