



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

May 16, 2022

### Front Crash Sensors May Malfunction

**NHTSA Campaign Number:** 22V320000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 19

#### **Summary**

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2022 New Range Rover vehicles. Due to improperly tightened fasteners, the front crash sensors may become loose and malfunction.

#### **Remedy**

Dealers will tighten the front crash sensor fasteners, free of charge. Owner notification letters are expected to be mailed July 8, 2022. Owners may contact Land Rover customer service at 1-800-369-1000. Land Rover's number for this recall is N685.

#### **Vehicle**

MAKE	MODEL	YEAR
------	-------	------

LAND ROVER	NEW RANGE ROVER	2022
------------	-----------------	------

## Improperly Calibrated Front Passenger OCS/FMVSS208

**NHTSA Campaign Number:** 22V319000

**Manufacturer** Rivian Automotive, LLC

**Components** SEATS, AIR BAGS

**Potential Number of Units Affected** 502

### **Summary**

Rivian Automotive, LLC (Rivian) is recalling certain 2022 R1T vehicles. The Occupant Classification System (OCS) may not deactivate the air bag when a child or child seat occupies the front passenger seat. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

### **Remedy**

Rivian Service Centers will replace the front passenger seat, free of charge. Owner notification letters are expected to be mailed July 1, 2022. Owners may contact Rivian customer service at 1-734-855-4345. Rivian's number for this recall is FSAM-651.

### **Vehicle**

#### **MAKE MODEL YEAR**

RIVIAN R1T      2022

## Fisheye and Narrow Camera Views Swapped

**NHTSA Campaign Number:** 22V317000

**Manufacturer** Tesla, Inc.

**Components** FORWARD COLLISION AVOIDANCE, LANE DEPARTURE, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 5

### **Summary**

Tesla, Inc. (Tesla) is recalling certain 2021 Model 3 and Model Y vehicles. The fisheye and narrow camera cable terminals were incorrectly installed in the cable harness connector, resulting in swapped camera views.

### **Remedy**

Tesla Service will correct the swapped terminals and recalibrate the cameras, free of charge. Owner notification letters are expected to be mailed July 8, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-22-17-007.

## Vehicles

### MAKE MODEL YEAR

TESLA MODEL 3 2021

TESLA MODEL Y 2021

## Brake Booster Corrosion May Impair Braking

**NHTSA Campaign Number:** 22V315000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 292,287

## Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2006-2012 ML-Class, GL-Class, and R-Class vehicles. Please refer to MBUSA's recall report for specific vehicle model details. Moisture may accumulate and cause corrosion in the brake booster housing unit, which can result in reduced brake performance or brake failure.

## Remedy

Owners are advised not to drive their vehicles until the remedy has been performed. Dealers will remove the rubber sleeve, inspect the brake booster, and as necessary, replace the brake booster. All repairs will be performed free of charge. Owner notification letters are expected to be mailed May 27, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

## Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	AMG R63	2007
MERCEDES BENZ	GL320	2007-2009
MERCEDES BENZ	GL350	2010-2012
MERCEDES BENZ	GL450	2007-2012
MERCEDES BENZ	GL550	2008-2012
MERCEDES BENZ	ML320	2007-2009
MERCEDES BENZ	ML350	2006-2011
MERCEDES BENZ	ML450	2010-2011

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MERCEDES BENZ	ML500	2006-2007
MERCEDES BENZ	ML550	2008-2011
MERCEDES BENZ	R320	2007-2009
MERCEDES BENZ	R500	2006-2007
MERCEDES-BENZ	AMG ML63	2007-2011
MERCEDES-BENZ	R350	2006-2012
MERCEDES-BENZ	R550	2008

## Overheating May Cause Center Display Malfunction

**NHTSA Campaign Number:** 22V296000

**Manufacturer** Tesla, Inc.

**Components** BACK OVER PREVENTION, EQUIPMENT

**Potential Number of Units Affected** 129,960

### **Summary**

Tesla, Inc. (Tesla) is recalling certain 2021-2022 Model S, Model X, and 2022 Model 3 and Model Y vehicles operating certain firmware releases. The infotainment central processing unit (CPU) may overheat during the preparation or process of fast-charging, causing the CPU to lag or restart.

### **Remedy**

Tesla will perform an over-the-air (OTA) software update that will improve CPU temperature management, free of charge. Owner notification letters are expected to be mailed July 1, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-22-00-009.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
TESLA	MODEL 3	2022
TESLA	MODEL S	2021-2022
TESLA	MODEL X	2021-2022
TESLA	MODEL Y	2022

## Insufficient Air Volume in Brake System

**NHTSA Campaign Number:** 22V295000

**Manufacturer** Mack Trucks, Inc.

**Components** SERVICE BRAKES, AIR

**Potential Number of Units Affected** 14

### **Summary**

Mack Trucks, Inc. (Mack) is recalling certain 2022 Granite trucks. The air tanks have an insufficient volume of air for the brake system. As such, these vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard number 121, "Air Brake Systems."

### **Remedy**

Dealers will install new air tanks, free of charge. Owner notification letters are expected to be mailed on July 1, 2022. Owners may contact Mack's customer service at 1-800-866-1177. Mack's number for this recall is SCC 0435.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

MACK	GRANITE (GR)	2022-2023
------	--------------	-----------

## **Power Steering Pressure Line May Detach and Leak**

**NHTSA Campaign Number:** 22V290000

**Manufacturer** Jayco, Inc.

**Components** STEERING

**Potential Number of Units Affected** 36

### **Summary**

Jayco, Inc. (Jayco) is recalling certain 2021-2022 Jayco Greyhawk, Greyhawk Prestige, Redhawk, Entegra Esteem, and Odyssey recreational vehicles. An inadequate connection between the power steering pressure line and the brake Hydroboost unit may result in a sudden loss of power steering fluid.

### **Remedy**

Dealers will inspect the connection between the power steering lines and the Hydroboost unit, and replace the power steering lines, as necessary, free of charge. Owner notification letters are expected to be mailed July 1, 2022. Owners may contact Jayco customer service at Jayco customer service at 1-800-283-8267. Jayco's number for this recall is 22V-089.

## Vehicles

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
ENTEGR	ESTEEM	2021-2022
ENTEGR	ODYSSEY	2021-2022
JAYCO	GREYHAWK	2021-2022
JAYCO	GREYHAWK PRESTIGE	2021-2022
JAYCO	REDHAWK	2021-2022