



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

May 2, 2022

### Turn Signal Malfunction/FMVSS 108

**NHTSA Campaign Number:** 22V249000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 65

#### **Summary**

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Grand Cherokee and Grand Cherokee L vehicles. Due to a software programming error, any failure with the turn signals would not be communicated to the driver. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

#### **Remedy**

Dealers will update the body control module software, free of charge. Owner notification letters are expected to be mailed June 3, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z35.

#### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

JEEP	GRAND CHEROKEE	2022
------	----------------	------

## Improperly Manufactured Fuel Tank

**NHTSA Campaign Number:** 22V259000

**Manufacturer** Nissan North America, Inc.

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 52

### **Summary**

Nissan North America, Inc. (Nissan) is recalling certain 2022 Rogue vehicles. Due to a manufacturing error, an area on the bottom wall of the fuel tank may be too thin.

### **Remedy**

Dealers will replace the fuel tank assembly and install a new lock ring, gasket, and o-ring seal, free of charge. Owner notification letters are expected to be mailed May 19, 2022. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC887.

### **Vehicle**

**MAKE MODEL YEAR**

NISSAN ROGUE 2022

## Unit of Speed May Fail to Display/FMVSS 101

**NHTSA Campaign Number:** 22V263000

**Manufacturer** Tesla, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 48,184

### **Summary**

Tesla, Inc. (Tesla) is recalling certain 2018-2022 Model 3 Performance vehicles. The unit of speed (mph or km/h) may fail to display on the speedometer while in Track Mode. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 101, "Control and Displays."

### **Remedy**

Tesla will perform an over-the-air (OTA) software update, free of charge. Owner notification letters are expected to be mailed June 6, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-22-00-008.

## Vehicle

**MAKE MODEL YEAR**

TESLA MODEL 3 2018-2022

## Headlight Failure

**NHTSA Campaign Number:** 22V261000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 129

## Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 GLC 300, GLC 300 4Matic, AMG GLC 63 4Matic, AMG GLC 63 S 4Matic, and AMG GLC 43 4Matic vehicles. The electrical connection for the headlights may not be watertight, which can result in headlight failure.

## Remedy

Dealers will inspect and replace the headlight sealing plugs, as necessary, free of charge. Owner notification letters are expected to be mailed June 14, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

## Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG GLC43	2021
MERCEDES-BENZ	AMG GLC63	2021
MERCEDES-BENZ	AMG GLC63 S	2021
MERCEDES-BENZ	GLC300	2021

## Sunroof Malfunction/FMVSS 118

**NHTSA Campaign Number:** 22V267000

**Manufacturer** BMW of North America, LLC

**Components** VISIBILITY

**Potential Number of Units Affected** 61,221

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2022 4 Series Gran Coupe (430i, 430i xDrive, M440i xDrive); 2019-2022 X5 sDrive40i, X5 xDrive40i, X5 xDrive50i, X5 M50i, X5M; 2021-2022 X5 xdrive45e; 2020-2022 X6 sDrive40i, X6 xDrive40i, X6 xDrive50i, X6M and 2019-2023 X7 xDrive40i, X7 xDrive50i, X7 M50i, X7 xDrive60i, X7 M60i, X7M, Alpina XB7 vehicles. The roof function control unit may be programmed incorrectly, allowing the sunroof to close without the key fob present inside the vehicle. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 118, "Power-Operated Window Systems."

### **Remedy**

Dealers will reprogram the roof function control unit, free of charge. Owner notification letters are expected to be mailed June 13, 2022. Owners may contact BMW customer service at 1-800-525-7417.

### **Vehicles**

#### **MAKE MODEL YEAR**

BMW	430I	2022
BMW	M440I	2022
BMW	X5	2019-2022
BMW	X6	2020-2022
BMW	X7	2019-2023

## **Improperly Secured Seat Belts**

**NHTSA Campaign Number:** 22V269000

**Manufacturer** Daimler Trucks North America, LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 3

### **Summary**

Daimler Trucks North America, LLC (DTNA) is recalling certain 2022 Western Star 4900 and 4700 vehicles. The seat belts may not be secured properly.

### **Remedy**

Dealers will inspect and tighten the seat belt tether bolts, as necessary, free of charge. Owner notification letters are expected to be mailed June 18, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-927.

## **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
WESTERN STAR	4700	2022
WESTERN STAR	4900	2022

## **Second Row Seats Not Correctly Installed**

**NHTSA Campaign Number:** 22V257000

**Manufacturer** Bentley Motors, Inc.

**Components** SEATS

**Potential Number of Units Affected** 1,923

### **Summary**

Bentley Motors, Inc. (Bentley) is recalling certain 2021-2022 Bentayga vehicles. The second row seats may be installed incorrectly, without being locked on all seat rails.

### **Remedy**

Dealers will check and reset the 2nd row seat rail positions to ensure proper engagement of the seat rails, free of charge. Owner notification letters are expected to be mailed May 16, 2022. Owners may contact Bentley customer service at 1-800-777-6923. Bentley's number for this recall is RC22/10 (RC36).

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
BENTLEY	BENTAYGA	2021-2022

## **Hydrogen Gas Detection Sensors May Fail**

**NHTSA Campaign Number:** 22V258000

**Manufacturer** Hyundai Motor America

**Components FUEL SYSTEM, OTHER, ELECTRICAL SYSTEM**

**Potential Number of Units Affected** 922

**Summary**

Hyundai Motor America (Hyundai) is recalling certain 2019-2021 Nexo vehicles. The hydrogen gas detection sensors may fail to detect leaks in the hydrogen gas delivery system.

**Remedy**

Owners are advised to park their vehicles outside and away from structures until the recall remedy is completed. Dealers will replace the hydrogen gas detection sensors, free of charge. Owner notification letters are expected to be mailed June 13, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 225.

**Vehicle**

**MAKE MODEL YEAR**

HYUNDAI NEXO 2019-2021