



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

June 20, 2022

### Vehicle Display Malfunction/FMVSS 111

**NHTSA Campaign Number:** 22V404000

**Manufacturer** Porsche Cars North America, Inc.

**Components** POWER TRAIN, BACK OVER PREVENTION

**Potential Number of Units Affected** 12,490

#### **Summary**

Porsche Cars North America, Inc. (Porsche) is recalling certain 2020-2022 Taycan vehicles. A software error could cause the center screen (including rearview camera image) and the touch control panel remain to black directly after the ignition is activated. Also, the Real-Top-View (including rearview camera image) could display a flickering image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

#### **Remedy**

Dealers will install new software, free of charge. Owner notification letters are expected to be mailed August 5, 2022. Owners may contact Porsche's customer service at 1-800-767-7243. Porsche's number for this recall is ANA6.

#### **Vehicle**

**MAKE MODEL YEAR**

PORSCHE TAYCAN 2020-2022

## Steering Gear Assembled Incorrectly

**NHTSA Campaign Number:** 22V401000

**Manufacturer** Mack Trucks, Inc.

**Components** STEERING

**Potential Number of Units Affected** 6,023

### **Summary**

Mack Trucks, Inc. (Mack) is recalling certain 2021-22 Granite, Anthem, LR, Pinnacle, and Terrapro tractor trailers. The steering gears may have been assembled incorrectly, which can cause the gear to fracture.

### **Remedy**

The remedy is currently under development. Owner notification letters are expected to be mailed out July 29, 2022. Owners may contact Mack customer service at 1-800-866-1177. Mack's number for this recall is SC0437.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MACK	ANTHEM (AN)	2021-2022
MACK	GRANITE (GR)	2021-2022
MACK	LR	2021-2022
MACK	PINNACLE (PI)	2021-2022
MACK	TERRAPRO (TE)	2021-2022

## Rearview Image May Not Display/FMVSS 111

**NHTSA Campaign Number:** 22V407000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 117,759

### **Summary**

Chrysler (FCA US, LLC) is recalling certain 2022 Ram 1500, 2500 pickup trucks, and 3500 Cab Chassis vehicles with GVWR less than 10,000 lbs. The radio software may prevent the rearview image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

## Remedy

Dealers will reprogram the radio software, free of charge. Owner notification letters are expected to be mailed July 29, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z47.

## Vehicles

### MAKE MODEL YEAR

RAM	1500	2022
RAM	2500	2022
RAM	3500	2022

## Malfunctioning Exterior Driver-Side Door Handle

**NHTSA Campaign Number:** 22V422000

**Manufacturer** Lamborghini (Automobili Lamborghini)

**Components** STRUCTURE

**Potential Number of Units Affected** 21

## Summary

Lamborghini (Automobili Lamborghini) is recalling certain 2022 Huracan EVO and STO vehicles. The exterior driver-side door handle may not be assembled properly, which can prevent the opening of the driver-side door from the outside.

## Remedy

Dealers will inspect and repair the driver-side door handle, as necessary, free of charge. Owner notification letters are expected to be mailed July 1, 2022. Owners may contact Automobili Lamborghini customer service at 1-866-681-6276. Automobili Lamborghini's number for this recall is L62X-R.03.22.

## Vehicle

MAKE	MODEL	YEAR
------	-------	------

LAMBORGHINI	HURACAN	2022
-------------	---------	------

## Child Safety Lock Malfunction

**NHTSA Campaign Number:** 22V411000

**Manufacturer** Ford Motor Company

## **Components LATCHES/LOCKS/LINKAGES**

**Potential Number of Units Affected** 53,103

### **Summary**

Ford Motor Company (Ford) is recalling certain four-door 2021-2022 Bronco vehicles. The passenger-side rear door may be opened from inside of the vehicle when the child safety lock is in the "ON" position.

### **Remedy**

Dealers will inspect the passenger-side child safety locks door child safety lock and latch, and replace them, if necessary, free of charge. Owner notification letters are expected to be mailed July 25, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S44.

### **Vehicle**

**MAKE MODEL YEAR**

FORD BRONCO 2021-2022

## **Vehicle Rollaway Due to ABS Malfunction**

**NHTSA Campaign Number:** 22V426000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 270,904

### **Summary**

Chrysler (FCA US, LLC) is recalling certain 2018-2019 Jeep Grand Cherokee and Dodge Durango vehicles. A malfunction in the antilock-brake system (ABS) module may illuminate the brake lights, and allow the vehicle to start and shift out of Park without the brake pedal being applied.

### **Remedy**

The remedy is under development. Owner notification letters are expected to be mailed July 29, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z48.

### **Vehicles**

**MAKE MODEL YEAR**

DODGE DURANGO 2018-2019

JEEP GRAND CHEROKEE 2018-2019

## ABS Telltale Not Enabled/FMVSS 105

**NHTSA Campaign Number:** 22V424000

**Manufacturer** PACCAR Incorporated

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 3

### **Summary**

PACCAR Incorporated (PACCAR) is recalling certain 2022 Kenworth T180 and 2023 Kenworth T280 and Peterbilt 535 vehicles. The ABS telltale was not enabled on certain vehicles, and will not illuminate even during an ABS malfunction. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 105, "Hydraulic and Electric Brake Systems."

### **Remedy**

Dealers will perform a complete software update to correct the parameter setting, free of charge. Owner notification letters are expected to be mailed August 14, 2022. Owners may contact PACCAR's customer service at 1-425-828-5888 (Kenworth); 1-940-591-4220 (Peterbilt). PACCAR's number for this recall is 22KWC and 22PBC.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
KENWORTH	T180	2022
KENWORTH	T280	2023
PETERBILT	535	2023

## Transmission May Slip Into Unexpected Gear

**NHTSA Campaign Number:** 22V425000

**Manufacturer** PACCAR Incorporated

**Components** POWER TRAIN

**Potential Number of Units Affected** 402

### **Summary**

PACCAR, Incorporated (PACCAR) is recalling certain 2022 Kenworth T180, 2021-2023 Kenworth T280, 2022-2023 Kenworth T380, 2022-2023 Peterbilt 536, and 537 vehicles. Internal components of the transmission actuator may slip, causing the actuator to become miscalibrated.

## Remedy

Dealers will replace the transmission actuator, free of charge. Owner notification letters are expected to be mailed August 14, 2022. Owners may contact PACCAR's customer service at 1-425-828-5888 (Kenworth); 1-940-591-4220 (Peterbilt). PACCAR's number for this recall is 22KWD and 22PBD.

## Vehicles

MAKE	MODEL	YEAR
KENWORTH	T180	2022
KENWORTH	T280	2021-2023
KENWORTH	T380	2022-2023
PETERBILT	536	2022-2023
PETERBILT	537	2022-2023

## Instrument Panel Not Illuminated/FMVSS 101

**NHTSA Campaign Number:** 22V415000

**Manufacturer** Ford Motor Company

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 30,244

## Summary

Ford Motor Company (Ford) is recalling certain 2022 Transit vehicles. The Instrument Panel Cluster may not properly illuminate telltales or gauges and the speedometer and tachometer pointers. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard numbers 101, "Control and Displays," and 102, "Trans Shift Lever Seq/Starter Interlock/Trans Braking Effect," and 105, "Hydraulic and Electric Brake Systems," and 208, "Occupant Crash Protection."

## Remedy

Dealers will update the instrument panel cluster software, free of charge. Owner notification letters are expected to be mailed July 25, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22C11.

## Vehicle

**MAKE MODEL YEAR**

FORD TRANSIT 2022

## High Voltage Battery Contactor May Overheat

**NHTSA Campaign Number:** 22V412000

**Manufacturer** Ford Motor Company

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 48,924

### **Summary**

Ford Motor Company (Ford) is recalling certain 2021-2022 Mustang Mach-E vehicles. The high voltage battery main contactors may overheat.

### **Remedy**

Dealers will update the on-board software, free of charge. Owner notification letters are expected to be mailed July 18, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S41.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

FORD	MUSTANG MACH E	2021-2022
------	----------------	-----------

## High Pressure Fuel Pump Failure

**NHTSA Campaign Number:** 22V406000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** FUEL SYSTEM, DIESEL

**Potential Number of Units Affected** 138,645

### **Summary**

Chrysler (FCA US, LLC) is recalling certain 2014-2020 Jeep Grand Cherokee, and 2014-2019 Ram 1500 vehicles equipped with 3.0L diesel engines. A high pressure fuel pump (HPFP) failure may introduce internal debris into the fuel system, potentially resulting in fuel starvation.

### **Remedy**

Dealers will replace the HPFP, and inspect and replace, if necessary, additional fuel system components, free of charge. Owner notification letters are expected to be mailed July 29, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLS's number for this recall is Z46.

## Vehicles

MAKE	MODEL	YEAR
JEEP	GRAND CHEROKEE	2014-2020
RAM	1500	2014-2019

## Bracket May Interfere with Seat Belt Pretensioner

**NHTSA Campaign Number:** 22V396000

**Manufacturer** Corp. Micro Bird, Inc.

**Components** SEAT BELTS, SEATS

**Potential Number of Units Affected** 3

### Summary

Corp. Micro Bird Inc. (Micro Bird) is recalling certain 2017-2018 G5 school buses equipped with an elevated floor and electrically adjustable driver's seat. An incorrect bracket may have been installed on the driver's seat and may interfere with the seat belt pretensioner.

### Remedy

Micro Bird Corp will provide instructions for inspecting the driver's seat. If the incorrect bracket is found, dealers will replace the bracket, free of charge. Owner notification letters are expected to be mailed July 25, 2022. Owner's may contact Micro Bird customer service at 1-819-477-2012. Micro Bird's number for this recall is 22-093-CUC.

### Vehicle

MAKE	MODEL	YEAR
MICRO BIRD	G5	2017-2018