



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

June 27, 2022

Steering Gear Assembled Incorrectly

NHTSA Campaign Number: 22V429000

Manufacturer Navistar, Inc.

Components STEERING

Potential Number of Units Affected 3,570

Summary

Navistar, Inc. (Navistar) is recalling certain 2022-2023 IC CE School Buses. The steering gears may have been assembled incorrectly, which can cause the gear to fracture.

Remedy

Dealers will inspect the steering gear serial numbers, and replace the steering gears as necessary, free of charge. Owner notification letters are expected to be mailed August 18, 2022. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 22514.

Vehicle

MAKE MODEL YEAR

IC BUS CE 2022-2023

Steering Gear Assembled Incorrectly

NHTSA Campaign Number: 22V428000

Manufacturer Navistar, Inc.

Components STEERING

Potential Number of Units Affected 33,655

Summary

Navistar, Inc. (Navistar) is recalling certain 2022-2023 International HX, HV, LoneStar, LT, MV, RH, IC TC Commercial Bus, and 2022 International WorkStar vehicles. The steering gears may have been assembled incorrectly, which can cause the gear to fracture.

Remedy

Dealers will inspect the steering gear serial numbers, and replace the steering gears as necessary, free of charge. Owner notification letters are expected to be mailed August 18, 2022. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 22513.

Vehicles

MAKE	MODEL	YEAR
IC BUS	TC	2022-2023
INTERNATIONAL HV		2022-2023
INTERNATIONAL HX		2022-2023
INTERNATIONAL LONESTAR		2022-2023
INTERNATIONAL LT		2022-2023
INTERNATIONAL MV		2022-2023
INTERNATIONAL RH		2022-2023
INTERNATIONAL WORKSTAR		2022

Rear Suspension Toe Link May Separate

NHTSA Campaign Number: 22V427000

Manufacturer General Motors, LLC

Components SUSPENSION

Potential Number of Units Affected 736

Summary

General Motors, LLC (GM) is recalling certain 2022 Cadillac XT5, XT6, and GMC Acadia vehicles. The left-rear suspension toe link may have been tightened improperly, which could result in a loose or separated toe link.

Remedy

Dealers will inspect the left-rear suspension and replace the fastener if it is loose or missing, free of charge. Owner notification letters are expected to be mailed August 1, 2022. Owners may contact Cadillac customer service at 1-800-458-8006 or GMC customer service at 1-800-462-8782. GM's number for this recall is N222364330.

Vehicles

MAKE	MODEL	YEAR
CADILLAC	XT5	2022
CADILLAC	XT6	2022
GMC	ACADIA	2022

Wheel May Detach From Vehicle

NHTSA Campaign Number: 22V444000

Manufacturer Toyota Motor Engineering & Manufacturing

Components WHEELS

Potential Number of Units Affected 661

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2023 Subaru Solterra and Toyota BZ4X vehicles. The hub bolts on the wheels may loosen, causing a wheel to detach from the vehicle after low-mileage use.

Remedy

Owners are advised not to drive their vehicles until they are repaired. The remedy is currently under development. Letters notifying owners of the safety risk are expected to be mailed June 24, 2022. A second letter will be sent once the remedy is available. Owners may contact Toyota's customer service at 1-800-331-4331.

Vehicles

MAKE	MODEL	YEAR
SUBARU	SOLTERRA	2023
TOYOTA	BZ4X	2023

