



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

August 1, 2022

### Seat Belt Tensioners May Not Restrain Properly

**NHTSA Campaign Number:** 22V515000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** SEAT BELTS

**Potential Number of Units Affected** 2,584

#### **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2022 Audi S3 and A3 sedans. The retention force of the seat belt tensioner on the driver and front passenger seats may be inadequate to properly restrain the occupants during a crash.

#### **Remedy**

Dealers will replace the driver and front passenger seat belt assemblies, free of charge. Owner notification letters are expected to be mailed September 16, 2022. Owners may contact Audi's customer service at 1-800-253-2834. Audi's number for this recall is 68i2.

#### **Vehicles**

##### **MAKE MODEL YEAR**

AUDI A3 2022

AUDI S3 2022

## Seat Belt Pretensioners May Not Restrain Properly

**NHTSA Campaign Number:** 22V523000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 4,927

### **Summary**

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2022-23 Land Rover Defender, Discovery, Discovery Sport, Range Rover Sport & Range Rover Velar vehicles. The driver and front passenger seat belt pretensioners may be damaged, which can cause the seat belts to not properly restrain occupants.

### **Remedy**

Dealers will inspect and replace the front seat belt assemblies, as necessary, free of charge. Owner notification letters are expected to be mailed September 16, 2022. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N720.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
LAND ROVER	DEFENDER	2022-2023
LAND ROVER	DISCOVERY	2022-2023
LAND ROVER	DISCOVERY SPORT	2022-2023
LAND ROVER	RANGE ROVER SPORT	2022-2023
LAND ROVER	RANGE ROVER VELAR	2022-2023

## Seat Belt Pretensioners May Not Restrain Properly

**NHTSA Campaign Number:** 22V524000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 176

### **Summary**

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2022 Jaguar F-Type, F-Pace, and XF vehicles. The driver and front passenger seat belt pretensioners may be damaged, which can cause the seat belts to not properly restrain occupants.

## Remedy

Dealers will inspect and replace the front seat belt assemblies, as necessary, free of charge. Owner notification letters are expected to be mailed September 16, 2022. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H412.

## Vehicles

### MAKE MODEL YEAR

JAGUAR F-PACE 2022

JAGUAR F-TYPE 2022

JAGUAR XF 2022

## Front Air Bag May Not Deploy Properly/FMVSS 208

**NHTSA Campaign Number:** 22V519000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** AIR BAGS

**Potential Number of Units Affected** 3,533

## Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2022 Rav4, Rav4 Hybrid, and Rav4 Prime vehicles. The front passenger seat may have been assembled with interference between internal parts that may cause the Occupant Classification System (OCS) sensor to incorrectly detect the occupant. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

## Remedy

Dealers will inspect and repair the front passenger seat, as necessary, free of charge. Owner notification letters are expected to be mailed September 2, 2022. Owners may contact Toyota's customer service at 1-800-331-4331. Toyota's number for this recall is 22TA08.

## Vehicles

### MAKE MODEL YEAR

TOYOTA RAV4 2022

TOYOTA RAV4 HYBRID 2022

TOYOTA RAV4 PRIME 2022

## Passenger Air Bag May Deploy Incorrectly/FMVSS 208

**NHTSA Campaign Number:** 22V526000

**Manufacturer** Tesla, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 5

### **Summary**

Tesla, Inc. (Tesla) is recalling certain 2022 Model S vehicles. The front bumper carrier structure may alter the vehicle's crash detection, causing the front passenger air bag to deploy incorrectly during certain low speed crashes. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

### **Remedy**

Tesla Service will replace the front bumper carrier structure, free of charge. Owner notification letters are expected to be mailed September 19, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-22-10-006.

### **Vehicle**

**MAKE MODEL YEAR**

TESLA MODEL S 2022

## Rearview Image May Not Display/FMVSS 111

**NHTSA Campaign Number:** 22V514000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** BACK OVER PREVENTION, EQUIPMENT

**Potential Number of Units Affected** 43,091

### **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021 Golf GTI, Jetta GLI, Jetta NF, Arteon FL, Tiguan LWB, 2022 Taos, Jetta PA, Tiguan PA, 2021-2022 Atlas Cross Sport, and Atlas FL vehicles. The manufacturing process of the eMMC memory module in the infotainment system may cause the rearview camera image not to display. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

## Remedy

Dealers will update the infotainment software, free of charge. Owner notification letters are expected to be mailed September 16, 2022. Owners may contact Volkswagen's customer service at 1-800-893-5298. Volkswagen's number for this recall is 91DV.

## Vehicles

MAKE	MODEL	YEAR
VOLKSWAGEN	ARTEON	2021
VOLKSWAGEN	ATLAS	2021-2022
VOLKSWAGEN	ATLAS CROSS SPORT	2021-2022
VOLKSWAGEN	GLI	2021
VOLKSWAGEN	GTI	2021
VOLKSWAGEN	JETTA	2021-2022
VOLKSWAGEN	TAOS	2022
VOLKSWAGEN	TIGUAN	2021-2022

## Inoperative Rearview Camera Display/FMVSS 111

**NHTSA Campaign Number:** 22V527000

**Manufacturer** Nissan North America, Inc.

**Components** BACK OVER PREVENTION, EQUIPMENT

**Potential Number of Units Affected** 10,477

## Summary

Nissan North America, Inc. (Nissan) is recalling certain 2021-2022 Rogue, 2022 Frontier, Pathfinder, and Titan rental vehicles. When the Sirius XM subscription is set to "Not Subscribed," it may cause the infotainment head unit to reboot, resulting in an inoperative rearview camera. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

## Remedy

The Infotainment system software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed July 29, 2022. Owners may contact Nissan's customer service at 1-800-867-7669. Nissan's number for this recall is R22A5 PC901 PC902.

## Vehicles

MAKE	MODEL	YEAR
NISSAN	FRONTIER	2022
NISSAN	PATHFINDER	2022

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

NISSAN ROGUE		2021-2022
--------------	--	-----------

NISSAN TITAN		2022
--------------	--	------

## Inoperative Backup Lights and Rearview Image

**NHTSA Campaign Number:** 22V522000

**Manufacturer** Subaru of America, Inc.

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 59,934

### **Summary**

Subaru of America, Inc. (Subaru) is recalling certain 2015-2021 WRX vehicles. The backup light switch may corrode and become inoperative, which can result in the backup lights not illuminating and the rearview camera image not displaying when the vehicle is in reverse.

### **Remedy**

Dealers will inspect and replace the backup light switch, as necessary, free of charge. Owner notification letters are expected to be mailed September 19, 2022. Owners may contact Subaru's customer service at 1-844-373-6614. Subaru's number for this recall is WRE-22.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

SUBARU WRX		2015-2021
------------	--	-----------

## ECM Software Programmed Without Braking Function

**NHTSA Campaign Number:** 22V508000

**Manufacturer** Isuzu Motors Limited

**Components** ENGINE AND ENGINE COOLING

**Potential Number of Units Affected** 11

### **Summary**

Isuzu Motors Limited (Isuzu) is recalling certain 2022 FTR and FVR trucks. A programming error in the ECM software calibration, resulted in the vehicles not having engine braking functionality.

### **Remedy**

Dealers will reprogram the ECM with the corrected calibration, free of charge. Owner notification letters are expected to be mailed on September 1, 2022. Owners may contact Isuzu's customer service at 1-866- 441-9638. Isuzu's number for this recall is V2204.

### **Vehicles**

#### **MAKE MODEL YEAR**

ISUZU FTR	2022
ISUZU FVR	2022

## **Fuel Pump May Fail**

**NHTSA Campaign Number:** 22V516000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 49,443

### **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019-2021 Audi Q8, and 2020-2021 Audi Q7 vehicles. A component inside the fuel pump may break, causing the fuel pump to fail.

### **Remedy**

Dealers will replace the fuel pump, free of charge. Owner notification letters are expected to be mailed September 16, 2022. Owners may contact Audi's customer service at 1-800-253-2834. Audi's number for this recall is 20DR.

### **Vehicles**

#### **MAKE MODEL YEAR**

AUDI Q7	2020-2021
AUDI Q8	2019-2021

## **Child Seat May Not Secure Properly/FMVSS 225**

**NHTSA Campaign Number:** 22V520000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** CHILD SEAT

**Potential Number of Units Affected** 75,316

### **Summary**

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2022-2023 Tacoma vehicles. One or more of the individual welds in the upper child seat anchors may be insufficient. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 225, "Child Restraint Anchorage System."

### **Remedy**

The remedy is currently under development. Owner notification letters are expected to be mailed September 02, 2022. Owners may contact Toyota's customer service at 1-800-331-4331. Toyota's number for this recall is 22TB09/ 22TA09.

### **Vehicle**

**MAKE MODEL YEAR**

TOYOTA TACOMA 2022-2023

## **High Voltage Battery May Short-Circuit**

**NHTSA Campaign Number:** 22V541000

**Manufacturer** BMW of North America, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 83

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2022-2023 iX xDrive50, iX M60, 2022 i4 eDrive40, and i4 M50 vehicles. The high voltage battery may have internal damage, resulting in an electrical short-circuit.

### **Remedy**

Owners are advised not to drive or charge their vehicles, and to park outside and away from structures until the remedy is complete. Dealers will replace the high voltage battery, free of charge. Owner notification letters are expected to be mailed September 19, 2022. Owners may contact BMW customer service at 1-800-525-7417. Owners will also be contacted by phone.

### **Vehicles**



**MAKE MODEL YEAR**

BMW	I4	2022
BMW	IX	2022-2023