



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

August 22, 2022

Improper Rivets on Seat Belt Buckle Assembly

NHTSA Campaign Number: 22V617000

Manufacturer General Motors, LLC

Components SEAT BELTS

Potential Number of Units Affected 484,155

Summary

General Motors, LLC (M) is recalling certain 2021-2022 Cadillac Escalade, Escalade ESV, Chevrolet Suburban, Tahoe, GMC Yukon, and Yukon XL vehicles equipped with third-row seats. The rivet that retains the buckle to the mounting bracket in the left or right side third-row seat belt buckle assembly may have been improperly formed.

Remedy

Dealers will inspect the rivet head formation on both the left and right side third-row seat belt buckle assemblies and replace seat belt buckle assemblies, as necessary, free of charge. Owner notification letters are expected to be mailed September 26, 2022. Owners may contact Chevrolet customer service at 1-800-222-1020; Cadillac customer service at 1-800-458-8006; and GMC customer service at 1-800-462-8782. GM's number for this recall is N222372380.

Vehicles

MAKE	MODEL	YEAR
CADILLAC	ESCALADE	2021-2022

MAKE	MODEL	YEAR
CADILLAC	ESCALADE ESV	2021-2022
CHEVROLET	SUBURBAN	2021-2022
CHEVROLET	TAHOE	2021-2022
GMC	YUKON	2021-2022
GMC	YUKON XL	2021-2022

Rearview Camera Display May Not Operate

NHTSA Campaign Number: 22V621000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 46

Summary

Ford Motor Company (Ford) is recalling certain 2022 Transit vehicles equipped with a rearview camera. These vehicles may have a missing audio control module (ACM), resulting in no rearview camera image while in reverse gear.

Remedy

Dealers will install the audio control module and program the unit, free of charge. Owner notification letters are expected to be mailed September 26, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S54.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

FORD	TRANSIT	2022
------	---------	------

Windshield Wipers May Fail

NHTSA Campaign Number: 22V627000

Manufacturer Hyundai Motor America

Components VISIBILITY

Potential Number of Units Affected 122,919

Summary

Hyundai Motor America (Hyundai) is recalling certain 2020-2021 Palisade vehicles. The windshield wiper motor may become inoperative, causing the wipers to fail.

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed October 14, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 233.

Vehicle

MAKE MODEL YEAR

HYUNDAI PALISADE 2020-2021

Coolant Leak Inside EGR Module May Cause Fire

NHTSA Campaign Number: 22V614000

Manufacturer BMW of North America, LLC

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 298

Summary

BMW of North America, LLC. (BMW) is recalling certain 2018 540d xDrive vehicles equipped with an Exhaust Gas Recirculation (EGR) module with an integrated cooler. The EGR cooler may leak internally, causing coolant to mix with diesel engine soot, which could result in smoldering particles and a melting intake manifold.

Remedy

Dealers will replace the EGR module, and the intake manifold will be inspected and replaced, if necessary, free of charge. Owner notification letters are expected to be mailed on October 3, 2022. Owners may contact BMW customer service at 1-800-525-7417.

Vehicle

MAKE MODEL YEAR

BMW 540D 2018

Damaged Lamp Reflectors/FMVSS 108

NHTSA Campaign Number: 22V624000

Manufacturer Subaru of America, Inc.

Components EXTERIOR LIGHTING

Potential Number of Units Affected 188,397

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2017-2019 Impreza vehicles. The left and right side reflex reflector and left side low beam reflector may inadequately reflect light. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Dealers will replace the front headlamp assemblies, free of charge. Owner notification letters are expected to be mailed October 11, 2022. Owners may contact Subaru's customer service at 1-844-373-6614. Subaru's number for this recall is WRG-22.

Vehicle

MAKE MODEL YEAR

SUBARU IMPREZA 2017-2019

Damaged Driveshaft May Fracture

NHTSA Campaign Number: 22V623000

Manufacturer Ford Motor Company

Components POWER TRAIN, STRUCTURE

Potential Number of Units Affected 58,203

Summary

Ford Motor Company (Ford) is recalling certain 2021-2022 F-150 vehicles. Underbody heat and noise insulators may loosen and contact the aluminum driveshaft, which could damage the driveshaft and cause it to fracture.

Remedy

Dealers will inspect and repair the driveshaft, as necessary, and properly attach the underbody insulators, free of charge. Owner notification letters are expected to be mailed September 5, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S53.

Vehicle

MAKE MODEL YEAR

FORD F-150 2021-2022

Vehicle Rollaway from Faulty Shift Lever Assembly

NHTSA Campaign Number: 22V612000

Manufacturer Kia America, Inc.

Components POWER TRAIN

Potential Number of Units Affected 28,065

Summary

Kia America, Inc. (Kia) is recalling certain 2016 Sedona and Sorento vehicles. The vehicles may have been manufactured with faulty automatic transmission shift lever assembly components, preventing the shift lever from locking, which can allow the vehicle to rollaway.

Remedy

Dealers will inspect and replace the automatic transmission shift lever assembly components, as necessary, free of charge. Owner notification letters are expected to be mailed October 7, 2022. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC246.

Vehicles

MAKE MODEL YEAR

KIA SEDONA 2016

KIA SORENTO 2016

Electrical Short Circuit May Cause Engine Stall

NHTSA Campaign Number: 22V606000

Manufacturer Mack Trucks, Inc.

Components ENGINE AND ENGINE COOLING**Potential Number of Units Affected** 150**Summary**

Mack Trucks, Inc. (Mack) is recalling certain 2023 MD6/7 trucks. The engine control module (ECM) may experience an internal short-circuit, which can result in an unexpected engine shut down.

Remedy

Cummins will replace the ECM, free of charge. Owner notification letters are expected to be mailed on September 26, 2022. Owners may contact Mack's customer service at 1-800-866-1177. Mack's number for this recall is SC0438.

Vehicle**MAKE MODEL YEAR**

MACK MD 2023