



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

August 29, 2022

Improperly Welded Air Bag Cover Emblem May Detach

NHTSA Campaign Number: 22V632000

Manufacturer Hyundai Motor America

Components AIR BAGS

Potential Number of Units Affected 247

Summary

Hyundai Motor America (Hyundai) is recalling certain 2022 Elantra N and 2022-2023 Elantra vehicles. The emblem on the cover of the driver's front air bag may not have been welded properly, which can result in the emblem detaching upon deployment.

Remedy

Dealers will replace the air bag, free of charge. Owner notification letters are expected to be mailed October 17, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 234.

Vehicles

MAKE	MODEL	YEAR
HYUNDAI	ELANTRA	2022-2023
HYUNDAI	ELANTRA N	2022

Stability Control Commands may Fail to Processes

NHTSA Campaign Number: 22V630000

Manufacturer PACCAR Incorporated

Components POWER TRAIN

Potential Number of Units Affected 4

Summary

PACCAR Incorporated (PACCAR) is recalling certain 2022 Kenworth K270 and 2021 Peterbilt 220 vehicles. Software programming may prevent the electric power train control unit from processing stability control commands while in regenerative braking mode.

Remedy

Dealers will update the electric power train control unit with a software, free of charge. Owner notification letters are expected to be mailed October 16, 2022. Owners may contact Kenworth's customer service at 1-425-828-5888 and Peterbilt's customer service at 1-940-591-4220. PACCAR's numbers for this recall are 22KWH and 22PBH.

Vehicles

MAKE	MODEL	YEAR
KENWORTH	K270	2022
PETERBILT	220	2021

Insufficient Passenger Protection/FMVSS 222

NHTSA Campaign Number: 22V634000

Manufacturer Daimler Trucks North America, LLC

Components SEATS

Potential Number of Units Affected 7,601

Summary

Daimler Trucks North America LLC (DTNA) is recalling certain 2011-2021 Thomas Built Saf-T Liner HDX school buses. The forward seat barriers may not provide sufficient protection to passengers. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 222, "School Bus Passenger Seating and Crash Protection."

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed October 4, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL843. This recall replaces NHTSA recall 19V899.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

THOMAS BUILT BUSES SAF-T-LINER HDX	2011-2021	
------------------------------------	-----------	--

Tow Hitch Harness Fire While Parked or Driving

NHTSA Campaign Number: 22V626000

Manufacturer Kia America, Inc.

Components TRAILER HITCHES

Potential Number of Units Affected 36,417

Summary

Kia America, Inc. (Kia) is recalling certain 2020-2022 Telluride vehicles potentially equipped with a Genuine Kia 4-pin tow hitch harness installed as original equipment, or purchased as an accessory through a Kia dealership. Debris and moisture accumulation on the tow hitch harness module printed circuit board (PCB) may cause an electrical short, which can result in a fire.

Remedy

Owners are advised to park outside and away from structures until the recall repair is complete. The remedy is currently under development. Owner notification letters are expected to be mailed October 14, 2022. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC247.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

KIA	TELLURIDE	2020-2022
-----	-----------	-----------

Tow Hitch Harness Fire While Parked or Driving

NHTSA Campaign Number: 22V633000

Manufacturer Hyundai Motor America

Components TRAILER HITCHES

Potential Number of Units Affected 245,030

Summary

Hyundai Motor America (Hyundai) is recalling 2020-2022 Palisade vehicles potentially equipped with a tow hitch harness installed as original equipment, or purchased as an accessory through a Hyundai dealership. Debris and moisture accumulation on the tow hitch harness module printed circuit board (PCB) may cause an electrical short, which can result in a fire.

Remedy

Owners are advised to park outside and away from structures until the recall repair is complete. As an interim repair, dealers will inspect the tow hitch module and remove the fuse, as necessary, free of charge. The final remedy is currently under development. Owner notification letters are expected to be mailed October 17, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 235.

Vehicle

MAKE MODEL YEAR

HYUNDAI PALISADE 2020-2022

Vehicle Rollaway Due to Transmission Parking Wheel

NHTSA Campaign Number: 22V639000

Manufacturer Chrysler (FCA US, LLC)

Components POWER TRAIN

Potential Number of Units Affected 11

Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Gladiator vehicles. The transmission parking wheel may not properly engage with the parking mechanism.

Remedy

Dealers will replace the transmission, free of charge. Owner notification letters are expected to be mailed October 14, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA, LLC's number for this recall is Z84.

Vehicle

MAKE MODEL YEAR

JEEP GLADIATOR 2022