



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

[Air Bag Inflator May Explode or Deploy Improperly](#)

NHTSA Campaign Number: 22V543000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 1,216

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2016 Audi TT Roadster, TT Coupe, S3 Sedan, R8 Coupe, A3 Sedan, A3 Etron, A3 Cabriolet, 2016 Golf Sportwagen, Golf R, Golf GTI, Golf A7, and E Golf vehicles. During air bag deployment, the front passenger air bag may explode or deploy improperly.

Remedy

Dealers will replace the front-passenger air bag module, free of charge. Owner notification letters are expected to be mailed September 23, 2022. Owners may contact Volkswagen's customer service at 1-800-893-5298. Audi's customer service at 1-800-253-2834. Volkswagen's number for this recall is 69DY and 61C1.

Vehicles

MAKE	MODEL	YEAR
AUDI	A3	2016
AUDI	A3 ETRON	2016
AUDI	R8	2016
AUDI	S3	2016
AUDI	TT	2016

MAKE	MODEL	YEAR
VOLKSWAGEN	E-GOLF	2016
VOLKSWAGEN	GOLF	2016
VOLKSWAGEN	GOLF R	2016
VOLKSWAGEN	GOLF SPORTWAGEN	2016
VOLKSWAGEN	GTI	2016

Sunroof Malfunction/FMVSS 118

NHTSA Campaign Number: 22V542000

Manufacturer Volkswagen Group of America, Inc.

Components VISIBILITY

Potential Number of Units Affected 2,238

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2022 Golf R A8 and Golf GTI vehicles. The touch switch for the sunroof may be too sensitive, allowing it to be inadvertently pressed. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 118, "Power-Operated Window Systems."

Remedy

Dealers will replace the roof module switch, free of charge. Owner notification letters are expected to be mailed September 23, 2022. Owners may contact Volkswagen's customer service at 1-800-893-5298. Volkswagen's number for this recall is 60F6.

Vehicles

MAKE	MODEL	YEAR
VOLKSWAGEN	GOLF R	2022
VOLKSWAGEN	GTI	2022

Steering Gear Assembled Incorrectly

NHTSA Campaign Number: 22V547000

Manufacturer PACCAR Incorporated

Components STEERING

Potential Number of Units Affected 47,513

Summary

PACCAR Incorporated (PACCAR) is recalling certain 2022-2023 Kenworth T170, T270, T280, T370, T380, T440, T470, T480, T680, T800, T880, W900, W990, C500, and 2022-2023 Peterbilt 325, 330, 337, 348, 365, 367, 389, 520, 536, 537, 548, 567, and 579 vehicles. The steering gears may have been assembled incorrectly, which can cause the gears to fracture.

Remedy

Dealers will inspect the steering gear serial numbers, and replace the steering gears as necessary, free of charge. Owner notification letters are expected to be mailed September 26, 2022. Owners may contact Kenworth's customer service at 1-425-828-5888 and Peterbilt's customer service at 1-940-591-4220. PACCAR's numbers for this recall are 22PBE and 22KWE.

Vehicles

MAKE	MODEL	YEAR
KENWORTH	C500	2022-2023
KENWORTH	T170	2022-2023
KENWORTH	T270	2022-2023
KENWORTH	T280	2022-2023
KENWORTH	T370	2022-2023
KENWORTH	T380	2022-2023
KENWORTH	T440	2022-2023
KENWORTH	T470	2022-2023
KENWORTH	T480	2022-2023
KENWORTH	T680	2022-2023
KENWORTH	T800	2022-2023
KENWORTH	T880	2022-2023
KENWORTH	W900	2022-2023
KENWORTH	W990	2022-2023
PETERBILT	325	2022-2023
PETERBILT	330	2022-2023
PETERBILT	337	2022-2023
PETERBILT	348	2022-2023
PETERBILT	365	2022-2023
PETERBILT	367	2022-2023
PETERBILT	389	2022-2023
PETERBILT	520	2022-2023
PETERBILT	536	2022-2023
PETERBILT	537	2022-2023
PETERBILT	548	2022-2023
PETERBILT	567	2022-2023
PETERBILT	579	2022-2023

Electrical Short Circuit May Cause Engine Stall

NHTSA Campaign Number: 22V554000

Manufacturer Daimler Trucks North America, LLC

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 1,375

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2023 Freightliner 108SD, 114SD, Business Class M2, Cascadia, 2023 Freightliner FCCC MC, MT45, S2C 106CAB, XCM, S2RV 106CAB, XCR, XCS, and 2023 Western Star 4700, 49X, and 47X vehicles. The engine control module (ECM) may experience an internal short-circuit, which can result in an unexpected engine shut down.

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed September 26, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-949.

Vehicles

MAKE	MODEL	YEAR
FCCC	MC	2023
FCCC	MT45	2023
FCCC	S2C 106CAB	2023
FCCC	S2RV 106CAB	2023
FCCC	XCM	2023
FCCC	XCR	2023
FCCC	XCS	2023
FREIGHTLINER	108SD	2023
FREIGHTLINER	114SD	2023
FREIGHTLINER	BUSINESS CLASS M2	2023
FREIGHTLINER	CASCADIA	2023
WESTERN STAR	4700	2023
WESTERN STAR	47X	2023
WESTERN STAR	49X	2023

Electrical Short Circuit May Cause Engine Stall

NHTSA Campaign Number: 22V553000

Manufacturer Daimler Trucks North America, LLC

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 71

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2023 Thomas Built Saf-T-Liner HDX and Saf-T-Liner C2 school buses. The engine control module (ECM) may experience an internal short-circuit, which can result in an unexpected engine shut down.

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed September 26, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-949.

Vehicles

MAKE	MODEL	YEAR
THOMAS BUILT BUSES	SAF-T-LINER C2	2023
THOMAS BUILT BUSES	SAF-T-LINER HDX	2023

Steering Wheel May Loosen or Detach

NHTSA Campaign Number: 22V528000

Manufacturer Ford Motor Company

Components STEERING

Potential Number of Units Affected 692

Summary

Ford Motor Company (Ford) is recalling certain 2022 F-53 Motorhome Stripped Chassis, and F-59 Commercial Stripped Chassis vehicles. The steering wheel attachment bolt may loosen and separate from the steering column, resulting in a loose or detached steering wheel.

Remedy

Ford will work with the final stage vehicle manufacturers to replace and tighten the steering wheel attachment bolt, free of charge. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S50.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

FORD	F-53	2022
------	------	------

MAKE MODEL YEAR

FORD F-59 2022

Loss of Brake Function

NHTSA Campaign Number: 22V536000

Manufacturer Ferrari North America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 23,555

Summary

Ferrari North America, Inc. (Ferrari) is recalling certain 2005-2009 430, 2019-2020 488 Pista, 2016 F60 America, 2005-2011 612 Scaglietti, 2010-2011 612, 2018-2022 812, 2020-2022 F8 Spider, 2020-2022 F8 Tributo, 2021-2022 Roma, 2009-2017 California, 2015-2017 California T, 2013-2017 F12 Berlinetta, 2017 F12 TDF, 2012-2016 FF, 2017-2020 GTC4 Lusso, 2018-2020 GTC4 Lusso T, 2013-2015 LaFerrari, 2017 LaFerrari Aperta, and 2019-2022 Portofino vehicles. The brake fluid reservoir cap may not vent properly, creating a vacuum inside the brake fluid reservoir, and resulting in a brake fluid leak that may lead to a partial or total loss of brake function.

Remedy

Dealers will replace the brake fluid reservoir cap and update the software to provide a new warning message for low brake fluid, free of charge. Owner notification letters are expected to be mailed September 24, 2022. Owners may contact Ferrari customer service at 1-201-816-2668. Ferrari's number for this recall is RC 80. This recall is an expansion of NHTSA recall number 21V-833.

Vehicles

MAKE	MODEL	YEAR
FERRARI	430	2005-2009
FERRARI	488 PISTA	2019-2020
FERRARI	612	2010-2011
FERRARI	612 SCAGLIETTI	2005-2011
FERRARI	812	2018-2022
FERRARI	CALIFORNIA	2009-2017
FERRARI	CALIFORNIA T	2015-2017
FERRARI	F12 BERLINETTA	2013-2017
FERRARI	F12 TDF	2017
FERRARI	F60 AMERICA	2016
FERRARI	F8 SPIDER	2020-2022
FERRARI	F8 TRIBUTO	2020-2022
FERRARI	FF	2012-2016

MAKE	MODEL	YEAR
FERRARI	GTC4LUSSO	2018-2020
FERRARI	GTC4LUSSO T	2018-2019
FERRARI	LAFERRARI	2013-2015
FERRARI	LAFERRARI APERTA	2017
FERRARI	PORTOFINO	2019-2022
FERRARI	ROMA	2021-2022

Damaged Tail Light Side Marker Assembly/FMVSS 108

NHTSA Campaign Number: 22V544000

Manufacturer Chrysler (FCA US, LLC)

Components EXTERIOR LIGHTING

Potential Number of Units Affected 99,186

Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Grand Cherokee and 2021-2022 Jeep Grand Cherokee L vehicles. The tail light side marker assemblies may be damaged and not illuminate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamp, Reflective Devices, and Associated Equipment."

Remedy

Dealers will inspect and replace both body-mounted tail light assemblies, as necessary, free of charge. Owner notification letters are expected to be mailed September 16, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z50.

Vehicle

MAKE	MODEL	YEAR
JEEP	GRAND CHEROKEE	2021-2022