



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

October 17, 2022

Rearview Display Inoperative/FMVSS 111

NHTSA Campaign Number: 22V742000

Manufacturer Volkswagen Group of America, Inc.

Components BACK OVER PREVENTION

Potential Number of Units Affected 170,296

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021 Audi A8, RS7, RS6 Avant, RS5 Sportback, RS5 Coupe, Q8, Q7, Q5 Sportback, S4 Sedan, Q5, A7, A6, A6 Allroad, A5 Sportback, A5 Coupe, A5 Cabriolet, A4 Sedan, A4 Allroad, E-Tron Sportback Quattro, SQ7, S5 Cabriolet, E-Tron Quattro, SQ8, SQ5 Sportback, SQ5, S8, S7, S6 Sedan, S5 Sportback, S5 Coupe, 2022 E-Tron GT, and 2021-2022 RSQ8 vehicles. Due to a software issue, a blank or black screen may be displayed instead of the rearview camera image when the vehicle is placed in reverse gear. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will update the infotainment unit software, free of charge. Owner notification letters are expected to be mailed December 2, 2022. Owners may contact Audi's customer service at 1-800-253-2834. Volkswagen's number for this recall is 91DZ.

Vehicles

MAKE	MODEL	YEAR
AUDI	A4	2021
AUDI	A5	2021
AUDI	A5 CABRIOLET	2021
AUDI	A6	2021
AUDI	A7	2021
AUDI	A8	2021
AUDI	E-TRON	2021
AUDI	E-TRON GT	2022
AUDI	Q5	2021
AUDI	Q7	2021
AUDI	Q8	2021
AUDI	RS Q8	2021-2022
AUDI	RS5	2021
AUDI	RS6	2021
AUDI	RS7	2021
AUDI	S4	2021
AUDI	S5	2021
AUDI	S5 CABRIOLET	2021
AUDI	S6	2021
AUDI	S7	2021
AUDI	S8	2021
AUDI	SQ5	2021
AUDI	SQ7	2021
AUDI	SQ8	2021

Loss of Drive Power

NHTSA Campaign Number: 22V746000

Manufacturer Hyundai Motor America

Components POWER TRAIN

Potential Number of Units Affected 53,142

Summary

Hyundai Motor Company (Hyundai) is recalling certain 2021-2022 Santa Fe, Sonata, Veloster N, 2022 Santa Cruz, Elantra N, and Kona N vehicles. The vehicle's "fail-safe" limited-mobility drive mode may be impaired, when prompted by a transmission oil pump malfunction, which can result in a complete loss of drive power.

Remedy

Dealers will inspect and replace the transmission, as necessary. Dealers will also update the transmission control unit software. All repairs will be performed free of charge. Owner notification letters are expected to be mailed December 5, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 236.

Vehicles

MAKE	MODEL	YEAR
HYUNDAI	ELANTRA N	2022
HYUNDAI	KONA N	2022
HYUNDAI	SANTA CRUZ	2022
HYUNDAI	SANTA FE	2021-2022
HYUNDAI	SONATA	2021-2022
HYUNDAI	VELOSTER N	2021-2022

Loss of Drive Power

NHTSA Campaign Number: 22V760000

Manufacturer Kia America, Inc.

Components POWER TRAIN

Potential Number of Units Affected 69,038

Summary

Kia Motors, Inc. (Kia) is recalling certain 2021-2022 Sorento and 2021-2023 K5 vehicles. The vehicle's "fail-safe" limited-mobility drive mode may be impaired, when prompted by a transmission oil pump malfunction, which can result in a complete loss of drive power.

Remedy

Dealers will inspect and replace the transmission, as necessary. Dealers will also update the transmission control unit software. All repairs will be performed free of charge. Owner notification letters are expected to be mailed December 9, 2022. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC250.

Vehicles

MAKE	MODEL	YEAR
KIA	K5	2021-2023
KIA	SORENTO	2021-2022

Blank Rearview Camera Image/FMVSS 111

NHTSA Campaign Number: 22V743000

Manufacturer Bentley Motors, Inc.

Components BACK OVER PREVENTION

Potential Number of Units Affected 3,134

Summary

Bentley Motors, Inc. (Bentley) is recalling certain 2021-2022 Bentayga vehicles. Due to a software error, the rearview camera image may be blank when the car is placed in reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will update the infotainment unit software, free of charge. Owner notification letters are expected to be mailed December 2, 2022. Owners may contact Bentley customer service at 1-800-877-6923. Bentley's number for this recall is RE22/29 (RC54).

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

BENTLEY	BENTAYGA	2021-2022
---------	----------	-----------

Unintended Brake Light Illumination/FMVSS 108

NHTSA Campaign Number: 22V730000

Manufacturer Ford Motor Company

Components EXTERIOR LIGHTING, SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 11,098

Summary

Ford Motor Company (Ford) is recalling certain 2022 Maverick vehicles. Under certain circumstances, the Antilock Brake System (ABS) module may cause the brake lights to illuminate without the driver applying the brakes. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Dealers will update the software in the ABS module, free of charge. Owner notification letters are expected to be mailed November 14, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22C24.

Vehicle**MAKE MODEL YEAR**

FORD MAVERICK 2022