



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

November 14, 2022

### [Rearview Camera Malfunction/FMVSS 111](#)

**NHTSA Campaign Number:** 22V825000

**Manufacturer** Ford Motor Company

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 47,046

#### **Summary**

Ford Motor Company (Ford) is recalling certain 2021-2022 Bronco vehicles equipped with rearview camera systems and 8-inch screen displays. The rearview camera image may still be displayed after a backing event has ended. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

#### **Remedy**

The SYNC module software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed December 19, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22C27.

#### **Vehicle**

**MAKE MODEL YEAR**

FORD BRONCO 2021-2022

# Inoperative Rearview Camera Display/FMVSS 111

**NHTSA Campaign Number:** 22V823000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 2,585

## **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2022 Golf R A8, Audi S3, RS3 Sedan, Q4 E-Tron SUV, A3 Sedan, and 2022-2023 Volkswagen Golf GTI, and ID4 vehicles. The rearview camera image may be blank or unresponsive when the vehicle is placed in reverse gear or when the park function is manually activated. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

## **Remedy**

Dealers will replace the rearview camera, free of charge. Owner notification letters are expected to be mailed January 1, 2023. Owners may contact Volkswagen's customer service at 1-800-893-5298 and Audi's customer service at 1-800-253-2834. Volkswagen's numbers for this recall are (VW) 91EK and (Audi) 91EL.

## **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
AUDI	A3	2022
AUDI	Q4 E-TRON	2022
AUDI	RS3	2022
AUDI	S3	2022
VOLKSWAGEN	GOLF R	2022
VOLKSWAGEN	GTI	2022-2023
VOLKSWAGEN	ID.4	2022-2023

# Running Lights May Not Deactivate/FMVSS 108

**NHTSA Campaign Number:** 22V827000

**Manufacturer** General Motors, LLC

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 338,735

## **Summary**

General Motors, LLC (GM) is recalling certain 2021 Yukon, Yukon XL, Chevrolet Tahoe, Chevrolet Suburban, Cadillac Escalade, and Cadillac Escalade ESV vehicles. The daytime running lights (DRLs) may not deactivate when the headlights are on. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

## Remedy

Dealers will update the Body Control Module software, free of charge. Owner notification letters are expected to be mailed December 19, 2022. Owners may contact GM customer service at 1-888-988-7267, Chevrolet customer service at 1-800-222-1020, or Cadillac customer service at 1-800-458-8006. GM's number for this recall is N222382220.

## Vehicles

MAKE	MODEL	YEAR
CADILLAC	ESCALADE	2021
CADILLAC	ESCALADE ESV	2021
CHEVROLET	SUBURBAN	2021
CHEVROLET	TAHOE	2021
GMC	YUKON	2021
GMC	YUKON XL	2021

## Loss of Power Steering Assist

**NHTSA Campaign Number:** 22V818000

**Manufacturer** Tesla, Inc.

**Components** STEERING

**Potential Number of Units Affected** 40,168

## Summary

Tesla, Inc. (Tesla) is recalling certain 2017-2021 Model S and Model X vehicles. The electronic power assist steering (EPAS) system may experience a loss of power steering assist when driving on rough roads or after hitting a pothole.

## Remedy

Tesla has released an over-the-air (OTA) software update to recalibrate the EPAS system, free of charge. Owner notification letters are expected to be mailed December 31, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-22-00-014.

## Vehicles

MAKE	MODEL	YEAR
------	-------	------

TESLA	MODEL S	2017-2021
-------	---------	-----------

TESLA	MODEL X	2017-2021
-------	---------	-----------

# Windshield May Not Be Attached Properly

**NHTSA Campaign Number:** 22V820000

**Manufacturer** BMW of North America, LLC

**Components** VISIBILITY

**Potential Number of Units Affected** 47

## **Summary**

BMW of North America, LLC (BMW) is recalling certain 2023 X5 sDrive40i, xDrive40i, xDrive45e, and X7 xDrive40i vehicles. The windshield may not have been properly bonded to the vehicle which could allow water to enter the vehicle and contact electrical components, possibly resulting in a short-circuit.

## **Remedy**

Dealers will inspect the windshield seal and as necessary, remove and reinstall the windshield with a new seal, free of charge. Owner notification letters are expected to be mailed December 23, 2022. Owners may contact BMW customer service at 1-800-525-7417.

## **Vehicles**

### **MAKE MODEL YEAR**

BMW	X5	2023
BMW	X7	2023