



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

November 7, 2022

### [ABS Unit May Cause Engine Compartment Fire](#)

**NHTSA Campaign Number:** 22V810000

**Manufacturer** Hyundai Motor America

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 44,396

#### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2018 Santa Fe Sport vehicles. The Anti-Lock Brake System (ABS) module could malfunction and cause an electrical short, which could result in an engine compartment fire while parked or driving.

#### **Remedy**

Owners are advised to park outside and away from structures until the recall repair is complete. Dealers will replace the ABS multi-fuse, free of charge. Owner notification letters are expected to be mailed December 26, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 237. This recall is an expansion of recall 22V-056.

#### **Vehicle**

MAKE	MODEL	YEAR
------	-------	------

HYUNDAI	SANTA FE SPORT	2018
---------	----------------	------

## Seat Belt Pretensioners May Explode

**NHTSA Campaign Number:** 22V816000

**Manufacturer** Hyundai Motor America

**Components** SEAT BELTS

**Potential Number of Units Affected** 14,928

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2023 Genesis G80 Electric, 2021-2022 Santa Fe Hybrid, and 2022-2023 Santa Fe Plug-In Hybrid vehicles. In the event of a crash, the front driver-side and/or passenger-side seat belt pretensioners may explode upon deployment.

### **Remedy**

Dealers will secure the seat belt pretensioners with a cap, free of charge. Owner notification letters are expected to be mailed December 30, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 238/011G. This recall is an expansion of recall numbers 22V-354 and 22V-458.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
GENESIS	G80 ELECTRIC	2023
HYUNDAI	SANTA FE HYBRID	2021-2022
HYUNDAI	SANTA FE PLUG-IN HYBRID	2022-2023

## Tire Pressure Loss Not Detected/FMVSS 138

**NHTSA Campaign Number:** 22V815000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** TIRES

**Potential Number of Units Affected** 224,704

### **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019 Volkswagen Tiguan LWB, Golf Sportswagen A7, Golf Alltrack, Golf R GP, Audi Q3, Audi A3 Cabriolet, 2019-2020 Jetta NF, Jetta GLI, Golf GTI, Atlas, Golf A7, Audi A3, 2020-2021 Atlas Cross Sport, and 2021 Atlas FL vehicles. The tire pressure monitoring system may not detect an air pressure loss in adequate time when deflating occurs among all four tires

simultaneously. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 138, "Tire Pressure Monitoring Systems."

## Remedy

Dealers will update the TPMS software, free of charge. Owner notification letters are expected to be mailed December 30, 2022. Owners may contact Volkswagen's customer service at 1-800-893-5298 or Audi's customer service at 1-800-253-2834. Volkswagen's numbers for this recall are (Audi) 45J7, and (VW) 45J6 and 45J8.

## Vehicles

MAKE	MODEL	YEAR
AUDI	A3	2019-2020
AUDI	Q3	2019
VOLKSWAGEN	ATLAS	2019-2021
VOLKSWAGEN	ATLAS CROSS SPORT	2020-2021
VOLKSWAGEN	GOLF	2019-2020
VOLKSWAGEN	GOLF ALLTRACK	2019
VOLKSWAGEN	GOLF R	2019
VOLKSWAGEN	GOLF SPORTWAGEN	2019
VOLKSWAGEN	GTI	2019-2020
VOLKSWAGEN	JETTA	2019-2020
VOLKSWAGEN	TIGUAN	2019

## Inoperative TPMS Sensor/FMVSS 138

**NHTSA Campaign Number:** 22V808000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** TIRES

**Potential Number of Units Affected** 44,212

## Summary

Chrysler (FCA US LLC) is recalling certain 2022 Dodge Challenger, Dodge Charger, and Chrysler 300 vehicles. The Tire Pressure Monitoring System (TPMS) sensor battery may fail prematurely and cause the sensor to become inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 138, "Tire Pressure Monitoring Systems."

## Remedy

Dealers will inspect and replace the TPMS sensors, as necessary, free of charge. Owner notification letters are expected to be mailed December 16, 2022. Owners may contact FCA US, LLC at 1-800-853-1403. FCA US, LLC's number for this recall is ZB5. This recall is an expansion of previous recall number 22V-504.

## Vehicles

MAKE	MODEL	YEAR
CHRYSLER	300	2022
DODGE	CHALLENGER	2022
DODGE	CHARGER	2022

## Inoperative Rearview Camera Display/FMVSS 111

**NHTSA Campaign Number:** 22V806000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** EQUIPMENT, BACK OVER PREVENTION

**Potential Number of Units Affected** 6,076

### Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2021-2022 AUDI A8, A6 Allroad, E-TRON Quattro, 2022 S3, RSQ8, RS7, RS6 Avant, Q8, Q7, Q3, E-TRON Sportback Quattro, S5 Cabriolet, E-TRON GT, S5 Sportback, A7, A6, A5 Sportback, A5 Cabriolet, A4, A4 Allroad, A3, S8, SQ7, SQ8, S6, and S4 vehicles. The infotainment main unit may become damaged internally when the vehicle is shut off, resulting in an inoperative rearview camera display the next time the vehicle is started. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

### Remedy

Dealers will replace the infotainment main unit, free of charge. Owner notification letters are expected to be mailed December 25, 2022. Owners may contact Audi's customer service at 1-800-253-2834. Audi's number for this recall is 91Ei.

## Vehicles

MAKE	MODEL	YEAR
AUDI	A3	2022
AUDI	A4	2022
AUDI	A4 ALLROAD	2022
AUDI	A5	2022
AUDI	A5 CABRIOLET	2022
AUDI	A6	2022
AUDI	A6 ALLROAD	2021-2022
AUDI	A7	2022
AUDI	A8	2021-2022
AUDI	E-TRON	2021-2022

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
AUDI	E-TRON GT	2022
AUDI	Q3	2022
AUDI	Q7	2022
AUDI	Q8	2022
AUDI	RS Q8	2022
AUDI	RS6	2022
AUDI	RS7	2022
AUDI	S3	2022
AUDI	S4	2022
AUDI	S5	2022
AUDI	S5 CABRIOLET	2022
AUDI	S6	2022
AUDI	S8	2022
AUDI	SQ7	2022
AUDI	SQ8	2022

## Corroded Modulator Valve May Cause Brake Pull

**NHTSA Campaign Number:** 22V817000

**Manufacturer** Daimler Trucks North America, LLC

**Components** SERVICE BRAKES, AIR, FORWARD COLLISION AVOIDANCE

**Potential Number of Units Affected** 218,147

### Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2017-2023 Freightliner Cascadia, 2020-2022 Freightliner Business Class M2, 2021 Freightliner 108SD, and 2022 Freightliner 114SD, and 2020-2023 Western Star 49X, 2021-2023 Western Star 47X, and 2021-2022 Western Star 57X vehicles. The brake modulator valves on the front axle may corrode and cause the vehicle to pull to the affected side during an Adaptive Cruise Control (ACC) braking event.

### Remedy

Dealers will replace the front brake modulator valves, free of charge. Owner notification letters are expected to be mailed December 30, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-958. This recall expands and replaces previous recall 20V-390. All vehicles previously repaired under recall 20V-390 will need to have the new remedy performed.

### Vehicles

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
FREIGHTLINER	108SD	2021

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
FREIGHTLINER	114SD	2022
FREIGHTLINER	BUSINESS CLASS M2	2020-2022
FREIGHTLINER	CASCADIA	2017-2023
WESTERN STAR	47X	2021-2023
WESTERN STAR	49X	2020-2023
WESTERN STAR	57X	2021-2022

## Seat Belt Anchor May Detach from Seat

**NHTSA Campaign Number:** 22V803000

**Manufacturer** Porsche Cars North America, Inc.

**Components** SEAT BELTS, SEATS

**Potential Number of Units Affected** 15

### Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2022 911 GT3 vehicles. The screw that attaches the lower seat belt anchor to the seat frame may not have been tightened properly.

### Remedy

Dealers will replace and tighten the screws. If the screw threads are damaged, the seat frame will also be replaced. Repairs will be performed free of charge. Owner notification letters are expected to be mailed December 23, 2022. Owners may contact Porsche's customer service at 1-800-767-7243. Porsche's number for this recall is ANB6.

### Vehicle

**MAKE MODEL YEAR**

PORSCHE 911 GT3 2022