



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

February 6, 2023

### Second Row Side Air Bags May Not Deploy

Air bags that do not deploy as intended can increase the risk of injury in a crash.

**NHTSA Campaign Number:** 23V035000

**Manufacturer** Kia America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 31,943

#### Summary

Kia America, Inc. (Kia) is recalling certain 2023 Telluride vehicles. Due to a manufacturing error, the wire harness for the second row seat side air bags may become damaged, causing them not to deploy in the event of a crash.

#### Remedy

Dealers will inspect and replace, or secure the air bag wire harnesses, as necessary, free of charge. Owner notification letters are expected to be mailed February 28, 2023. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC262.

#### Vehicle

MAKE	MODEL	YEAR
KIA	TELLURIDE	2023

## Insufficient Pedestrian Warning Sound/FMVSS 141

A vehicle that fails to make sufficient sound may result in pedestrians being unaware of an approaching vehicle, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V030000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** ELECTRICAL SYSTEM, BACK OVER PREVENTION

**Potential Number of Units Affected** 1,072

### Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2021-2022 I-Pace vehicles. The vehicles fail to make sufficient pedestrian warning sounds when stationary and in reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 141, "Minimum Sound Requirements for Hybrid and Electric Vehicles."

### Remedy

Dealers will update the audio amplifier software, free of charge. Owner notification letters are expected to be mailed March 24, 2023. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H421.

### Vehicle

---

MAKE	MODEL	YEAR
JAGUAR	I-PACE	2021-2022

---

## Insufficient Pedestrian Warning Sound/FMVSS 141

A vehicle that fails to make sufficient sound may result in pedestrians being unaware of an approaching vehicle, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V031000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** ELECTRICAL SYSTEM, BACK OVER PREVENTION

**Potential Number of Units Affected** 868

### Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2020-2021 Range Rover PHEV and 2020-2022 Range Rover Sport PHEV vehicles. The vehicles fail to make sufficient pedestrian warning sounds when stationary and in reverse. As such, these vehicles fail to comply with the

requirements of Federal Motor Vehicle Safety Standard number 141, "Minimum Sound Requirements for Hybrid and Electric Vehicles."

## Remedy

Dealers will update the audio amplifier software, free of charge. Owner notification letters are expected to be mailed March 24, 2023. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N742.

## Vehicles

---

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER PHEV	2020-2021
LAND ROVER	RANGE ROVER SPORT PHEV	2020-2022

---

## High Voltage Battery Control Module May Restart

A reset or deactivation may cause a loss of drive power, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V040000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 20,904

## Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021 ID.4 vehicles. Software programming may cause the high voltage (HV) battery management control module to reset or the pulse inverter to deactivate.

## Remedy

Dealers will update the HV battery management control unit and the pulse inverter control unit software, free of charge. Owner notification letters are expected to be mailed March 31, 2023. Owners may contact Volkswagen's customer service at 1-800-893-5298. Volkswagen's number for this recall is 97ZZ.

## Vehicle

---

MAKE	MODEL	YEAR
VOLKSWAGEN	ID.4	2021

---

## Roof Moldings May Detach

A detached roof molding could become a road hazard, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V038000

**Manufacturer** Hyundai Motor America

**Components** STRUCTURE

**Potential Number of Units Affected** 16,104

### Summary

Hyundai Motor America (Hyundai) is recalling certain 2022 Tucson and 2022-2023 Santa Cruz vehicles. The roof moldings may detach.

### Remedy

Dealers will inspect and replace, or secure the roof moldings, as necessary, free of charge. Owner notification letters are expected to be mailed April 1, 2023. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 241.

### Vehicles

MAKE	MODEL	YEAR
HYUNDAI	SANTA CRUZ	2022-2023
HYUNDAI	TUCSON	2022