

NHTSA Recalls of Interest August 28, 2023

Software Error May Cause Unintended Acceleration

Unintended vehicle acceleration can increase the risk of a crash.

NHTSA Campaign Number: 23V589000

Manufacturer Hyundai Motor America

Components ELECTRICAL SYSTEM, VEHICLE SPEED CONTROL

Potential Number of Units Affected 37,997

Summary

Hyundai Motor America (Hyundai) is recalling certain 2021-2023 Elantra HEV vehicles. A software error in the motor control unit may cause unintended vehicle acceleration after the brake pedal is released.

Remedy

Dealers will update the motor control unit software, free of charge. Owner notification letters are expected to be mailed October 17, 2023. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 248.

Vehicle

MAKE	MODEL	YEAR
HYUNDAI	ELANTRA HEV	2021-2023

Loss of Drive Power

A loss of drive power can increase the risk of a crash.

NHTSA Campaign Number: 23V588000

Manufacturer Honda (American Honda Motor Co.)

Components POWER TRAIN

Potential Number of Units Affected 19

Summary

Honda (American Honda Motor Co.) is recalling certain 2023 CR-V Hybrid and Accord Hybrid vehicles. The electronic transmission may have been improperly manufactured, which can result in a loss of drive power.

Remedy

Dealers will replace the electronic continuously variable transmission (e-CVT), free of charge. Owner notification letters are expected to be mailed October 11, 2023. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are NFG and HFF.

Vehicles

MAKE	MODEL	YEAR
HONDA	ACCORD HYBRID	2023
HONDA	CR-V HYBRID	2023

Seat Belt Audio Chime Malfunction/FMVSS 208

An audible chime that does not properly alert the driver to fasten their seat belt increases the risk of injury in a crash.

NHTSA Campaign Number: 23V584000

Manufacturer BMW of North America, LLC

Components SEAT BELTS, ELECTRICAL SYSTEM

Potential Number of Units Affected 144

Summary

BMW of North America, LLC (BMW) is recalling certain 2019-2022 330i, 330i xDrive, M340i, 2022 430i Coupe, 2021-2022 430i, M440i Convertible, and 2020-2022 228i xDrive Gran Coupe vehicles. The

receiver audio module control unit software may fail to properly generate audible seat belt warnings to the driver to fasten their seat belt. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers will update the receiver audio module software, free of charge. Owner notification letters are expected to be mailed October 6, 2023. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	228I	2020-2022
BMW	330I	2019-2022
BMW	430I	2021-2022
BMW	M340I	2019-2022
BMW	M440I	2021-2022