



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

September 11, 2023

### Insufficient Sealant on High-Voltage Battery

Liquid accumulation in the high voltage battery can cause electrical arcing, increasing the risk of a fire.

**NHTSA Campaign Number:** 23V615000

**Manufacturer** Porsche Cars North America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 4,777

#### Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2023 Taycan, Taycan 4S, Taycan Turbo S, Taycan Turbo, Taycan GTS, Taycan 4 Cross Turismo, Taycan 4S Cross Turismo, Taycan Turbo S Cross Turismo, Taycan Turbo Cross Turismo, and Taycan GTS Sport Turismo vehicles. The high-voltage battery may have an insufficient amount of sealant, which can allow liquid to accumulate in the battery.

#### Remedy

Dealers will test the battery for leakage and replace the battery as necessary, free of charge. Owner notification letters are expected to be mailed October 31, 2023. Owners may contact Porsche's customer service at 1-800-767-7243. Porsche's number for this recall is APB2.

#### Vehicles

---

MAKE	MODEL	YEAR
PORSCHE	TAYCAN	2023

---

MAKE	MODEL	YEAR
PORSCHE	TAYCAN 4 CROSS TURISMO	2023
PORSCHE	TAYCAN 4S	2023
PORSCHE	TAYCAN 4S CROSS TURISMO	2023
PORSCHE	TAYCAN CROSS TURISMO	2023
PORSCHE	TAYCAN GTS	2023
PORSCHE	TAYCAN GTS SPORT TURISMO	2023
PORSCHE	TAYCAN TURBO	2023
PORSCHE	TAYCAN TURBO S	2023
PORSCHE	TAYCAN TURBO S CROSS TURI	2023

## Insufficient Sealant on High-Voltage Battery

Liquid accumulation in the high voltage battery can cause electrical arcing, increasing the risk of a fire.

**NHTSA Campaign Number:** 23V613000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 1,899

### Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2023 Audi RS E-Tron GT and E-Tron GT vehicles. The high-voltage battery may have an insufficient amount of sealant, which can allow liquid to accumulate in the battery.

## Remedy

Dealers will test the battery for leakage and replace the battery as necessary, free of charge. Owner notification letters are expected to be mailed October 31, 2023. Owners may contact Audi's customer service at 1-800-253-2834. Volkswagen's number for this recall is 93T7.

## Vehicles

MAKE	MODEL	YEAR
AUDI	E TRON GT	2023
AUDI	RS E-TRON GT	2023

## Rearview Camera Image May Not Display/FMVSS 111

A rearview camera that does not properly display an image can reduce the driver's rear view, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V610000

**Manufacturer** Kia America, Inc.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 144,979

### Summary

Kia America, Inc. (Kia) is recalling certain 2022-2023 Sorento, Sorento Hybrid, and Sorento Plug-in Hybrid (PHEV) vehicles. The mounting clips for the rearview camera may break, which can cause the rearview camera image not to appear properly on the display. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

### Remedy

Dealers will inspect and replace the rearview camera housing, as necessary, free of charge. Owner notification letters are expected to be mailed October 27, 2023. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC280.

## Vehicles

MAKE	MODEL	YEAR
KIA	SORENTO	2022-2023

---

MAKE	MODEL	YEAR
KIA	SORENTO HYBRID	2022-2023

---

KIA	SORENTO PHEV	2022-2023
-----	--------------	-----------

---

## Ignition Switch May Fail

Ignition switch failure can cause the electrical system to shut down and the engine to stall while driving, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V604000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 47,651

### Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019-2020 Jetta vehicles equipped with a conventional ignition switch. The ignition switch may fail, especially in high temperature environments.

### Remedy

Dealers will replace the ignition switch, free of charge. Owner notification letters are expected to be mailed October 27, 2023. Owners may contact Volkswagen's customer service at 1-800-893-5298. Volkswagen's number for this recall is 28H7.

### Vehicle

---

MAKE	MODEL	YEAR
VOLKSWAGEN	JETTA	2019-2020

---

## Loose Steering Gear Fasteners

Loose steering gear fasteners may result in a loss of vehicle control, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V605000

**Manufacturer** Mack Trucks, Inc.

**Components** STEERING

**Potential Number of Units Affected** 395

### Summary

Mack Trucks, Inc. (Mack) is recalling certain 2024 MD6 and MD7 vehicles. The steering gear fasteners may not be properly tightened.

### Remedy

Dealers will tighten the steering gear fasteners, free of charge. Owner notification letters are expected to be mailed October 23, 2023. Owners may contact Mack's customer service at 1-800-866-1177. Mack's number for this recall is SC0449.

### Vehicle

---

MAKE	MODEL	YEAR
MACK	MD	2024

---

### Insufficient Sealant on High-Voltage Battery

Liquid accumulation in the high voltage battery can cause electrical arcing, increasing the risk of a fire.

**NHTSA Campaign Number:** 23V613000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 1,899

### Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2023 Audi RS E-Tron GT and E-Tron GT vehicles. The high-voltage battery may have an insufficient amount of sealant, which can allow liquid to accumulate in the battery.

### Remedy

Dealers will test the battery for leakage and replace the battery as necessary, free of charge. Owner notification letters are expected to be mailed October 31, 2023. Owners may contact Audi's customer service at 1-800-253-2834. Volkswagen's number for this recall is 93T7.

### Vehicles

---

MAKE	MODEL	YEAR
AUDI	E TRON GT	2023
AUDI	RS E-TRON GT	2023

---

# Inoperative Rear Turn Signals

Inoperative rear turn signals may not notify other drivers of a turning vehicle, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V609000

**Manufacturer** Subaru of America, Inc.

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 8,915

## Summary

Subaru of America, Inc. (Subaru) is recalling certain 2022 BRZ and Toyota GR86 vehicles. The rear turn signals may intermittently become inoperative.

## Remedy

Dealers will replace both rear combination lamp assemblies, free of charge. Interim letters notifying owners of the safety risk are expected to be mailed October 29, 2023. Second letters will be sent once the remedy is available. Subaru owners may contact Subaru's customer service at 1-844-373-6614. Toyota owners may contact Toyota customer service at 1-800-331-4331. Subaru's number for this recall is WRM-23.

## Vehicles

---

MAKE	MODEL	YEAR
SUBARU	BRZ	2022
TOYOTA	GR86	2022

---