



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

October 30, 2023

### Incorrectly Assembled Steering Rack

A damaged tire can fail and increase the risk of a crash or injury.

**NHTSA Campaign Number:** 23V704000

**Manufacturer** Honda (American Honda Motor Co.)

**Components** STEERING

**Potential Number of Units Affected** 176,410

#### Summary

Honda (American Honda Motor Co.) is recalling certain 2022-2024 Civic 4-door and Civic 5-door vehicles that received a replacement power steering rack as part of a service repair. The steering rack may have been incorrectly assembled, which can allow the tire to chafe against the lower suspension or tie rod end, possibly resulting in tire damage.

#### Remedy

Dealers will inspect and replace the electric power steering rack, as necessary, free of charge. Owner notification letters are expected to be mailed December 4, 2023. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is YFW.

#### Vehicle

---

MAKE	MODEL	YEAR
HONDA	CIVIC	2022-2024

---

# Inoperative Hands-On Detection System

An inoperative hands-on detection system may fail to detect when the driver's hands are not on the steering wheel and therefore not engage the emergency stopping assistant system, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V700000

**Manufacturer** BMW of North America, LLC

**Components** STEERING, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 9,211

## Summary

BMW of North America, LLC (BMW) is recalling certain 2023-2024 740i, 740i xDrive, 760i xDrive, i7 eDrive50, i7 xDrive60, i7 M70, 2024 750e xDrive, 530i, 530i xDrive, i5 eDrive40, and i5 M60 vehicles. The ground connection to the steering wheel may not have been attached correctly, resulting in an inoperative hands-on detection system.

## Remedy

Dealers will inspect and reattach the ground connection as necessary, free of charge. Owner notification letters are expected to be mailed December 8, 2023. Owners may contact BMW customer service at 1-800-525-7417.

## Vehicles

MAKE	MODEL	YEAR
BMW	530I	2024
BMW	740I	2023-2024
BMW	750E	2024
BMW	760I	2023-2024
BMW	I5	2024
BMW	I5 M60	2024

MAKE	MODEL	YEAR
BMW	I7	2023-2024
BMW	I7 M70	2023-2024

## Rear Seat Heater May Overheat Rear Seats

Overheated rear seats can increase the risk of a burn injury.

**NHTSA Campaign Number:** 23V708000

**Manufacturer** Lucid USA, Inc.

**Components** SEATS

**Potential Number of Units Affected** 1,267

### Summary

Lucid USA, Inc. (Lucid) is recalling certain 2022-2023 Lucid Air vehicles. Under certain conditions, temperature monitoring for the rear seat heaters could become inoperative and result in the rear seats overheating.

### Remedy

Lucid has released an over-the-air (OTA) software update, free of charge. Owner notification letters are expected to be mailed December 11, 2023. Owners may contact Lucid customer service at 1-888-99-LUCID or 1-888-995-8243. Lucid's number for this recall is SR-23-05-0.

### Vehicle

MAKE	MODEL	YEAR
LUCID	AIR	2022-2023

## Loose Steering Fastener May Fail

The power steering assist cylinder may separate from the steering arm, causing a loss of vehicle control and increasing the risk of a crash.

**NHTSA Campaign Number:** 23V713000

**Manufacturer** Mack Trucks, Inc.

**Components** STEERING

**Potential Number of Units Affected** 47

### Summary

Mack Trucks, Inc. (Mack) is recalling certain 2024 LR vehicles. The fasteners that connect the power steering assist cylinder to steering arm may be loose or missing.

### Remedy

Dealers will inspect and tighten the steering gear fasteners and install a new cotter pin, free of charge. Owner notification letters are expected to be mailed December 15, 2023. Owners may contact Mack customer service at 1-800-866-1177. Mack's number for this recall is SC0451.

### Vehicle

---

MAKE	MODEL	YEAR
MACK	LR	2024

---