



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

December 4, 2023

Driver's Air Bag Inflator May Explode

An inflator explosion may result in sharp metal fragments striking the driver or other occupants, resulting in serious injury or death.

NHTSA Campaign Number: 23V797000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 486

Summary

BMW of North America, LLC (BMW) is recalling certain 2014 X3 xDrive28i, X3 xDrive35i, X4 xDrive35i, X5 sDrive35i, and X5 xDrive35i vehicles. The driver's air bag inflator may explode during deployment, due to a manufacturing defect.

Remedy

Dealers will replace the driver's front air bag, free of charge. Owner notification letters are expected to be mailed January 16, 2024. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	X3	2014

MAKE	MODEL	YEAR
BMW	X4	2014
BMW	X5	2014

Front Passenger Air Bag May Deploy Improperly

An air bag that does not deploy properly in a crash increases the risk of injury.

NHTSA Campaign Number: 23V780000

Manufacturer Volvo Car USA, LLC

Components AIR BAGS

Potential Number of Units Affected 346

Summary

Volvo Car USA, LLC. (Volvo Car) is recalling certain 2019-2024 S60 vehicles. The passenger air bag may not be secured properly, which can cause the air bag to deploy improperly.

Remedy

Dealers will inspect and tighten the bolts securing the passenger air bag, as necessary, free of charge. Owner notification letters are expected to be mailed January 15, 2024. Owners may contact Volvo Car customer service at 1-800-458-1552. Volvo Car's number for this recall is R10254.

Vehicle

MAKE	MODEL	YEAR
VOLVO	S60	2019-2024

Missing Internal Bushing in Brake Calipers

A loss of brake fluid may reduce braking performance, increasing the risk of crash.

NHTSA Campaign Number: 23V791000

Manufacturer Nissan North America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 2

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2021 Rogue vehicles. The left and/or right rear brake caliper assemblies may be missing an internal bushing, allowing the O-ring seal to move and brake fluid to leak.

Remedy

Dealers will replace the left and right rear brake calipers, free of charge. Owner notification letters are expected to be mailed January 10, 2024. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC933. The two vehicles that were previously inspected under recall 21V-286 and did not receive a brake caliper replacement will need to have the new remedy completed.

Vehicle

MAKE	MODEL	YEAR
NISSAN	ROGUE	2021

Loose Seat Belt Buckle Attachment Bolt

An improperly tightened seat belt buckle may not restrain an occupant as intended, increasing the risk of injury during a crash.

NHTSA Campaign Number: 23V786000

Manufacturer General Motors, LLC

Components SEAT BELTS

Potential Number of Units Affected 115

Summary

General Motors, LLC (GM) is recalling certain 2023-2024 GMC Hummer EV pick up, 2024 GMC Hummer EV SUV, and 2024 Chevrolet Silverado EV vehicles. The left or right front seat belt buckle attachment bolts may not be tightened properly.

Remedy

Dealers will tighten the left and right front seat belt buckle attachment bolts, free of charge. Owner notification letters are expected to be mailed January 8, 2024. Owners may contact GMC customer service at 1-833-EVCHEVY (1-833-382-4389) (TTY 711 / 1-800-833-2438) /1-833-HUMMER-EV (1-833-486-6373) (TTY 711 / 1-800-833-2438). GM's number for this recall is N232419280.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	SILVERADO EV	2024

MAKE	MODEL	YEAR
GMC	HUMMER EV	2023-2024

Seat Belt Bracket Improperly Welded

An improperly welded seat belt bracket may not restrain an occupant as intended, increasing their risk of injury during a crash.

NHTSA Campaign Number: 23V785000

Manufacturer General Motors, LLC

Components SEAT BELTS

Potential Number of Units Affected 43

Summary

General Motors, LLC (GM) is recalling certain 2023-2024 LYRIQ vehicles. The bracket that anchors the left-rear and center-rear seat belts may have been improperly welded to the seat frame.

Remedy

Owners are advised not to use the left-rear and center-rear seating positions until the recall repair is completed. Dealers will replace the rear seat cushion frame, free of charge. Owner notification letters are expected to be mailed January 8, 2024. Owners may contact Cadillac customer service at 1-800-458-8006. GM's number for this recall is N232425220.

Vehicle

MAKE	MODEL	YEAR
CADILLAC	LYRIQ	2023-2024

Steering Gear Improperly Tightened

A loose steering gear can cause a loss of vehicle control, increasing the risk of a crash.

NHTSA Campaign Number: 23V770000

Manufacturer BMW of North America, LLC

Components STEERING

Potential Number of Units Affected 201

Summary

BMW of North America, LLC (BMW) is recalling certain 2024 2 Series Coupe (230i), 330i, X3 sDrive30i, X3 xDrive30i, X3 M40i, and X4 xDrive30i, X4 M40i vehicles. The steering gear may not have been tightened properly, which can allow it to loosen.

Remedy

Dealers will replace the steering gear, free of charge. Owner notification letters are expected to be mailed January 8, 2024. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	230I	2024
BMW	330I	2024
BMW	X3	2024
BMW	X4	2024

High Voltage Battery May Fail and Cause Fire

A vehicle fire while parked or driving can increase the risk of injury.

NHTSA Campaign Number: 23V787000

Manufacturer Chrysler (FCA US, LLC)

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 32,125

Summary

Chrysler (FCA US, LLC) is recalling certain 2021-2023 Jeep Wrangler Plug-In Hybrid Electric (PHEV) vehicles. The high voltage battery may fail internally and lead to a vehicle fire while parked or driving.

Remedy

Owners are advised not to recharge their vehicles, and to park outside and away from structures, until they are repaired. Dealers will update the high voltage battery pack software and replace the battery pack assembly if necessary, free of charge. Owner notification letters are expected to be mailed January 11, 2024. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 89A.

Vehicle

MAKE	MODEL	YEAR
JEEP	WRANGLER	2021-2023

Doors May Open While Driving

Vehicle doors opening unexpectedly while driving can increase the risk of a crash or injury.

NHTSA Campaign Number: 23V775000

Manufacturer Ford Motor Company

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 45,173

Summary

Ford Motor Company (Ford) is recalling certain 2015 Fiesta, 2016 Fusion, and 2016 Lincoln MKZ vehicles sold, or ever registered in Alabama, Arkansas, Arizona, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, New Mexico, Nevada, Oklahoma, Oregon, South Carolina, Texas, Utah, Washington, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands. A component inside the door latches may break, which can make it difficult to latch or possibly allow the doors to open while driving.

Remedy

Dealers will inspect the door latch date codes and if necessary, replace all four side door latches, free of charge. Owner notification letters are expected to be mailed December 4, 2023. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S15. This recall is an expansion of NHTSA recall number 20V-177.

Vehicles

MAKE	MODEL	YEAR
FORD	FIESTA	2015
FORD	FUSION	2016
LINCOLN	MKZ	2016

Electronic Parking Brake May Fail

Electronic parking brake failure may result in a vehicle rollaway, increasing the risk of a crash.

NHTSA Campaign Number: 23V776000

Manufacturer Xos, Inc.

Components PARKING BRAKE

Potential Number of Units Affected 97

Summary

Xos, Inc. (Xos) is recalling certain 2021-2022 SV05 vehicles. The electronic parking brake may malfunction or fail to engage without warning to the driver.

Remedy

Dealers will replace the electronic parking brake controller system, free of charge. Owner notification letters are expected to be mailed January 4, 2024. Owners may contact Xos customer service at 1-818-316-1890. Xos's number for this recall is REC 004-23.

Vehicle

MAKE	MODEL	YEAR
XOS	SV05	2021-2022
