



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

January 22, 2024

Front-Drive Unit May Leak Oil and Cause Fire

A fire increases the risk of injury.

NHTSA Campaign Number: 24V014000

Manufacturer General Motors, LLC

Components POWER TRAIN

Potential Number of Units Affected 66

Summary

General Motors, LLC (GM) is recalling certain 2022 BrightDrop EV600 vehicles. The front-drive unit may leak oil and cause an engine compartment fire.

Remedy

GM will replace the vehicles, free of charge. Owner notification letters are expected to be mailed February 15, 2024. Owners may contact GM customer service at 1-888-988-7267. BrightDrop owners may contact customer service number 888-987-4377. GM's number for this recall is N232466420.

Vehicle

MAKE	MODEL	YEAR
BRIGHTDROP	EV600	2022

Loss of Power Steering Assist

The incorrectly machined bracket may cause a reduction in hydraulic force, requiring greater steering effort and increasing the risk of a crash.

NHTSA Campaign Number: 24V016000

Manufacturer E-One Incorporated

Components STEERING

Potential Number of Units Affected 280

Summary

E-One Incorporated (E-One) is recalling certain 2022-2023 Cyclone 2, Cyclone N, Typhoon N, and 2023 Cyclone E vehicles. The steering assist bracket may have been machined incorrectly.

Remedy

Dealers will inspect and replace the steering assist bracket, free of charge. Owner notification letters are expected to be mailed January 31, 2024. Owners may contact E-One customer service at 1-352-237-1122.

Vehicles

MAKE	MODEL	YEAR
E-ONE	CYCLONE E	2023
E-ONE	CYCLONE II	2022-2023
E-ONE	CYCLONE N	2022-2023
E-ONE	TYPHOON N	2022-2023

Incorrect Weld May Cause Seat Failure/FMVSS 207

A loose or detached seat assembly increases the risk of injury.

NHTSA Campaign Number: 24V019000

Manufacturer Newmar Corporation

Components SEATS

Potential Number of Units Affected 160

Summary

Newmar Corporation (Newmar) is recalling certain 2022-2023 Dutch Star, Mountain Aire, London Aire, Essex, and 2016 London Aire motorhomes. The pedestal mounting plate may be improperly welded, causing the plate to separate and the seat assembly to loosen or detach. As such, these seat assemblies fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 207, "Seating Systems," and number 210, "Seat belt assembly anchorages."

Remedy

Dealers will inspect for a missing weld, and replace the pedestal as necessary, free of charge. Owner notification letters were mailed January 31, 2024. Owners may contact Newmar customer service at 1-800-731-8300. Newmar's number for this recall is 608 RSB.

Vehicles

MAKE	MODEL	YEAR
NEWMAR	DUTCH STAR	2022-2023
NEWMAR	ESSEX	2022-2023
NEWMAR	LONDON AIRE	2016, 2022-2023
NEWMAR	MOUNTAIN AIRE	2022-2023
