



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

March 25, 2024

### Side Curtain Air Bag Inflators May Rupture

An inflator rupture may result in sharp metal fragments striking occupants, resulting in injury or death.

**NHTSA Campaign Number:** 24V198000

**Manufacturer** Chrysler (FCA US, LLC) (Stellantis)

**Components** AIR BAGS

**Potential Number of Units Affected** 284,982

#### Summary

Chrysler (FCA US, LLC) (Stellantis) is recalling certain 2018-2021 Dodge Charger and Chrysler 300 vehicles. The right and left side curtain air bag inflators may rupture due to a manufacturing defect.

#### Remedy

Dealers will replace both side curtain air bags, free of charge. Owner notification letters are expected to be mailed May 3, 2024. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 19B.

#### Vehicles

---

MAKE	MODEL	YEAR
CHRYSLER	300	2018-2021

---

---

MAKE	MODEL	YEAR
DODGE	CHARGER	2018-2021

---

## Driver's Air Bag May Not Deploy/FMVSS 208

An air bag that does not deploy in a crash can increase the risk of injury.

**NHTSA Campaign Number:** 24V199000

**Manufacturer** Chrysler (FCA US, LLC) (Stellantis)

**Components** AIR BAGS, STEERING

**Potential Number of Units Affected** 38,164

### Summary

Chrysler (FCA US, LLC) (Stellantis) is recalling certain 2023-2024 Ram 1500, Jeep Wrangler, Jeep Wagoneer, Jeep Grand Wagoneer, Chrysler Pacifica, Ram 3500, Ram 3500 cab chassis, Ram 2500, Ram 4500 cab chassis, Ram 5500 cab chassis, 2023 Jeep Gladiator, Jeep Grand Cherokee, Jeep Grand Cherokee L, Ram 3500 Cab Chassis with a GVWR less than 10,000 lbs., and Chrysler Voyager vehicles. The steering column control module may not be welded properly, which can prevent the driver's air bag from deploying in a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

### Remedy

Dealers will inspect and replace the steering column control module, as necessary free of charge. Owner notification letters are expected to be mailed May 3, 2024. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's numbers for this recall are 14B, 33B, 34B, 35B, 36B.

### Vehicles

---

MAKE	MODEL	YEAR
CHRYSLER	PACIFICA	2023-2024

---

CHRYSLER	VOYAGER	2023
----------	---------	------

---

JEEP	GLADIATOR	2023
------	-----------	------

---

JEEP	GRAND CHEROKEE	2023
------	----------------	------

---

MAKE	MODEL	YEAR
JEEP	GRAND WAGONEER	2023-2024
JEEP	WAGONEER	2023-2024
JEEP	WRANGLER	2023-2024
RAM	1500	2023-2024
RAM	2500	2023-2024
RAM	3500	2023-2024
RAM	4500	2023-2024
RAM	5500	2023-2024

## Left Turn Signal and Taillight May Fail/FMVSS 108

An inoperative left turn signal may not notify other drivers of a turning vehicle, and an inoperative left taillight can reduce the vehicle's visibility to other drivers. Both scenarios can increase the risk of a crash.

**NHTSA Campaign Number:** 24V197000

**Manufacturer** Chrysler (FCA US, LLC) (Stellantis)

**Components** ELECTRICAL SYSTEM, EXTERIOR LIGHTING

**Potential Number of Units Affected** 12,375

### Summary

Chrysler (FCA US, LLC) (Stellantis) is recalling certain 2021-2022 Ram ProMaster vehicles. The wiring harness may have a poor connection, which can cause the left taillight and left turn signal to become inoperative. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

## Remedy

The remedy is under development. Owner notification letters are expected to be mailed May 3, 2024. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 21B.

## Vehicle

---

MAKE	MODEL	YEAR
RAM	PROMASTER	2021-2022

---

## Rearview Camera Image May Not Display

Loss of the rearview camera image can reduce the driver's rear visibility, increasing the risk of a crash.

**NHTSA Campaign Number:** 24V212000

**Manufacturer** Jayco, Inc.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 136

### Summary

Jayco, Inc. (Jayco) is recalling certain 2023-2024 Jayco Solstice, Solstice LI, Entegra Coach Expanse, and Expanse LI motorhomes built on Ford chassis. The rearview camera, or 360-degree view camera if equipped, may not display a rearview image when the vehicle is placed in reverse.

### Remedy

Ford or Lincoln dealers will replace the rearview camera, and update the software and wiring as necessary, free of charge. Owner notification letters are expected to be mailed April 19, 2024. Owners may contact Jayco customer service at 1-800-283-8267. Jayco's number for this recall is Ford 23V-598.

## Vehicles

---

MAKE	MODEL	YEAR
ENTEGRRA	EXPANSE	2023-2024
ENTEGRRA	EXPANSE LI	2023-2024
JAYCO	SOLSTICE	2023-2024

---

---

MAKE	MODEL	YEAR
JAYCO	SOLSTICE LI	2023-2024

---

## Transmission Harness May Short and Cause Roll Away

An unexpected shift from Park to Neutral can cause a vehicle roll away and increase the risk of a crash or injury.

**NHTSA Campaign Number:** 24V205000

**Manufacturer** Hyundai Motor America

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 15,645

### Summary

Hyundai Motor America (Hyundai) is recalling certain 2024 Genesis GV70 vehicles. Water may leak into the transmission control harness, which can cause a short circuit and unexpectedly shift the transmission from Park to Neutral.

### Remedy

Owners are advised to turn off the ignition and use the emergency parking brake after parking their vehicles. Dealers will inspect the transmission control harness and repair the connector, or replace the harness and internal wiring, as necessary, free of charge. Owner notification letters are expected to be mailed May 14, 2024. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 020G.

### Vehicle

---

MAKE	MODEL	YEAR
GENESIS	GV70	2024

---

## Loss of Drive Power from Damaged Charging Unit

A loss of drive power increases the risk of a crash.

**NHTSA Campaign Number:** 24V204000

**Manufacturer** Hyundai Motor America

## Components ELECTRICAL SYSTEM

**Potential Number of Units Affected** 98,878

### Summary

Hyundai Motor America (Hyundai) is recalling certain 2022-2024 IONIQ 5, 2023-2024 IONIQ 6, Genesis GV60, Genesis GV70 "Electrified," and Genesis GV80 "Electrified" vehicles. The Integrated Charging Control Unit (ICCU) may become damaged and stop charging the 12-Volt battery, which can result in a loss of drive power.

### Remedy

Dealers will inspect and replace the ICCU and its fuse, as necessary. In addition, dealers will update the ICCU software. All repairs will be performed free of charge. Owner notification letters are expected to be mailed May 14, 2024. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 257/021G.

### Vehicles

MAKE	MODEL	YEAR
GENESIS	GV60	2023-2024
GENESIS	GV70 EV	2023-2024
GENESIS	GV80 EV	2023-2024
HYUNDAI	IONIQ 5	2022-2024
HYUNDAI	IONIQ 6	2023-2024

## Loss of Drive Power from Damaged Charging Unit

A loss of drive power increases the risk of a crash.

**NHTSA Campaign Number:** 24V200000

**Manufacturer** Kia America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 48,232

### Summary

Kia America, Inc. (Kia) is recalling certain 2022-2024 EV6 vehicles. The Integrated Charging Control Unit (ICCU) may become damaged and stop charging the 12-Volt battery, which can result in a loss of drive power.

### Remedy

Dealers will inspect and replace the ICCU and its fuse, as necessary. In addition, dealers will update the ICCU software. All repairs will be performed free of charge. Owner notification letters are expected to be mailed April 29, 2024. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC302.

### Vehicle

---

MAKE	MODEL	YEAR
KIA	EV6	2022-2024

---

## Brake Pad Wear Warning Light Failure/FMVSS 135

Driving with worn brake pads can reduce braking ability, increasing the risk of a crash.

**NHTSA Campaign Number:** 24V201000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 2,842

### Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2021-2024 E-Pace vehicles. The brake pad wear warning light may not appear on the instrument cluster as intended, failing to warn the driver that the brake pads are worn out. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 135, "Light Vehicle Brake Systems."

### Remedy

Dealers will update the car configuration file software, free of charge. Owner notification letters are expected to be mailed May 10, 2024. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H481.

### Vehicle

---

MAKE	MODEL	YEAR
JAGUAR	E-PACE	2021-2024

---

