



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

March 11, 2024

Inflator May Deploy Improperly

An air bag that deploys improperly may not protect the driver as intended during a crash, increasing the risk of injury.

NHTSA Campaign Number: 24V154000

Manufacturer Nissan North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 351

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2024 Titan, Frontier, Infiniti QX60, Pathfinder, 2023-2024 Sentra, Versa, Kicks, Infiniti QX50, and 2023 Rogue vehicles. Due to a manufacturing issue, the driver's air bag inflator may absorb moisture, and cause the air bag to deploy improperly.

Remedy

Dealers will replace the front driver's air bag assembly, free of charge. Owner notification letters are expected to be mailed April 10, 2024. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's numbers for this recall are PD103, PD104, and PMA34.

Vehicles

MAKE	MODEL	YEAR
INFINITI	QX50	2023-2024

MAKE	MODEL	YEAR
INFINITI	QX60	2024
NISSAN	FRONTIER	2024
NISSAN	KICKS	2023-2024
NISSAN	PATHFINDER	2024
NISSAN	ROGUE	2023
NISSAN	SENTRA	2023-2024
NISSAN	TITAN	2024
NISSAN	VERSA	2023-2024

Seat Belts May Not Restrain Occupants/FMVSS 208

Improperly restrained occupants have an increased risk of injury during a crash.

NHTSA Campaign Number: 24V156000

Manufacturer Nissan North America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 9,720

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2023 Rogue vehicles. The driver and front passenger seat belt pretensioners may have been incorrectly manufactured, which can cause the seat belts to not properly restrain occupants. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection," 209, "Seat Belt Assemblies," and 210 "Seat Belt Assembly Anchorages."

Remedy

Dealers will replace the front seat belt assemblies, as necessary, free of charge. Owner notification letters are expected to be mailed April 19, 2024. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PD105.

Vehicle

MAKE	MODEL	YEAR
NISSAN	ROGUE	2023

Unsecured Lap Belt Pretensioners/FMVSS 208-210

An unsecured lap belt pretensioner will not properly restrain an occupant during a crash, increasing the risk of injury.

NHTSA Campaign Number: 24V176000

Manufacturer Nissan North America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 12,019

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2024 Pathfinder and Infiniti QX60 vehicles. The lap belt pretensioner in the left-side front seat belt assembly may be improperly secured, due to a missing rivet. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard numbers 208 "Occupant Crash Protection," 209 "Seat Belt Assemblies," and 210 "Seat Belt Assembly Anchorages."

Remedy

Dealers will inspect and replace the left-side front lap seat belt pretensioner assemblies as necessary, free of charge. Owner notification letters are expected to be mailed April 18, 2024. Owners may contact Nissan customer service at 1-800-867-7669. Owners may contact Infiniti customer service at 1-800-662-6200. Nissan's numbers for this recall are PD106 and PD107.

Vehicles

MAKE	MODEL	YEAR
INFINITI	QX60	2024
NISSAN	PATHFINDER	2024

Steering Gear Shaft May Fracture

Fractured steering gear teeth can cause a loss of steering control, increasing the risk of a crash.

NHTSA Campaign Number: 24V164000

Manufacturer Navistar, Inc.

Components STEERING

Potential Number of Units Affected 272

Summary

Navistar, Inc. (Navistar) is recalling certain 2025 International HV, HX, LT, and MV vehicles. The steering gear sector shaft may have been improperly heat-treated, which can cause the gear teeth to crack or fracture.

Remedy

Dealers will replace the steering gears, free of charge. Owner notification letters are expected to be mailed April 29, 2024. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 24505.

Vehicles

MAKE	MODEL	YEAR
INTERNATIONAL	HV	2025
INTERNATIONAL	HX	2025
INTERNATIONAL	LT	2025
INTERNATIONAL	MV	2025

Loss of Power Steering Assist

A sudden loss of power steering assist can increase the risk of a crash.

NHTSA Campaign Number: 24V161000

Manufacturer Jayco, Inc.

Components STEERING

Potential Number of Units Affected 286

Summary

Jayco, Inc. (Jayco) is recalling certain 2023-2025 Entegra Coach Anthem and Cornerstone motorhomes. The steering gear may have foreign material inside the gear that could build pressure within the system, resulting in a loss of power steering assist.

Remedy

Dealers will remove and replace the steering gear, free of charge. Owner notification letters are expected to be mailed April 12, 2024. Owners may contact Jayco customer service at 1-800-283-8267. Jayco's number for this recall is Shyft Group 24V-052.

Vehicles

MAKE	MODEL	YEAR
ENTEGR	ANTHEM	2023-2025
ENTEGR	CORNERSTONE	2023-2025

Air Bag Malfunction Warning Light Failure

A warning light that fails to indicate a problem with air bag deployment can increase the risk of injury during a crash.

NHTSA Campaign Number: 24V173000
Manufacturer Faraday Future Eco Sales Co. LLC
Components AIR BAGS, ELECTRICAL SYSTEM
Potential Number of Units Affected 11

Summary

Faraday Future Eco Sales. LLC (FF) is recalling certain 2023 Faraday Future FF 91 2.0 Alliance vehicles. A software error may prevent the air bag malfunction warning light from illuminating when a system fault is detected in the Airbag Control Unit (ACU).

Remedy

FF will deploy an over-the-air (OTA) iHUB module software update, free of charge. Owner notification letters are expected to be mailed March 15, 2024. Owners may contact Faraday customer service at 1-800-228-7702. FF's number for this recall is 24-90-32-01.

Vehicle

MAKE	MODEL	YEAR
FARADAY FUTURE	FF-91 ALLIANCE	2023

Engine Compartment Fire from Oil Leak

An oil leak in the presence of hot engine components can increase the risk of an engine compartment fire while driving.

NHTSA Campaign Number: 24V169000

Manufacturer Kia America, Inc.

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 36,248

Summary

Kia America, Inc. (Kia) is recalling certain 2019-2020 K900, and 2018-2023 Stinger vehicles equipped with a 3.3-liter turbo gasoline direct injection engine. The left turbocharger oil feed pipe and hose assembly may deteriorate and leak oil.

Remedy

Dealers will replace the left turbocharger oil feed pipe and hose assembly, free of charge. Owner notification letters are expected to be mailed April 26, 2024. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC300.

Vehicles

MAKE	MODEL	YEAR
KIA	K900	2019-2020
KIA	STINGER	2018-2023

Incorrect Park Brake Pressure Switch

The park brake light may indicate that the park brake is applied when it is not, possibly resulting in a vehicle roll away and increasing the risk of a crash.

NHTSA Campaign Number: 24V167000

Manufacturer Mack Trucks, Inc.

Components PARKING BRAKE

Potential Number of Units Affected 117

Summary

Mack Trucks, Inc. (Mack) is recalling certain 2024 MD6 and MD7 vehicles. The park brake light may indicate the incorrect brake status due to an incorrect park brake pressure switch.

Remedy

Dealers will inspect and replace the brake pressure switch as necessary, free of charge. Owner notification letters are expected to be mailed April 26, 2024. Owners may contact Mack customer service at 1-800-866-1177. Mack's number for this recall is SC0460.

Vehicle

MAKE	MODEL	YEAR
MACK	MD	2024

Front Spring Strut Failure

A loss of stability while riding can increase the risk of a crash.

NHTSA Campaign Number: 24V165000

Manufacturer BMW of North America, LLC

Components SUSPENSION

Potential Number of Units Affected 191

Summary

BMW of North America, LLC (BMW) is recalling certain 2024 R 1250RT, K 1600GT, K 1600GTL, and K 1600B motorcycles. The front spring strut may contain an incorrectly manufactured proportional valve that can loosen, and result in strut failure and a loss of stability.

Remedy

Dealers will inspect the strut production dates and replace the front spring struts as necessary, free of charge. Owner notification letters are expected to be mailed April 22, 2024. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	K 1600 B	2024
BMW	K 1600 GT	2024
BMW	K 1600 GTL	2024

MAKE	MODEL	YEAR
BMW	R 1250 RT	2024

Low Air Pressure Warning Malfunction/FMVSS 121

A low air pressure warning that does not function properly can result in driving without functioning brakes, increasing the risk of a crash.

NHTSA Campaign Number: 24V162000

Manufacturer Autocar, LLC

Components SERVICE BRAKES, AIR

Potential Number of Units Affected 586

Summary

Autocar, LLC (Autocar) is recalling certain 2020-2024 DC (Legend) vehicles. A software error may cause the low air pressure warning to not function properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 121, "Air Brake Systems."

Remedy

Dealers will update the low air pressure warning software, free of charge. Owner notification letters are expected to be mailed April 26, 2024. Owners may contact Autocar customer service at 1-888-218-3611. Autocar's number for this recall is DC-2401.

Vehicle

MAKE	MODEL	YEAR
AUTOCAR	LEGEND	2020-2024

Improperly Secured Windows May Detach

During air bag deployment, an unsecured windshield may not support the front air bags as intended, increasing the risk of injury in a crash.

NHTSA Campaign Number: 24V155000

Manufacturer Porsche Cars North America, Inc.

Components VISIBILITY

Potential Number of Units Affected 8,101

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2020-2024 911 vehicles. The front windshield and rear window may not be properly secured and can detach.

Remedy

Dealers will inspect and replace the windshield and rear window as necessary, free of charge. Owner notification letters are expected to be mailed April 26, 2024. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is ARA3.

Vehicle

MAKE	MODEL	YEAR
PORSCHE	911	2020-2024