



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

May 12, 2025

Rearview Camera Image May Not Display/FMVSS 111

Software Update Repairs Recall

NHTSA Campaign Number: 25V293000

Manufacturer Polestar Automotive USA, Inc.

Components BACK OVER PREVENTION

Potential Number of Units Affected 3,664

Summary

Polestar Automotive USA, Inc. (Polestar) is recalling certain Polestar 3 vehicles. The rearview camera image may not display when the vehicle is placed in reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

The software will be updated by a dealer or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed July 1, 2025. Owners may contact Polestar's customer service at 1-800-806-2504. Polestar's number for this recall is RP1057.

Vehicle

MAKE	MODEL	YEAR
POLESTAR	POLESTAR 3	2025

Rearview Camera Image May Not Display/FMVSS 111

Software Update Repairs Recall

NHTSA Campaign Number: 25V282000

Manufacturer Volvo Car USA, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 413,151

Summary

Volvo Car USA, LLC (Volvo Car) is recalling certain 2021-2025 XC40, 2022 V90, 2022-2025 S90, V90CC, C40, XC60, and 2023-2025 S60, V60, V60CC, and XC90 vehicles. The rearview camera image may not display when the vehicle is placed in reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

The software will be updated by a dealer or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed June 24, 2025. Owners may contact Volvo Car customer service at 1-800-458-1552. Volvo Car's number for this recall is R10320.

Vehicles

MAKE	MODEL	YEAR
VOLVO	C40	2022-2025
VOLVO	S60	2023-2025
VOLVO	S90	2022-2025
VOLVO	V60	2023-2025
VOLVO	V60CC	2023-2025
VOLVO	V90	2022
VOLVO	V90CC	2022-2025

MAKE	MODEL	YEAR
VOLVO	XC40	2021-2025
VOLVO	XC60	2022-2025
VOLVO	XC90	2023-2025

Improperly Tightened Seat Fasteners/FMVSS 207, 222

A seat with loose fasteners may not properly restrain an occupant during a crash, increasing the risk of injury.

NHTSA Campaign Number: 25V289000

Manufacturer Blue Bird Body Company

Components SEATS

Potential Number of Units Affected 34

Summary

Blue Bird Body Company (Blue Bird) is recalling certain 2026 Vision and All American school buses equipped with a lap belt-ready or 3-pt seats. The seat mounting fasteners may have been improperly tightened. As such, these vehicles fail to comply with Federal Motor Vehicle Safety Standard numbers 207, "Seating Systems," 210, "Seat Belt Assembly Anchorages," and 222, "School Bus Passenger Seating and Crash Protection."

Remedy

Blue Bird will replace the seat fasteners, free of charge. Owner notification letters are expected to be mailed July 3, 2025. Owners may contact Blue Bird customer service at 1-478-822-2242. Blue Bird's number for this recall is R25DM.

Vehicles

MAKE	MODEL	YEAR
BLUE BIRD	ALL AMERICAN	2026
BLUE BIRD	VISION	2026

Electric Oil Pump May Overheat and Cause Fire

Fire Risk Warning

A fire while parked or driving can increase the risk of injury.

NHTSA Campaign Number: 25V291000

Manufacturer Hyundai Motor America

Components POWER TRAIN

Potential Number of Units Affected 620

Summary

Hyundai Motor America (Hyundai) is recalling certain 2025 Hyundai Palisade vehicles. An insufficient seal on the controller for the electric oil pump may allow moisture to accumulate in the printed circuit board, which can cause an electrical short and result in a fire.

Remedy

Owners are advised to park their vehicles outside and away from structures until the recall remedy is completed. Dealers will replace the electric oil pump controller, free of charge. Owner notification letters are expected to be mailed July 4, 2025. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 278.

Vehicle

MAKE	MODEL	YEAR
HYUNDAI	PALISADE	2025

Loose Cylinder Head Screws May Allow Oil to Leak

The screws can loosen, allowing oil to leak and increasing the risk of a fire.

NHTSA Campaign Number: 25V294000

Manufacturer Volkswagen Group of America, Inc.

Components ENGINE

Potential Number of Units Affected 89,417

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2022-2024 Q5 Quattro and Q5 Sportback Quattro vehicles. The cylinder head cover screws may have been improperly tightened.

Remedy

Dealers will inspect and replace the screws as necessary, free of charge. Owner notification letters are expected to be mailed July 8, 2025. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 15ZK.

Vehicles

MAKE	MODEL	YEAR
AUDI	Q5	2022-2024
AUDI	Q5 SPORTBACK	2022-2024

Reduced Brake Performance/FMVSS 121

Reduced brake performance can extend the distance required to stop, increasing the risk of a crash.

NHTSA Campaign Number: 25V295000

Manufacturer Daimler Trucks North America, LLC

Components SERVICE BRAKES, AIR

Potential Number of Units Affected 68

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2025 Freightliner 114SD, Business Class M2, Cascadia, and Western Star 49X vehicles. The air tank capacity may be too small, resulting in reduced braking performance. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 121, "Air Brake Systems."

Remedy

The remedy is currently under development. Interim owner notification letters explaining the safety risk are expected to be mailed July 6, 2025. A second notice will be sent once the remedy becomes available. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is F1019.

Vehicles

MAKE	MODEL	YEAR
FREIGHTLINER	114SD	2025

MAKE	MODEL	YEAR
FREIGHTLINER	BUSINESS CLASS M2	2025
FREIGHTLINER	CASCADIA	2025
WESTERN STAR	49X	2025