



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest April 22, 2013

RECALL Subject : Front Brake Torque Member may Fail

Report Receipt Date: APR 12, 2013

NHTSA Campaign Number: 13V139000

Component(s): SERVICE BRAKES

Potential Number of Units Affected: 19,258

All Products Associated with this Recall

Vehicle MakeModelModel Year(s)

- INFINITI JX 2013
- NISSAN PATHFINDER 2013

Details

2 Associated Documents

Manufacturer: Nissan North America, Inc.

SUMMARY:

Nissan is recalling certain model year 2013 Pathfinder and Infiniti JX vehicles manufactured December 3, 2012, through January 29, 2013. The front brake torque member was improperly cast resulting in structural weakness. This can lead to premature failure and cracking.

CONSEQUENCE:

If the brake torque member fails, the brake caliper may move and contact the inside of the road wheel, resulting in reduced braking, increasing the risk of a crash.

REMEDY:

Nissan will notify owners, and dealers will inspect the manufacturing date of the torque members and replace them, as necessary, free of charge. The recall is expected to begin in early May 2013. Owners may contact Nissan Customer Service at 1-800-647-7261.