



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest August 14, 2015

RECALL Subject : Harness Adjuster/Release Button may Stick

Report Receipt Date: AUG 11, 2015

NHTSA Campaign Number: 15C003000

Component(s): CHILD SEAT

Potential Number of Units Affected: 213,753

Child Restraints Brand	NameModel	Production Dates
• BRITAX	ADVOCATE CLICKTIGHT	08/01/2014 - 07/29/2015
• BRITAX	BOULEVARD CLICKTIGHT	08/01/2014 - 07/29/2015
• BRITAX	MARATHON CLICKTIGHT	08/01/2014 - 07/29/2015

Manufacturer: Britax Child Safety, Inc.

SUMMARY:

Britax Child Safety, Inc. (Britax) is recalling certain Advocate ClickTight child seats, model numbers E9LT95Q, E9LT95Z, E9LT95N, and E1A025Q, Boulevard ClickTight child seats, model numbers E9LT86F, E1A135Q, E9LT86G, E9LT85Q, E9LT86A, E9LT86H, E9LT85S, E1A015Q, E1A016A, and E1A016H, and Marathon ClickTight child seats, model numbers E1A116L, E9LT76P, E9LT71Q, E9LT76N, E9LT76B, E9LT75R, E9LT76L, E1A006B, E1A005R and EXA116L, manufactured August 1, 2014, to July 29, 2015. The affected child seats have a red harness adjuster button that may stick in the down (harness release) position allowing the shoulder harness to loosen.

CONSEQUENCE:

If the harness loosens, the child may not be properly restrained, increasing their risk of injury in the event of a crash.

REMEDY:

Britax will notify registered owners and send them a remedy kit that includes a lubricant to apply to the harness adjuster button, free of charge. The recall is expected to begin on August 17, 2015.