



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest December 24, 2012

Report Date :**December 24, 2012 at 03:08 PM**
NHTSA CAMPAIGN ID Number:**12V567000**

Vehicle Make / Model:

HYUNDAI / VELOSTER

Manufacturer: Hyundai-Kia America Technical Center Inc

NHTSA CAMPAIGN ID Number: 12V567000

Model Year(s):

2012

Report Receipt Date: DEC 07, 2012

NHTSA Action Number: N/A

Component: PARKING BRAKE:CONVENTIONAL:MECHANICAL:LINKAGE AND CABLE

Potential Number of Units Affected: 4,490

Summary:

Hyundai is recalling certain model year 2012 Veloster vehicles manufactured from July 2, 2011, through February 27, 2012 and equipped with manual transmissions. Moisture and road grime may cause the parking brake components to bind.

Consequence:

If the parking brake components bind, the parking brake may not operate properly, and the parking brake may drag while driving or may not fully engage when the vehicle is parked. If the parking brake is not fully engaged when parked, a manual transmission may move unintentionally, increasing the risk of a crash.

Remedy:

Hyundai will notify owners, and dealers will replace the rear brake caliper assemblies free of charge. The safety recall will begin during January 2013. Owners may contact Hyundai at 1-800-633-5151.

Report Date :**December 24, 2012 at 03:09 PM**
NHTSA CAMPAIGN ID Number:**12V568000**

Vehicle Make / Model:

HYUNDAI / VELOSTER

Manufacturer: Hyundai-Kia America Technical Center Inc

NHTSA CAMPAIGN ID Number: 12V568000

Model Year(s):

2012

Report Receipt Date: DEC 07, 2012

NHTSA Action Number: PE12027

Component: VISIBILITY:SUN ROOF ASSEMBLY

Potential Number of Units Affected: 13,500

Summary:

Hyundai is recalling certain model year 2012 Veloster vehicles manufactured from November 1, 2011, through April 17, 2012 and equipped with panoramic sunroofs. The panoramic sunroof assembly may be weakened during installation at the factory.

Consequence:

If the assembly was weakened at the factory, the panoramic glass panel may break while the vehicle is in motion leading to personal injury or a vehicle crash.

Remedy:

Hyundai will notify owners, and dealers will inspect the sunroof's integrity and replace the sunroof glass assembly, as necessary, free of charge. The safety recall will begin during January 2013. Owners may contact Hyundai at 1-800-633-5151.

Report Date :**December 24, 2012 at 03:10 PM**
NHTSA CAMPAIGN ID Number:**12V571000**

Vehicle Make / Model:

JAGUAR / XF

Manufacturer: Jaguar Land Rover North America, LLC

NHTSA CAMPAIGN ID Number: 12V571000

Model Year(s):

2013

Report Receipt Date: DEC 07, 2012

NHTSA Action Number: N/A

Component: ELECTRICAL SYSTEM

Potential Number of Units Affected: 13

Summary:

Jaguar Land Rover is recalling certain model year 2013 XF vehicles manufactured October 3, 2012, through October 12, 2012 and equipped with a gasoline engine. The electronic modules which control the fuel pump may shut down causing the fuel pump to stop pumping fuel. The resulting fuel starvation will cause the engine to stall.

Consequence:

An engine stall without warning while driving may lead to a loss of motive power, a loss of power-assisted braking and a loss of power-assisted steering. Each of these conditions may increase the risk of a vehicle crash.

Remedy:

Jaguar Land Rover will notify owners, and dealers will install an additional wiring harness to the in-tank fuel pump, free of charge. The recall is expected to begin on, or before, January 18, 2013. Owners may contact Jaguar Land Rover at 1-800-452-4827.

Report Date :**December 24, 2012 at 03:11 PM**
NHTSA CAMPAIGN ID Number:**12V594000**

Vehicle Make / Model:

CHEVROLET / COLORADO

GMC / CANYON

Manufacturer: General Motors LLC

NHTSA CAMPAIGN ID Number: 12V594000

Model Year(s):

2010-2012

2010-2012

Report Receipt Date: DEC 19, 2012

NHTSA Action Number: N/A

Component: LATCHES/LOCKS/LINKAGES:HOOD:LATCH

Potential Number of Units Affected: 118,800

Summary:

General Motors is recalling certain model year 2010-2012 Chevrolet Colorado and GMC Canyon vehicles manufactured from November 9, 2009, through August 28, 2012, for failing to comply with the requirements of Federal Motor Vehicle Safety Standard No. 113, "Hood Latch System." The hood may be missing the secondary hood latch.

Consequence:

If the primary hood latch is not engaged, the hood could open unexpectedly. During vehicle operation, this could obstruct the view of the driver and increase the risk of a crash.

Remedy:

General Motors will notify owners and instruct them to inspect their vehicle for the presence of a secondary hood latch. Dealers will replace the hood on any affected vehicles, free of charge. The recall is expected to begin on January 17, 2013. Owners may contact Chevrolet at 1-800-630-2438 or GMC at 1-866-996-9463.