

NHTSA Recalls of Interest

January 28, 2013

Report Receipt Date: JAN 18, 2013 NHTSA Campaign Number: 13V016000

Component(s): AIR BAGS

Potential Number of Units Affected: 748,481

All Products Associated with this Recall —

Vehicle Make - Model - Model Year(s)

- HONDAODYSSEY2011-2013
- HONDAPILOT2009-2013



4 Associated Documents



Manufacturer: Honda (American Honda Motor Co.)

SUMMARY:

Honda is recalling certain model year 2009-2013 Pilot and 2011-2013 Odyssey passenger vehicles manufactured from March 13, 2008, through December 21, 2012. One or more rivets that attach the airbag module to the airbag cover may be missing.

CONSEQUENCE:

The absence of more than one rivet could alter the performance of the driver's airbag during deployment. This could potentially increase the risk of injury during a crash.

REMEDY:

Honda will notify owners and instruct them to take their vehicle to a Honda dealer. The dealer will inspect the driver's airbag module and replace it if necessary, free of charge. The recall is expected to begin on, or about, February 16, 2013. Owners may contact Honda at 1-800-999-1009.

NOTES:

Honda's recall campaign number is S75. Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Report Receipt Date: JAN 16, 2013 NHTSA Campaign Number: 13V014000 Component(s): AIR BAGS, SEATS Potential Number of Units Affected: 3,235

All Products Associated with this Recall



Vehicle Make - Model - Model Year(s)

- TOYOTA4RUNNER2009-2012
- TOYOTAAVALON2009-2010
- TOYOTACAMRY2009-2012
- TOYOTACAMRY HYBRID2009-2012
- TOYOTACOROLLA2010-2013
- TOYOTAFJ CRUISER2009-2010
- TOYOTAHIGHLANDER2009-2013
- TOYOTAHIGHLANDER HYBRID2009-2010
- TOYOTAPRIUS2009-2012
- **TOYOTAPRIUS V2012**
- TOYOTARAV42009-2012
- TOYOTASEQUOIA2010-2012
- TOYOTASIENNA2010-2013
- TOYOTATACOMA2009-2012
- TOYOTATUNDRA2010-2013
- TOYOTAVENZA2009-2013





Manufacturer: Southeast Toyota Distributors, LLC

SUMMARY:

Southeast Toyota Distributors, LLC (SET) is recalling certain models interspersed through model years 2009 through 2013 as follows: model year 2009-2012 Tacoma, 4Runner, Camry, Camry Hybrid, Prius, and RAV4; model year 2009-2010 Avalon, FJ Cruiser, and Highlander Hybrid; model year 2010-2013 model year Corolla, Sienna and Tundra; model year 2009-2013 Highlander and Venza; model year 2012 Prius V; and model year 2010-2012 Sequoia. During modification by SET to include accessories such as leather seat covers, seat heaters or headrest DVD systems, these vehicles may not have had the passenger seat occupant sensing system calibration tested. Without passing the calibration test, the occupant sensing system may not operate as designed.

CONSEQUENCE:

If the front passenger seat occupant sensing system is out of calibration, the front passenger airbags may not deploy or they may deploy inappropriately for the passenger's size and position. This could increase the risk of personal injury during the event of a vehicle crash necessitating airbag deployment.

REMEDY:

Southeast Toyota will notify owners, and dealers will test the sensitivity of the occupant detection sensors, and recalibrate them as necessary. The recall is expected to begin during January 2013. Owners may contact Southeast Toyota at 1-800-301-6859.