



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

January 30, 2017

### Front Passenger Air Bag may not Vent Properly

**NHTSA Campaign Number:** 16V935000

**Manufacturer** Daimler Vans USA, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 22

#### **Summary**

Daimler Vans USA, LLC (DVUSA) is recalling certain model year 2017 Mercedes-Benz Metris Vans manufactured September 9, 2016, to September 28, 2016. The affected vehicles have a ZF passenger air bag that may have been manufactured with an incorrect Tether Activation Unit (TAU). As a result, in the event of a crash necessitating deployment of the passenger frontal air bag, the air bag may not vent properly.

#### **Remedy**

DVUSA will notify owners, and authorized Mercedes-Benz Sprinter dealers will replace the front passenger air bag, free of charge. The recall is expected to begin February 8, 2017. Owners may contact DVUSA customer service at 1-877-762-8267.

#### **Vehicle**

MAKE	MODEL YEAR
------	------------

MERCEDES-BENZ METRIS	2017
----------------------	------

## Front Passenger Air Bag may not Fully Inflate

**NHTSA Campaign Number:** 16V937000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** AIR BAGS

**Potential Number of Units Affected** 2

### **Summary**

Toyota Motor Engineering & Manufacturing (Toyota) is recalling one 2016 Toyota 4Runner vehicle manufactured November 1, 2016 and one 2017 Lexus GX460 vehicle manufactured November 16, 2016. The affected vehicles are equipped with Takata PSPI-LD front passenger air bag inflators that may have been manufactured without ignition booster tablets. As a result, in the event of a crash, the air bag may not fully inflate during deployment of the primary stage. As such, these vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

### **Remedy**

Toyota dealers have replaced the passenger side air bag modules, free of charge. Toyota notified the affected dealers on December 15, 2016. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is G06, GLR.

### **Vehicles**

MAKE	MODEL	YEAR
------	-------	------

LEXUS	GX460	2017
-------	-------	------

TOYOTA	4RUNNER	2016
--------	---------	------

## Seat Belt Pretensioners may not Function Properly

**NHTSA Campaign Number:** 16V940000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 8,232

## Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2017 Jaguar XE vehicles manufactured July 12, 2016, to December 2, 2016, and Jaguar F-Type vehicles manufactured July 14, 2016, to December 16, 2016. The affected vehicles have NCS Pyrotechnie front seat seatbelt pretensioners that may not function properly in the event of a crash.

## Remedy

Jaguar will notify owners, and dealers will inspect the front seat belt assemblies, replacing them as necessary, free of charge. The recall is expected to begin February 20, 2017. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is J081.

## Vehicles

### MAKE MODEL YEAR

JAGUAR F-TYPE 2017

JAGUAR XE 2017

## Possible Front Passenger Air Bag Non-Deployment

**NHTSA Campaign Number:** 16V941000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 550

## Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2016 Land Rover Range Rover and Range Rover Sport vehicles and 2017 Range Rover Evoque vehicles. The affected vehicles have a front passenger NCS Pyrotechnie air bag inflator initiator that may fail to ignite during a crash, preventing the air bag from deploying.

## Remedy

Land Rover will notify owners, and dealers will replace the front passenger air bag, free of charge. The recall is expected to begin February 20, 2017. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is P094.

## Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2016
LAND ROVER	RANGE ROVER SPORT	2016
RANGE ROVER	EVOQUE	2017

### Seat Belt Pretensioners may not Function Properly

**NHTSA Campaign Number:** 16V942000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 13,500

### Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain model year 2017 Land Rover Discovery Sport vehicles and 2016-2017 Land Rover Range Rover and Range Rover Sport vehicles. The affected vehicles have NCS Pyrotechnie seatbelt pretensioners that may not function properly in the event of a crash.

### Remedy

Land Rover will notify owners, and dealers will inspect the front seat belt assemblies, replacing them as necessary, free of charge. The recall is expected to begin February 20, 2017. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is P095.

## Vehicles

MAKE	MODEL	YEAR
LAND ROVER	DISCOVERY SPORT	2017
LAND ROVER	RANGE ROVER	2016-2017
LAND ROVER	RANGE ROVER SPORT	2016-2017

### Possible Front Passenger Air Bag Non-Deployment

**NHTSA Campaign Number:** 16V943000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 16

#### **Summary**

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain model year 2016-2017 Jaguar XJ vehicles manufactured September 12, 2016, to October 26, 2016. The affected vehicles have a front passenger NCS Pyrotechnie air bag inflator initiator that may fail to ignite during a crash, preventing the air bag from deploying.

#### **Remedy**

Jaguar will notify owners, and dealers will replace the front passenger air bag, free of charge. The recall is expected to begin February 20, 2017. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is J080.

#### **Vehicle**

MAKE	MODEL	YEAR
------	-------	------

JAGUAR	XJ	2016-2017
--------	----	-----------

### Seat Mounted Air Bags may not Deploy

**NHTSA Campaign Number:** 16V946000

**Manufacturer** Porsche Cars North America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 85

#### **Summary**

Porsche Cars North America, Inc. (Porsche) is recalling certain model year 2017 718 Boxster, 718 Boxster S, 718 Cayman, 718 Cayman S, 911 Carrera, 911 Carrera S, 911 Carrera S Cabriolet, 911 Carrera 4S, 911 Turbo, 911 Turbo S, 911 Carrera 4S Cabriolet, and 911 Turbo Cabriolet vehicles. The seat mounted side NCS Pyrotechnie air bag inflator initiator may fail to ignite during a crash.

## Remedy

Porsche will notify owners, and dealers will replace the affected air bag modules, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AG10.

## Vehicles

MAKE	MODEL	YEAR
PORSCHE	718 BOXSTER	2017
PORSCHE	718 CAYMAN	2017
PORSCHE	911	2017

## Driver Side Frontal Air Bag May Rupture

**NHTSA Campaign Number:** 16V947000

**Manufacturer** Chrysler (FCA US LLC)

**Components** AIR BAGS

**Potential Number of Units Affected** 12,691

## Summary

Chrysler (FCA US LLC) is recalling certain model year 2009 Dodge Durango and Chrysler Aspen vehicles manufactured January 17, 2007, to December 18, 2008, and 2010 RAM 3500 cab chassis manufactured September 25, 2009, to February 1, 2010. The affected vehicles are equipped with a Takata dual-stage driver frontal air bag that may be susceptible to moisture intrusion which, over time, could cause the inflator to rupture.

## Remedy

Chrysler has notified owners, and dealers will replace the driver's frontal air bag inflator, free of charge. The recall began January 11, 2017. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is S92. Note: This recall covers vehicles that were accidentally excluded from recall 15V-313.

## Vehicles

MAKE	MODEL	YEAR
CHRYSLER	ASPEN	2009

MAKE	MODEL	YEAR
------	-------	------

DODGE	DURANGO	2009
-------	---------	------

DODGE	RAM 3500	2010
-------	----------	------

Side Curtain Air Bags may not Inflate Properly

**NHTSA Campaign Number:** 16V953000

**Manufacturer** Chrysler (FCA US LLC)

**Components** AIR BAGS

**Potential Number of Units Affected** 1

**Summary**

Chrysler (FCA US LLC) is recalling one model year 2017 RAM ProMaster City vehicle manufactured on November 5, 2016. This vehicle has side curtain air bags that may not inflate properly in the event of a crash.

**Remedy**

Chrysler has notified the owner, and a dealer inspected the side curtain air bags, free of charge. The recall began January 17, 2017. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is S95.

**Vehicle**

MAKE	MODEL	YEAR
------	-------	------

RAM	PROMASTER CITY	2017
-----	----------------	------

Air Bags or Seat Belt Pretensioners may not Deploy

**NHTSA Campaign Number:** 16V955000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** AIR BAGS, SEAT BELTS

**Potential Number of Units Affected** 5,901

**Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain model year 2017 Audi A7, A4, A6, Volkswagen Golf and Tiguan vehicles and 2016 Volkswagen e-Golf vehicles for Autoliv driver frontal air bags, passenger frontal air bags or head air bags that may not deploy properly. Additionally, certain 2017 Audi Q7, A4 Sedan, A4 Allroad, and 2018 Audi Q5 vehicles are being recalled because the seat belt pretensioners may not activate properly.

### **Remedy**

Volkswagen and Audi will notify owners, and dealers will replace the affected air bags and seat belt pretensioners, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Volkswagen customer service at 1-800-893-5298 or Audi customer service at 1-800-253-2834.

### **Vehicles**

<b>MAKE</b>	<b>MODEL YEAR</b>	
AUDI	A4	2017
AUDI	A6	2017
AUDI	A7	2017
AUDI	Q5	2018
AUDI	Q7	2017
VOLKSWAGEN	E-GOLF	2016
VOLKSWAGEN	GOLF	2017
VOLKSWAGEN	TIGUAN	2017

[Driver Air Bag may not Fully Inflate](#)

**NHTSA Campaign Number:** 16V956000

**Manufacturer** Hyundai Motor America

**Components** AIR BAGS

**Potential Number of Units Affected** 110

### **Summary**

Hyundai Motor Company (Hyundai) is recalling certain model year 2017 Hyundai Elantra vehicles manufactured April 15, 2016, to September 13, 2016, and Sonata vehicles manufactured May 27, 2016 to September 16, 2016. In these vehicles, the end seal for the Key Safety System driver's frontal air bag inflator may not have been properly installed, possibly resulting in reduced inflation of the frontal air bag in the event of a crash.



## Remedy

Hyundai will notify owners, and dealers will replace the driver's frontal air bag module, free of charge. The recall is expected to begin February 13, 2017. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 156.

## Vehicles

MAKE	MODEL	YEAR
------	-------	------

HYUNDAI	ELANTRA	2017
---------	---------	------

HYUNDAI	SONATA	2017
---------	--------	------

## Air Bag Inflator may Rupture due to Corrosion

**NHTSA Campaign Number:** 17V001000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** VISIBILITY, AIR BAGS

**Potential Number of Units Affected** 234,054

## Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2011-2017 Audi Q5 vehicles. The sunroof drainage system may allow water to soak into the foam surrounding the ISI Automotive side head air bag inflator canister resulting in the corrosion of the canister. This corrosion can weaken the canister and, during deployment of the side head air bag, the inflator may fracture and propel fragments into the passenger compartment.

## Remedy

Audi will notify owners, and dealers will inspect the inflator and either coat it or replace it, as necessary, after removing the surrounding foam, free of charge. The recall is expected to begin in February 2017. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 69P1.

## Vehicle

MAKE	MODEL	YEAR
------	-------	------

AUDI	Q5	2011-2017
------	----	-----------

