



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

January 16, 2017

### Seat Mounted Air Bags may not Deploy

**NHTSA Campaign Number:** 16V914000

**Manufacturer** BMW of North America, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 3,506

#### **Summary**

BMW of North America, LLC (BMW) is recalling certain model year 2017 BMW 640i, 640i xDrive, 650i, 650i xDrive, M6, 535i, 535i xDrive, 430i, 430i xDrive, 440i, 440i xDrive, M4, X1 sDrive28i, X1 xDrive28i, i3, i8, Rolls-Royce Dawn, Mini Clubman Cooper, Clubman Cooper S, Cooper All4, Cooper S All4, Mini 4-Door Cooper, Cooper S, Mini 2-Door Cooper, Cooper S, John Cooper Works and 2016 BMW 528i, 528i xDrive, 535i, 535i xDrive, 550i, 550i xDrive, M5 and 535d vehicles. The affected vehicles have Autoliv seat-mounted side air bag inflators with NCS Pyrotechnic initiators that may fail to ignite during a crash.

#### **Remedy**

BMW will notify owners, and dealers will replace the air bag modules, free of charge. The recall is expected to begin February 6, 2017. Owners may contact BMW customer service at 1-800-525-7417.

#### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
BMW	430I	2017

MAKE	MODEL	YEAR
BMW	440I	2017
BMW	528I	2016
BMW	535D	2016
BMW	535I	2016-2017
BMW	550I	2016
BMW	640I	2017
BMW	650I	2017
BMW	I3	2017
BMW	I8	2017
BMW	M4	2017
BMW	M5	2016
BMW	M6	2017
BMW	X1 SAV	2017
MINI	CLUBMAN	2017
MINI	COOPER	2017
MINI	COOPER S	2017
ROLLS-ROYCE	DAWN	2017

[Seat Mounted Air Bag may not Deploy/FMVSS 208/214](#)

**NHTSA Campaign Number:** 16V918000

**Manufacturer** Volvo Car USA LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 377

### Summary

Volvo Car USA LLC (Volvo) is recalling certain model year 2017 S60 and S60 Cross Country, V60 and V60 Cross Country, and XC60 vehicles manufactured August 16, 2016, through October 21, 2016. The affected vehicles have driver and front passenger seat Autoliv side mounted side air bags (SAB) inflators with NCS Pyrotechnie initiators that may fail to ignite during a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection" and number 214, "Side Impact Protection."

## **Remedy**

Volvo will notify owners, and dealers will inspect and, if necessary, replace the front seat side air bags, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Volvo customer service at 1-800-458-1552. Volvo's number for this recall is R89712.

## **Vehicles**

### **MAKE MODEL YEAR**

VOLVO S60	2017
VOLVO V60	2017
VOLVO XC60	2017