



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest
March 23, 2015

**RECALL Subject : Driver Side Air Bag Inflator may Rupture , 1
INVESTIGATION(S)**

Report Receipt Date: MAR 16, 2015
NHTSA Campaign Number: 15V153000
Component(s): AIR BAGS
Potential Number of Units Affected: 104,871

Vehicle Make	Model	Model Year(s)
• HONDA	ACCORD	2001
• HONDA	CIVIC	2004
• HONDA	PILOT	2008

Manufacturer: Honda (American Honda Motor Co.)

SUMMARY:

American Honda Motor Company, Inc. (Honda) is recalling certain model year 2001 Accord, 2004 Civic, and 2008 Pilot vehicles. Upon deployment of the driver side frontal air bag, excessive internal pressure may cause the inflator to rupture.

CONSEQUENCE:

In the event of a crash necessitating deployment of the driver side frontal air bag, the inflator could rupture with metal fragments striking and potentially seriously injuring the vehicle occupants.

REMEDY:

Honda will notify owners, and dealers will replace the driver side frontal air bag inflator in all affected vehicles, free of charge. The manufacturer has not yet provided a notification schedule.

