



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

March 26, 2012

The following is an example of a series of 9 recalls announced for the same item at various users of the product.

Report Date :**March 26, 2012 at 12:48 PM**
NHTSA CAMPAIGN ID Number:**12V119000**

Equipment Brand Name / Part No. or Model No.:

WEBASTO / HOLLANDIA 600

WEBASTO / HOLLANDIA 700

WEBASTO / HOLLANDIA TVS 900

Manufacturer: TRISTATE LEATHER

NHTSA CAMPAIGN ID Number: 12V119000

Production Dates:

Information not Available

Information not Available

Information not Available

Mfr's Report Date: MAR 21, 2012

NHTSA Action Number: EQ10007

Component: VISIBILITY:SUN ROOF ASSEMBLY

Potential Number of Units Affected: 3,164

Summary:

WEBASTO PRODUCT NORTH AMERICA, INC. (WEBASTO) IS RECALLING CERTAIN HOLLANDIA 700 AND 600 SERIES AND HOLLANDIA TVS 900 SERIES SUNROOFS INSTALLED AS ORIGINAL EQUIPMENT BY TRISTATE LEATHER ON VARIOUS PASSENGER VEHICLES. THE ADHESIVE BOND BETWEEN THE GLASS AND THE METAL FRAME CAN DEBOND INCREASING THE RISK THAT THE SUNROOF GLASS WOULD SEPARATE FROM THE VEHICLE. COMPLETE GLASS-TO-FRAME DEBONDING CAN DEVELOP GRADUALLY AND MAY BE EVIDENCED BY METAL CORROSION AROUND THE SUNROOF FRAME, WIND NOISE, VIBRATION, VISUAL BOND SEPARATION AND/OR WATER LEAKAGE.

Consequence:

IN THE EVENT OF A SEPARATION, THE FALLING GLASS COULD CREATE A ROAD HAZARD OR STRIKE A TRAILING VEHICLE, AND CAUSE A CRASH.

Remedy:

WEBASTO, THE MANUFACTURER OF THE SUNROOFS, WILL BE PERFORMING THE SAFETY RECALL CAMPAIGN. OWNERS WHO HAVE BEEN IDENTIFIED AS HAVING AN AFFECTED SUNROOF INSTALLED IN THEIR VEHICLE WILL RECEIVE A SAFETY RECALL NOTICE FROM WEBASTO. THE SAFETY RECALL BEGAN ON OCTOBER 8, 2010. IN ORDER TO DETERMINE IF YOUR VEHICLE IS AFFECTED, PLEASE REVIEW THE LIST OF VEHICLES PROVIDED TO US BY TRISTATE LEATHER BY CLICKING ON THE HYPERLINK [AFFECTED VEHICLE LIST](#) OR YOU MAY VISIT WEBASTO'S WEBSITE AT WWW.SUNROOFCHECK.COM. YOU CAN ALSO CALL WEBASTO TOLL-FREE AT 1-888-749-8632.

