



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest May 5, 2014

RECALL Subject : Passenger's Side Curtain Air Bag may not Deploy

Report Receipt Date: APR 07, 2014

NHTSA Campaign Number: 14V175000

Component(s):

Potential Number of Units Affected: 24,889

Vehicle	MakeModel	Model Year(s)
• HONDA	ODYSSEY	2014

Manufacturer: Honda (American Honda Motor Co.)

SUMMARY:

Honda is recalling certain model year 2014 Odyssey vehicles manufactured October 2, 2013, through December 16, 2013. The shorting terminal, an electrical connector used to prevent air bag deployment before being installed into a vehicle, may have been damaged during assembly of the passenger-side side curtain air bag.

CONSEQUENCE:

If the shorting terminal is damaged, the passenger-side side curtain air bag may fail to deploy thereby increasing the risk of occupant injury in a crash.

REMEDY:

Honda will notify owners, and dealers will replace the damaged shorting pin with a new shorting coupler, free of charge. The recall is expected to begin in early May 2014.

