



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest November 12, 2012

Report Date :**November 12, 2012 at 10:56 AM**
NHTSA CAMPAIGN ID Number:**12V527000**

Vehicle Make / Model:

JEEP / GRAND CHEROKEE
JEEP / LIBERTY

Manufacturer: CHRYSLER GROUP LLC

NHTSA CAMPAIGN ID Number: 12V527000

Model Year(s):

2002-2004

2002-2003

Report Receipt Date: NOV 08, 2012

NHTSA Action Number: EA12001

Component: AIR BAGS:FRONTAL:SENSOR/CONTROL MODULE

Potential Number of Units Affected: 744,822

Summary:

Chrysler is recalling certain model year 2002 and 2003 Jeep Liberty vehicles manufactured January 9, 2001, through March 28, 2003, and 2002 through 2004 Jeep Grand Cherokee vehicles manufactured February 13, 2001, through May 23, 2003. A component in the air bag control module may fail causing the front airbags, side curtain airbags, and/or seatbelt pretensioners to deploy inadvertently while the vehicle is being operated.

Consequence:

Inadvertent deployment of the airbags may increase the risk of injury and the possibility of a vehicle crash.

Remedy:

Chrysler will notify owners, and dealers will install a supplemental jumper harness to the airbag control module, free of charge. The recall is expected to begin during January 2013. Owners may contact Chrysler at 1-800-247-9753.

Report Date :**November 12, 2012 at 11:00 AM**
NHTSA CAMPAIGN ID Number:**12V521000**

Vehicle Make / Model:

JAGUAR / XF

Manufacturer: Jaguar Land Rover North America, LLC

NHTSA CAMPAIGN ID Number: 12V521000

Model Year(s):

2010-2012

Report Receipt Date: OCT 26, 2012

NHTSA Action Number: N/A

Component: FUEL SYSTEM, GASOLINE

Potential Number of Units Affected: 4,195

Summary:

Jaguar is recalling certain model year 2010-2012 XF vehicles equipped with a 5.0L gasoline engine. The affected vehicles may have a fuel tank fuel outlet flange that may crack.

Consequence:

The cracked flange may result in fuel leakage onto the ground. This leaking fuel, in the presence of an ignition source, may result in a vehicle fire.

Remedy:

Jaguar will notify owners, and dealers will replace the affected fuel tank fuel outlet flanges, free of charge. The recall is expected to begin on, or before, December 7, 2012. Owners may contact Jaguar at 1-800-452-4827