



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

November 14, 2016

### **RECALL Subject : Seat Belt Buckle may Separate/FMVSS 210, 209**

**Report Receipt Date:** NOV 02, 2016

**NHTSA Campaign Number:** 16V798000

**Component(s):** SEAT BELTS

**Potential Number of Units Affected:** 74,027

Vehicle Make	Model	Model Year(s)
• VOLVO	S60	2016-2017
• VOLVO	S90	2016-2017
• VOLVO	V60	2016-2017
• VOLVO	XC60	2016-2017
• VOLVO	XC90	2016-2017

**Manufacturer:** Volvo Car USA LLC

#### **SUMMARY:**

Volvo Car USA LLC (Volvo) is recalling certain model year 2016-2017 XC90, S90, XC60, V60 Cross Country, V60, S60 Cross Country, S60, and S60 Inscription vehicles manufactured February 16, 2015, to August 22, 2016. On the affected vehicles, the front passenger seat belt buckle attaching stud may loosen, allowing the buckle to separate from the seat belt bracket. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 210, "Seat Belt Assembly Anchorages" and number 209, "Seat Belt Assemblies."

**CONSEQUENCE:**

If the seat belt buckle separates from the bracket, the front seat passenger may not be adequately restrained in the event of a crash, increasing their risk of injury in the event of a crash.

**REMEDY:**

Volvo will notify owners, and dealers will inspect the front passenger seat belt buckle stud, replacing the seat belt buckle as needed, free of charge. The recall is expected to begin December 12, 2016.