



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

February 13, 2017

Front Passenger Air bag may not Deploy

NHTSA Campaign Number: 17V061000

Manufacturer General Motors LLC

Components AIR BAGS

Potential Number of Units Affected 91,007

Summary

General Motors LLC (GM) is recalling certain 2006-2010 Pontiac Solstice and 2007-2010 Saturn Sky vehicles. The IEE Passenger Air Bag Suppression System (PPS) sensor may become bent or damaged within the front passenger seat, possibly disabling the front passenger air bag.

Remedy

The remedy for this recall is still under development. The manufacturer has not yet provided a notification schedule. Owners may contact Pontiac customer service at 1-800-762-2737 or Saturn customer service at 1-800-553-6000. GM's number for this recall is 17036.

Vehicles

MAKE MODEL YEAR

PONTIAC SOLSTICE 2006-2010

SATURN SKY 2007-2010

Passenger Air Bag May Not Deploy Properly

NHTSA Campaign Number: 17V062000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 4

Summary

BMW of North America, LLC (BMW) is recalling certain 2016-2017 X1 xDrive28i and X1 sDrive28i vehicles. The affected vehicles have a Yanfeng instrument panel that may not allow the front passenger air bag to deploy properly in the event of a crash.

Remedy

BMW will notify owners, and dealers will replace the instrument panel, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact BMW customer service at 1-800-525-7417.

Vehicle

MAKE MODEL YEAR

BMW X1 SAV 2016-2017

Loss of Power Brake Assist

NHTSA Campaign Number: 17V063000

Manufacturer Hyundai Motor America

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 33,803

Summary

Hyundai Motor Company (Hyundai) is recalling certain 2017 Elantra vehicles. In the affected vehicles, the Mando brake booster may fail, resulting in a loss of power brake assist.

Remedy

Hyundai has notified owners, and dealers will replace the brake system booster assembly, free of charge. The recall began on February 6, 2017. Owners may contact Hyundai customer service at 1-800-633-5151. Hyundai's number for this recall is 157.

Vehicle

MAKE MODEL YEAR

HYUNDAI ELANTRA 2017

Passenger Frontal Air Bag Inflator May Rupture

NHTSA Campaign Number: 17V068000

Manufacturer Nissan North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 46

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2002 Pathfinder and Infiniti QX4 vehicles. These vehicles are equipped with Takata air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the front air bags, these inflators may rupture.

Remedy

Nissan will notify owners, and dealers will replace the front passenger air bag assembly, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Nissan customer service at 1-800-647-7261.

Vehicles

MAKE MODEL YEAR

INFINITI QX4 2002

NISSAN PATHFINDER 2002

Engine may Seize

NHTSA Campaign Number: 17V070000

Manufacturer Volkswagen Group of America, Inc.

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 2

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2017 Jetta vehicles equipped with a 1.4L engine. These vehicles have an engine that may seize due to an improper casting of the block.

Remedy

Volkswagen will either buy back the vehicle or replace the engine block, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 10F4.

Vehicle

MAKE	MODEL YEAR
-------------	-------------------

VOLKSWAGEN JETTA	2017
------------------	------