



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

February 27, 2017

Air Bag Control Unit may be Damaged in a Crash

NHTSA Campaign Number: 17V093000

Manufacturer Daimler Vans USA, LLC

Components AIR BAGS

Potential Number of Units Affected 15,338

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2013-2016 Mercedes-Benz Sprinter 2500 and 3500 and Freightliner Sprinter 2500 and 3500 vans. These vehicles were manufactured without a reinforcement plate and protective bracket on the air bag control unit. As a result, the air bag control unit may not remain functional after the initial impact, possibly preventing additional air bags from deploying in response to a secondary impact.

Remedy

DVUSA will notify owners, and dealers will install a reinforcement plate and protective bracket around the air bag control unit, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact DVUSA customer service at 1-877-762-8267.

Vehicles

MAKE	MODEL	YEAR
FREIGHTLINER	SPRINTER 2500	2013-2016
FREIGHTLINER	SPRINTER 3500	2013-2016

MAKE	MODEL	YEAR
------	-------	------

MERCEDES BENZ	SPRINTER 2500	2013-2016
---------------	---------------	-----------

MERCEDES BENZ	SPRINTER 3500	2013-2016
---------------	---------------	-----------

Curtain Air Bag Securing Bolts may Fail/FMVSS 226

NHTSA Campaign Number: 17V104000

Manufacturer Volvo Car USA LLC

Components AIR BAGS

Potential Number of Units Affected 5,529

Summary

Volvo Car USA LLC (Volvo) is recalling certain 2017 XC90, S90, and V90 Cross Country vehicles. The bolts that secure the Autoliv Inflatable Curtain (IC) air bags in place may break, possibly resulting in the IC air bag deploying improperly in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 226, "Ejection Mitigation."

Remedy

Volvo will notify owners, and dealers will inspect and replace the bolts, as necessary, free of charge. The recall is expected to begin April 1, 2017. Owners may contact Volvo customer service at 1-800-458-1552. Volvo's number for this recall is R89714.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

VOLVO	S90	2017
-------	-----	------

VOLVO	V90CC	2017
-------	-------	------

VOLVO	XC90	2017
-------	------	------