



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

March 13, 2017

### [Frontal Air Bag may not Deploy Properly/FMVSS 208](#)

**NHTSA Campaign Number:** 17V123000

**Manufacturer** Ford Motor Company

**Components** AIR BAGS

**Potential Number of Units Affected** 27,531

#### **Summary**

Ford Motor Company (Ford) is recalling certain 2016-2017 Ford Edge and Lincoln MKX vehicles and 2017 Lincoln Continental

vehicles. In the event of a crash, the Takata driver's frontal air bag may not fully inflate or the air bag cushion may detach from

the air bag module. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

#### **Remedy**

Ford will notify owners, and dealers will replace the driver frontal air bag module, free of charge. Remedy parts are not currently available. Owners will be notified of the safety recall in March 2017. Owners will receive a second notice when remedy parts are available, currently expected to be in August 2017. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17C02.

## Vehicles

MAKE	MODEL	YEAR
FORD	EDGE	2016-2017
LINCOLN	CONTINENTAL	2017
LINCOLN	MKX	2016-2017

[Seat Mounted Air Bag may not Deploy/FMVSS 208/214](#)

**NHTSA Campaign Number:** 17V127000

**Manufacturer** Volvo Car USA LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 112

### Summary

Volvo Car USA LLC (Volvo) is recalling certain 2017 S60, S60CC, V60, V60 Cross Country, and XC60 vehicles. The affected vehicles have Autoliv driver and front passenger seat side mounted side air bags (SAB) with inflator initiators that may fail to ignite during a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection" and number 214, "Side Impact Protection."

### Remedy

Volvo will notify owners, and dealers will inspect and, if necessary, replace the front seat side air bags, free of charge. The recall is expected to begin March 31, 2017. Owners may contact Volvo customer service at 1-800-458-1552. Volvo's number for this recall is R89712. Note: This recall is an expansion of recall 16V-918.

## Vehicles

MAKE	MODEL	YEAR
------	-------	------

VOLVO	S60	2017
VOLVO	S60CC	2017
VOLVO	V60	2017
VOLVO	V60CC	2017
VOLVO	XC60	2017

---

Rearview Camera Display may not Function Properly

**NHTSA Campaign Number:** 17V132000

**Manufacturer** Subaru of America, Inc.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 25,567

**Summary**

Subaru of America, Inc. (Subaru) is recalling certain 2017 Impreza vehicles. Due to a software problem, the Harman rearview camera display may not work properly.

**Remedy**

Subaru will notify owners, and dealers will update the infotainment software, free of charge. The recall is expected to begin on March 20, 2017. Owners may contact Subaru customer service at 1-800-782-2783. Subaru's number for the recall is WTN-74.

**Vehicle**

**MAKE MODEL YEAR**

SUBARU IMPREZA 2017

---

Front Passenger Air Bag may not Deploy/FMVSS 208

**NHTSA Campaign Number:** 17V133000

**Manufacturer** Porsche Cars North America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 17,871

**Summary**

Porsche Cars North America, Inc. (Porsche) is recalling certain 2015-2016 Macan S and Macan Turbo and 2017 Macan GTS vehicles. The IEE passenger occupant detection sensor mat may fail in the front passenger seat, deactivating the front passenger air bag. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

## Remedy

Porsche will notify owners, and dealers will replace the sensor mat and seat cushion, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AH02.

## Vehicles

MAKE	MODEL	YEAR
PORSCHE	MACAN GTS	2017
PORSCHE	MACAN S	2015-2016
PORSCHE	MACAN TURBO	2015-2016

---

### Passenger Frontal Air Bag may not Deploy

**NHTSA Campaign Number:** 17V134000

**Manufacturer** Porsche Cars North America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 120

## Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2016 911 GT3 RS and 911 R vehicles and 2017 911 Carrera, 911 Carrera Cabriolet, 911 Carrera 4, 911 Carrera 4S, 911 Carrera 4S Cabriolet, 911 Carrera S, 911 Carrera S Cabriolet, 911 Targa 4, 911 Targa 4S, 911 Turbo S, 911 Turbo S Cabriolet, 718 Boxster, 718 Boxster S, 718 Cayman and 718 Cayman S vehicles. The Autoliv passenger frontal air bag inflator initiator may fail to ignite during a crash.

## Remedy

Porsche will notify owners, and dealers will replace the affected air bags, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AH03.

## Vehicles

MAKE	MODEL	YEAR
PORSCHE	718 BOXSTER	2017
PORSCHE	718 CAYMAN	2017
PORSCHE	911	2016
PORSCHE	911 CARRERA	2017

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
PORSCHE	911 GT3 RS	2016
PORSCHE	911 TARGA 4	2017

---

Side Air Bags may Deploy Unexpectedly

**NHTSA Campaign Number:** 17V144000

**Manufacturer** Nissan North America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 54,751

**Summary**

Nissan North America, Inc. (Nissan) is recalling certain 2012 Nissan Versa vehicles. Degradation of the Bosch side impact sensor connector pins may cause the curtain and seat-mounted air bags to deploy unexpectedly if the door is slammed.

**Remedy**

Nissan will notify owners, and dealers will install a new jumper harness, and replace the side impact satellite sensors, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Nissan customer service at 1-800-647-7261.

**Vehicle**

**MAKE MODEL YEAR**

NISSAN VERSA 2012