



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

March 20, 2017

Possible Driver-Side Curtain Airbag Non-Deployment

NHTSA Campaign Number: 17V143000

Manufacturer Nissan North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 79

Summary

Nissan North America Inc. (Nissan) is recalling certain 2017 Infiniti QX30 vehicles. The affected vehicles have an Autoliv driver-side curtain air bag inflator initiator that may fail to ignite during a crash, preventing the air bag from deploying.

Remedy

Nissan will notify owners, and dealers will replace the driver-side curtain air bag assembly, free of charge. The recall is expected to begin in March 2017. Owners may contact Infiniti customer Service at 1-800-662-6200.

Vehicle

MAKE MODEL YEAR

INFINITI QX30 2017

Tire Pressure Warning Light/FMVSS 138

NHTSA Campaign Number: 17V146000

Manufacturer Chrysler (FCA US LLC)

Components TIRES

Potential Number of Units Affected 278

Summary

Chrysler (FCA US LLC) is recalling certain 2017 Fiat 500X vehicles. When the vehicle has a tire with low tire pressure, the Magneti Marelli Ellectronics tire pressure monitoring system (TPMS) warning light may not illuminate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 138, "Tire Pressure Monitoring Systems."

Remedy

Fiat will notify owners, and dealers will update the instrument panel software, free of charge. The recall is expected to begin April 21, 2017. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is T16.

Vehicle

MAKE MODEL YEAR

FIAT 500X 2017

Blind Spot Monitoring Function Not Installed

NHTSA Campaign Number: 17V148000

Manufacturer Daimler Vans USA, LLC

Components LANE DEPARTURE

Potential Number of Units Affected 72

Summary

Daimler Vans USA LLC (DVUSA) is recalling certain 2016-2017 Mercedes-Benz Metris vehicles. These vans were to be equipped with the Blind Spot Monitoring (BSM) feature, however, the installed instrument cluster and steering wheel does not support the function, and thus, the BSM system does not work on the vehicle.

Remedy

DVUSA will notify owners, and dealers will install the correct instrument cluster and steering wheel to enable the BSM function, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact DVUSA customer service at 1-877-762-8267.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

MERCEDES BENZ	METRIS	2016-2017
---------------	--------	-----------

[Seatbelt Component may Detach and Enter the Cabin](#)

NHTSA Campaign Number: 17V150000

Manufacturer Volkswagen Group of America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 1,676

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2017 Audi A5 Cabriolet and S5 Cabriolet vehicles. A component within the Autoliv front, rear, and rear center seat belt retractor pretensioners may detach after the seatbelt retractor pretensioner is deployed in the event of a crash.

Remedy

Audi will notify owners, and dealers will replace the safety belt retractors/pretensioners, free of charge. The recall is expected to begin in May 2017. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for the recall is 6908.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

AUDI	A5 CABRIOLET	2017
------	--------------	------

AUDI	S5 CABRIOLET	2017
------	--------------	------

[Seat Belt Linkages may Detach](#)

NHTSA Campaign Number: 17V152000

Manufacturer Hyundai Motor America

Components SEAT BELTS

Potential Number of Units Affected 977,778

Summary

Hyundai Motor America (Hyundai) is recalling certain 2011-2014 Sonata and 2011-2015 Sonata Hybrid vehicles. In the affected vehicles, the ZF-TRW seat belt linkages for both front seat belts may detach from the seat belt anchor pretensioners.

Remedy

Hyundai will notify owners and dealers will inspect the connection between the seat belt linkages and the seat belt anchor pretensioners, repairing them as necessary, free of charge. The recall is expected to begin April 7, 2017. Owner's may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for the recall is 160.

Vehicles

MAKE	MODEL	YEAR
HYUNDAI	SONATA	2011-2014
HYUNDAI	SONATA HYBRID	2011-2015

[Passenger Frontal Air Bag may not Deploy](#)

NHTSA Campaign Number: 17V154000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 205

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2016 Land Rover Range Rover and Range Rover Sport vehicles. The Autoliv passenger frontal air bag inflator initiator may fail to ignite during a crash.

Remedy

Land Rover will notify owners, and dealers will replace the front passenger air bag, free of charge. The recall is expected to begin May 1, 2017. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N026.

Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2016
LAND ROVER	RANGE ROVER SPORT	2016
